

4th year Maintenance bid

73

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Nil:- Maintenance of Road from					
2028 Chikabari To Khar/Basti					
in Thakurganj Block.					
Agency:- Md Haider Reza, Kicharganj.					
Agr No:- 31/MMG/SY/SBD/2019-20					
Date of Start:- 26/02/2020.					
Actual Date of completion:- 09/03/21					
4th year Maintenance ^{period}					
10/03/24 to 09/03/25					

① Restoration of Aquatic Bank with
Soil, manure etc - - - -

2x 10.70x 1.50x 0.90 =	29.43m ³
3x 5.600x 1.40x 1.00 =	23.52m ³
2x 11.20x 1.20x 0.60 =	16.128m ³
7x 6.10x 0.90x 0.80 =	30.744m ³
10x 2.100x 1.00x 1.00 =	21.00m ³
6x 2.00x 1.00x 1.00 =	12.00m ³
Total:-	132.822m ³
Rate:-	7

② Making up of Berm/shoulder

Stripping excess Soil - - - -

2x 30.00x 1.50 =	90.0m ²
2x 4x 16.200x 1.500 =	194.40m ²
12x 30.00x 1.000 =	360.00m ²
2x 25.00x 1.00 =	50.00m ²
Total:-	694.40m ²

Continuation

Abstract of cost

75

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Rectification of Ray cuts/Berms with Sed - - - -					
132.822 M ³ (vide page- 73)					
@RS- 379.59/M ³ = RS - - - -					50418.00
② making up of Berms/Shoulder stripping excess soil - - - -					
694.40 M ² (vide page- 73)					
@RS- 56.81/M ² = RS - - - -					39449.00
③ Repair of pot holes filled with 25mm bitumy - - - -					
144.73 M ² (vide page- 74)					
@RS- 388.12/M ² = RS - - - -					56173.00
④ patch repair over pot holes with 20mm seal surface - - - -					
144.73 M ² (vide page- 74)					
@RS- 267.74/M ² = RS - - - -					38750.00
⑤ Repair to pot holes with seal Surfacing using bitumy - - - -					
144.73 M ² (vide page- 75)					
@RS- 285.35/M ² = RS - - - -					41299.00
⑥ maintenance of C/D works (slab) - -					
2.0 Nos (vide page- 74)					
@RS- 2273.47/No = RS - - - -					4547.00

Continuation

Continuation