

Name of district - Musahi to Mandal Tol, Road

39

00000

Schedule XLY-Form No.-134

G.T. S.No. V.

Biraul

DIVISION

Biraul

SUB-DIVISION

MB No - 1005

MEASUREMENT BOOK

Sri- Rakesh Kumar Thakur (ABSENER)



Particulars	Details of actual measurement			Contents of area
	No.	L	B	D.
N/Work: Maintenance of Road				
from Mahabari to				
Mantal to				
Agency: Shri Rakash Kumar				
Rakhar				
Agreement No. 15.583/19-20				
Date of start: 19/08/19				
Act. Date of Comp. 14/02/20				

Measurement

Restoration of virinula

width 2nd measurement

8 x 6 x 0.9 x 0.9 =	12.496 m ³
12 x 6 x 0.7 x 0.9 =	15.12 m ³
8 x 5 x 0.9 x 0.9 =	10.8 m ³
	<u>56.16 m³</u>

② Maintenance of up bunds

Shoulder Shifting

excav soil

4 x 2 x 16 x 0.50 =	64 m ³
4 x 2 x 18 x 0.50 =	72 m ³
8 x 2 x 12 x 0.50 =	96 m ³
0 x 2 x 16 x 0.50 =	32 m ³
	<u>264 m³</u>

③ Maintenance of Slab culvert

61 Nos

Particulars	Details of actual measurement				Contents of area	
	No.	L.	B.	D.		
		<u>Amount of cost</u>				
			x	x		
① Restoration of raincuts						
with soil masonry						
P/27		56.16m ³				
Limited		53.16m ³				
		@ 378.92/m ³ = 20111/-				
② Maintenance of shoulder						
P/27		264m ²				
		@ 52.14/m ² = 13084/-				
③ Maintenance of slab culvert						
			@	2291.44	= 2291/-	
					37486/-	
Less 10% below					(-) 3748.6/-	
					33737/-	
<u>Material consumption</u>						
		x				
Earth	=	53.16m ³				
	</					