

4th Oct 2021 - 202108 21st Oct 2021
3847

MMGSy (GEN)

Shedule XLV Form No. 134.

3847 3847 3847/2021

DIVISION

SUB-DIVISION

3847 3847 3847/2021

Measurement Book

Singh Kumar Singh
At - Kandiya

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>1st YEAR MAINTENANCE</u>					
N/W - 508 Halli Tola Road to Purvi tola masadh.					
N/A - Sanjay Kumar Singh.					
Agg No. - 0.5/mmGSY/GEN/SBT/2021-22					
Date of work Order - 08/06/2021					
Date of Comp. - 07/06/2022					
<u>ITEMS OF WORK.</u>					
①. Restoration of drain/Bumr with soil measure 2					
5 X 1.70 X 1.20 X 1.50 =					15.303
3 X 1.75 X 1.10 X 0.80 =					4.62 ³
4 X 1.90 X 1.15 X 1.00 =					8.74 ^{m³}
7 X 1.80 X 1.10 X 0.85 =					11.78 ^{m³}
5 X 1.75 X 1.20 X 1.50 =					15.75 ^{m³}
2 X 1.75 X 1.50 X 1.00 =					5.25 ^{m³}
					= 61.44 ^{m³}
② Making of Berms/shoulder, stripping excess soil from the shoulder Surface to achieve level 2					
2 X 2 X 25 X 1.10 =					110 m ²
3 X 2 X 22 X 1.20 =					158 m ²
2 X 2 X 15 X 1.00 =					60 m ²
2 X 2 X 5 X 1.00 =					20 m ²
					= 348 m ²
③ Path repair on already filled pot hole with 75 mm BM with					

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Rs. 1166.58					Rs. 4666 = 00
					Rs. 57127 = 00
added 12% GST + Rs.					6855 = 00
added 17% L-C + Rs.					571 = 00
added 8% Fee + Rs.					572 = 00
					Total Rs. = 65,125 = 00
Less 0.2% (-) Rs.					130 = 00
					Rs. = 64995 = 00
18.02.05					
75					AE

Continuation