

कार्यपालक अभियंता का कार्यालय,
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, हिलसा

पत्र संख्या ...846 8180... हिलसा/दिनांक ...05-05-2025...

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, हिलसा

सेवा में,

नोडल पदाधिकारी,
MR 3054,
ग्रामीण कार्य विभाग, बिहार, पटना।


विषय:- नई अनुरक्षण निति 2018 शीर्ष के अंतर्गत कराये जा रहे अनुरक्षण कार्य के भुगतान हेतु राशि अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषयक नई अनुरक्षण निति 2018 शीर्ष के पथ में कराये जा रहे अनुरक्षण कार्य के भुगतान हेतु राशि की अधियाचना विहित प्रपत्र में संलग्न कर समर्पित किया जाता है।

अनु:- यथोक्त।

विश्वासभाजन



5-5-25
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, हिलसा

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)

Form of Utilization Certificate up to the Date MAY 25

RWD, Works Division ,Hilsa

Sl.No	Name of Scheme	Sanction No. & Date with Amount (in lacs Rs.)	Amount Received (in lacs Rs.)	Particulars
1	Construction of Rural roads under NEW MAINTENANCE POLICY (2018)	29 WE/30.03.2025	10999.30683	Certified that out of Rs.10999.30683 lacs of grants-in-aid sanctioned during the years 2018-19 to 2024-25 in favors of E-in-C, RWD Bihar, Patna a sum of Rs. 10901.36426 lacs has been utilized for the purpose of NEW MAINTENANCE POLICY (2018) as given in the margin for which it was sanctioned and that the balance of Rs.97.94257 lacs remaining unutilized at the end of the period under report.
	Total :	Total -	10999.30683	


2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-

- Works have been supervised by Executive Engineer/ Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- All other codal formalities have been observed.

3. Physical Progress achieved :-

- Construction of Road Works.
- Construction of CD works


D.A.O
RWD (W), Hilsa


Executive Engineer
RWD (W), Hilsa


कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग
कार्य प्रमंडल हिलसा

का0आ0सं0 838 हिलसा, दिनांक 02-05-2025

कार्यालय आदेश

प्रमाणित किया जाता है कि बिहार ग्रामीण पथ अनुरक्षण निती-2018 योजनान्तर्गत L026 Ekangarsarai Dhurgaon Path to Atramchak (Project ID-10200812035) का कार्य गुणवत्ता एवं विशिष्टियों के अनुरूप पूर्ण कराया गया है। पथ के मापीपुस्त की जाँच मेरे द्वारा 25 प्रतिशत एवं सहायक अभियंता के द्वारा 50 प्रतिशत एवं कनीय अभियंता के द्वारा शत प्रतिशत किया गया है।

कनीय अभियंता
ग्रामीण कार्य विभाग
कार्य प्रशाखा एकंगरसराय


सहायक अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रमंडल एकंगरसराय


कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल हिलसा

Requisition Format for scheme Head : MR(3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

RWD, Works Division : HILSA

Sl No	Package No	Project ID as Per MIS	Name of Road	Administrative Approval (AA) Letter No & Date	Administrative		Agreement		Agreement No & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (In mm/km)	Thickness of Bitumen Layer (In MM)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (In Lakh)	Upto date Expenditure as per MIS (In Lakh)	Requisition against work done (In Lakh)	Remarks
					Length (Km)	Amount (In Lakh)	Initial Rectification with Surface Renewal	5 Year Routine Maintenance										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RN/NA/HI L/23/0014	10200812035	L026 Ekangarsarai Dhurgson Path to Atramchak	2328/04.05.2023	1.38	70.221	52.33884	12.25333	06/MIBD/2024-25 16/08/2024	15/05/2025	-	3167	25.00	5.00	30.10671	30.10671	22.19432	SURFACE COMPLETE
Total					1.380	70.2210	52.3388	12.2533							30.10671	30.10671	22.19432	

1 Signed Hard Copy and Soft Copy (In Excel) of recorded IRI is enclosed.

2 Up-to-date Physical Progress has been uploaded in MIS

[Signature]
23/5/25
Divisional Account Officer
RWD, Works Division, HILSA

[Signature]
23/5/25
Executive Engineer
RWD (W) Division HILSA

Name of Road: L026 Ekangarsarai Dhurgaon Path to Atramchak

Name of Contractor: Bijay Kumar Singh

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY ROAD	Latitude	Longitude	Event
25/2/25	13:40:7	96	0.1	310	20.2	3100	3203	G	25.2196	85.275505	Normal
25/2/25	13:42:0	96	0.1	330	20.2	3300	3402	G	25.219592	85.27648	Normal
25/2/25	13:43:2	96	0.1	270	20.2	2700	2804	G	25.219795	85.27749	Normal
25/2/25	13:44:13	96	0.1	240	20.2	2400	2504	G	25.220172	85.278265	Normal
25/2/25	13:45:0	96	0.1	270	30.3	2700	2804	G	25.221093	85.278113	Normal
25/2/25	13:46:0	96	0.1	380	10.1	3800	3901	G	25.221973	85.27878	Normal
25/2/25	13:47:45	95	0.1	310	10.1	3100	3203	G	25.222422	85.27838	Normal
25/2/25	13:48:55	96	0.1	280	10.1	2800	2903	G	25.222472	85.27941	Normal
25/2/25	13:50:6	96	0.1	330	10.1	3300	3402	G	25.222063	85.280285	Normal
25/2/25	13:53:37	96	0.1	280	20.2	2800	2903	G	25.22249	85.280842	Normal
25/2/25	13:54:45	96	0.1	320	10.1	3200	3303	G	25.223315	85.28101	Normal
25/2/25	13:55:20	96	0.1	330	20.2	3300	3402	G	25.223308	85.28101	Normal
25/2/25	13:59:0	96	0.1	310	20.2	3100	3203	G	25.222473	85.280823	Normal
25/2/25	14:0:41	96	0.1	330	20.2	3300	3402	G	25.22197	85.28101	Normal

$$Y = 0 \cdot X^2 + 0.998 \cdot X + 109.5$$

$$X = 10500$$

$$Y = 10588$$


(R) RURAL ROAD

Good Average Poor

<4000 4001-5000 >5001


Sumit
02/05/25
A.E

File : C:\Users\lwd\Desktop\27021227 Xis. Section No. : 96. Eqn : $Y = 0 \cdot X^2 + 0.998 \cdot X + 109.5$
Name of Customer : Bijay Kumar Singh. Name of Work/ Road : L025 Ekangarsarai Dhurgson Path to Atramchak. Lab



52/5/2015
A.A.E

File : C:\Users\rwd\Desktop\27021227.Xls, Section No. :96, Eqn : $Y = 0 \cdot X^2 + 0.998 \cdot X + 109.5$
Name of Customer : Bijay Kumar Singh, Name of Work/ Road : L026 Ekangarsarai Dhurgaon Path to Atramchak, Lab



NMP - L026 Se Ekangarsarai Dhurgaon Path to Atramchal

Schedule XLV-Form No. 134

Sri Bijay Kumar Singh

MB No. - 1957

HILSA

DIVISION

EKANGARSARAI

SUB-DIVISION

MEASUREMENT BOOK

2nd On A/c Bill Abstract (Recast)
Final Bill.

21

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Clearing & grubbing Rd. land vide item no. ① VTMP ①					
Qty = 0.311 Ha @ 75573.34/Ha =					23503.00
② E/w in excavation for structure vide item no. ② VTMP ① & item no. ① VTMP ②					
Qty = 29.80 + 84.709 = 114.509 m ³					
@ 398.62/m ³ =					45646.00
③ Sand filling in found ⁿ trenches vide item no. ② VTMP ②					
Qty = 1.254 m ³ @ 575.24/m ³ =					721.00.
④ Providing M15 (1:2.5:5) as levelling course vide item no. ③ VTMP ②, item no. ④ VTMP ② & item no. ⑤ VTMP ②					
Qty = 12.657 m ³ + 4.600 m ³ + 54.075 m ³					
= 71.332 @ 6186.61/m ³ =					441303.00
⑤ Plain/Reinforced Cement Concrete vide item no. ⑥ VTMP ②					
Qty = 26.261 m ³ @ 6656.68/m ³ =					174811.00
⑥ Plain/Reinforced Cement Conc. in Substructure (M20) vide item no. ① VTMP ③					
Qty = 33.74 m ³ @ 7137.30 =					240812.00

Continuation C.O = 926796.00

Particulars	Details of actual measurement				Contents area
	No.	L	B.	D.	
			B/F	=	92679.
⑦ Plain / RCC M20 in Substructure					
Vide item no ② VTMP ③					
Qty = $7.38 \text{ m}^3 @ 7137.30/\text{m}^3$					52673.
⑧ Providing & laying RCC NP3					
Pipe vide item no ④ VTMP ③					
Qty = $7.50 \text{ m} @ 6724.58/\text{m}$					50434
⑨ Supplying, fitting & placing					
HYSD Bar vide item no. ⑤					
VTMP ③					
Qty =					
Qty Limit = $0.626 \text{ MT} @ 82010.33/\text{MT}$					50518.00
⑩ Brick Masonry in C.M in					
Parapet vide item no. ①					
VTMP ④					
Qty = $10.22 \text{ m}^3 @ 6954.36/\text{m}^3$					78028.00
⑪ Plastering with Cement Mortar					
(1:4) vide item no. ② VTMP ④					
Qty = $78.72 \text{ m}^2 @ 205.83/\text{m}^2$					16203.00
⑫ GSB Gr-II for pot/patch					
work vide item no. ① VTMP ④					
Qty = $20.672 \text{ m}^3 @ 1926.11/\text{m}^3$					39817.00
⑬ Providing & laying WBM					
Gr-II vide item no. ②					
VTMP ⑤					
Qty = $15.555 \text{ m}^3 @ 3860.61/\text{m}^3$					60052.00
				C.O	1274521.01

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
		B/F			1274521.00
14) Providing & laying WBM					
Gr-III vide item no. (3)					
VTMP (6)					
Qty = $36.051 \text{ m}^3 @ 3794.16/\text{m}^3$					136783.00
15) Providing & filling joint					
Sealing vide item no. (4)					
VTMP (6)					
Qty = $15.00 \text{ m}^3 @ 55.44$					832.00
16) Providing Weep holes in					
Brick Masonry vide item no.					
(1) VTMP (6)					
Qty = 20 Nos. @ $285.44/\text{each}$					5709.00
17) Draining spouts vide item					
no. (6) VTMP (6)					
Qty = 2 No. @ $5736.44/\text{each}$					11473.00
18) Providing & applying P.C					
vide item no. (1) VTMP (4)					
Qty = $480.68 \text{ m}^2 @ 59.94/\text{m}^2$					28812.00
19) Providing & applying T.C					
vide item no. (1) VTMP (7)					
Qty = $480.68 \text{ m}^2 @ 20.59/\text{m}^2$					9897.00
20) Patch work using MSS vide					
item no. (3) VTMP (7)					
Qty = 480.71 m^2					
Qty Unit = $480.68 \text{ m}^2 @ 259.36$					
					124669.00

Continuation C.O = 1592696.1

Particulars	Details of actual measurement				Contents & area
	No.	L	B	D	
			B/P	—	1592696.
1) Providing & laying T.C					
vide item no. ① VTMP ⑧					
Qty = $4923.75 \text{ m}^2 @ 1719/\text{m}^2 = 84639.0$					
2) Providing & laying SPBC					
vide item no. ② VTMP ⑧					
Qty = 124.632 m^3					
Qty limit = $123.0988 \text{ m}^3 @ 13435.21$					
				=	1653858.0
3) Providing & laying 300mm					
irrigation Conduit pipe vide					
item no. ① VTMP 24 ⑨					
Qty = $30 \text{ m} @ 1020.58/\text{m} = 30617.00$					
24) Const of DLC vide item					
no. ① VTMP ⑩					
Qty = $1.50 \text{ m}^3 @ 3918.49/\text{m}^3 = 5878.00$					
25) Panel concrete vide item					
no. ② VTMP ⑩					
Qty = $30.208 \text{ m}^3 @ 8004.65 = 241804.00$					
26) Km Stone vide item no. ⑩					
③ VTMP ⑩					
Qty = $3 \text{ Nos} @ 2751.85/\text{each} = 8256.00$					
27) 200m stone vide item no.					
④ VTMP ⑩					
Qty = $5 \text{ Nos} @ 794.88/\text{each} = 3974.00$					
				C.O =	3621722.00

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			B/F	—	3621722.00
28) Direction & Place of identification					
Sign vide item no. ⑤ VTMP					
⑩					
Qty = $3.84 \text{ m}^2 @ 14886.20/\text{m}^2$					57163.00
29) 600mm equilateral & triangle					
vide item no. ⑥ VTMP ⑩					
Qty = 8 Nos @ 4354.73/each					34838.00
30) 600mm Circular vide item no.					
⑦ VTMP ⑪					
Qty = 1 No. @ 4227.75/each					4228.00
31) 600 x 450 mm rectangular vide					
item no. ⑧ VTMP ⑪					
Qty = 2 Nos. @ 4083.22/each					8166.00
32) 900 mm Side Octagon vide					
item no. ⑨ VTMP ⑪					
Qty = 1 No. @ 8552.58/each					8553.00
33) Planting of Trees vide					
item no. ① VTMP ⑪					
Qty = 52 Nos. @ 1288.76/each					67016.00
34) Road Marking :					
(i) BT portion vide item no. ②/①					
VTMP ⑪					
Qty = $260.00 \text{ m}^2 @ 667.72/\text{m}^2$					173607.00
				C.O =	3975293.00

Continuation

Particulars	Details of actual measurement -				Contents of area
	No.	L.	B.	D.	
			B/F	—	3975293.0
ii) Pedestrian vide item no. ②/ii)					
VTMP ⑪					
Qty = $12.00 \text{ m}^2 @ 667.72/\text{m}^2$					8013.00
iii) PCC portion vide item no. ②/iii)					
VTMP ⑪					
Qty = $16.00 \text{ m}^2 @ 786.61/\text{m}^2$					12586.00
3) Providing & fixing 'logs'					
vide item no. ① VTMP ⑫					
Qty = 3 Nos. @ $10670.67/\text{each}$					32012.00
4) Painting of Parapet walls					
vide item no. ② VTMP ⑫					
Qty = $(20.640 + 21.44 + 21.44 +$					
$16.32 + 19.52 + 26.56) \text{ m}^2$					
= 125.92 m^2					
@ $137.83/\text{m}^2$					17356.00
37) Boundary Pillar/Guard Post					
vide item no. ① VTMP ⑬					
Qty = 96 Nos @ $668.20/\text{No.}$					64147.00
38) RCC M25 in Deck Slab vide					
item no. ③ VTMP ⑬					
Qty = $4.608 \text{ m}^3 @ 7228.53/\text{m}^3$					33295.00
39) Const. of Subgrade & E/w Shoulder					
vide item no. ⑩ VTMP ⑭					
Qty = $1030.95 \text{ m}^3 @ 264.63/\text{m}^3$					272820.00
				C.O =	4415522.00

Continuation

[illegible]