

21121211 2111 410 500 510 211 4 13 11 11

(25)

Schedule XLV-Form No. 134

MMSY (MEN)

R.W.D (w) SASARAM DIVISION

R.W.D (w) SASARAM SUB-DIVISION

Measurement Book

3076

Barbaram Singh

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
3rd Year ABSTRACT OF COST					
① Restoration of Raincoats -					
Qty vide TMB P.No - (43)					
I.No ① 35.3 $22m^2$ @ 378.32 =					13363.00
② Making up of Beams/Shoulder -					
Qty vide TMB P.No - (43)					
I.No ② 168 m^2 @ 57.35 =					9635.00
③ Repair of pot holes 75mm BM -					
Qty vide TMB P.No - (43)					
I.No ③ 1.55 m^3 @ 11950.28 =					18523.00
④ Patch repair over pot holes -					
20mm premix Carpet - do - do -					
Qty vide TMB P.No - (44)					
I.No ④ 21.0 m^2 @ 321.12 =					6744.00
⑤ Patch repair over bituminous					
20mm premix do - do					
Qty vide TMB P.No - (44)					
I.No ⑤ 20.86 m^2 @ 338.72 =					7066.00
⑥ Maint. of H.P.C -					
Qty vide TMB P.No - (44)					
I.No ⑥ 3.00 @ 1109.67 =					3329.00
⑦ Maint. of slab curbs -					
Qty vide TMB P.No - (44)					
I.No ⑦ 1.00 @ 2291.44 =					2291.00
⑧ Maint. of Road signs -					
Qty vide TMB P.No - (44)					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
I.No. ⑧ 0-08 km @	1066	.50	=	80 = ∞	
⑨ Main l.of 9.00 meter km post-					
Qty vide TMB P.No - ④④					
I.No. ⑩ 0.09 km @	650	.87	=	59 = ∞	
⑩ Cartling of branches of tree shrub					
Qty vide TMB P.No - ④④					
I.No. ⑪ I.No @	105	.39	=	105 = ∞	
⑪ White washing on parapet wall -					
Qty vide TMB P.No - ④④					
I.No - ⑫ 630 m ² @	16	.47	=	1038 = ∞	
Total R S =				62233 = ∞	
Less 10 % Below RS =				6223 = ∞	
RS =				56010 = ∞	

50%
28.56.24
J.E. 10/10/2011