

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/10/-	Const. of road with 5 years.				
	- Maint. from Ramchandra Das's				
	house via govt. Middle School				
	Bansupatti to N.H. 77 near Shiv				
	Mandir under Margay Scheme.				
Agency-	Savit Kumar Shahi				
Agg. No.-	118535/20-21				
D.O.-S/-	09.02.21				
D.O.CI-	08.11.21				
A.D.O.CI-	04.02.22				
Maint. period/-	05.02.24 to				
	04.02.25				

Record Measurement:-

① Restoration of rain cuts/berms-

2 x 22.10m x 0.70m x 0.25m =	7.74m ³
2 x 17.90m x 0.65m x 0.25m =	5.82m ³
2 x 26.40m x 0.60m x 0.25m =	7.92m ³
2 x 15.80m x 0.65m x 0.25m =	5.13m ³
2 x 20.30m x 0.75m x 0.25m =	7.61m ³
	34.22m ³

② Making up of berms/shoulders-

4 x 12.50m x 0.60m =	30.0m ²
4 x 9.30m x 0.45m =	16.74m ²
2 x 17.10m x 0.40m =	13.68m ²
2 x 22.40m x 0.50m =	22.40m ²
	82.82m ²

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				RP/-	82.82m ²
2x13.20m x 0.40m =					10.56m ²
					93.38m ²
③ Repair of pot holes with					
1x6.0m x 0.70m =					4.20m ²
1x8.10m x 0.55m =					4.45m ²
1x10.30m x 0.60m =					6.18m ²
					14.83m ²
④ Patch repair over pot holes					
1x9.40m x 0.60m =					5.64m ²
1x8.35m x 0.50m =					4.17m ²
1x10.40m x 0.70m =					7.28m ²
					17.09m ²
⑤ Repair of Bituminous with					
1x12.40m x 0.45m =					5.58m ²
1x11.60m x 0.30m =					3.48m ²
1x17.25m x 0.90m =					6.90
					8.62m ²
					15.96m ²
⑥ Repair of road sign					
1x0.08 km					0.08 km
⑦ Cutting of branches of tree					
1x1.0 NO					1.0 NO.
⑧ P/L of hot applied thermoplate					
1x18.40m x 0.45m =					8.28m ²
1x16.35m x 0.50m =					8.17m ²
2x20.20m x 0.70m =					28.28m ²
1x12.0m x 0.45m =					5.40m ²
					50.13m ²

Continuation

Qty VMBP (18)

Unit Qty - 50.0m²

Sch. XLV—Form No. 134

Sch. XLV—Form No. 134					Contents of area
Particulars	Details of actual measurement				
	No.	L.	B.	D.	
⑨ Rigid portion -					
	2	16.90m	0.45m	=	15.21m ²
	1	17.40m	0.50m	=	8.70m ²
	1	22.30m	0.40m	=	8.92m ²
	1	15.40m	0.60m	=	9.24m ²
	1	12.0m	0.50m	=	6.0m ²
Qty of TMS R(18) =				50.0m ²	48.07m ²
⑩ Area of Already Planted -					
	0	16.0	1.0	=	16.0
<i>10/03/20</i> <i>28</i> <i>Signature</i> <i>10/03/20</i> <i>22</i>					

Abstract of Cost (3rd yr. Maint. Bill)

54

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of rain cuts/berms—					
Qty VmBPS ① = 34.22 m ³					
① Rs. 404.06/m ³ Rs. 13827.00					
② Making up of berms/Shoulders—					
Qty VmBPS ② = 93.38 m ²					
② Rs. 60.28/m ² Rs. 5629.00					
③ Repair of pot holes with—					
Qty VmBPS ③ = 14.53 m ²					
③ Rs. 309.02/m ² Rs. 4583.00					
④ Patch repair over pot—					
Qty VmBPS ④ = 17.09 m ²					
④ Rs. 265.52/m ² Rs. 4538.00					
⑤ Maint. of bituminous run—					
Qty VmBPS ⑤ = 15.96 m ²					
⑤ Rs. 283.67/m ² Rs. 4527.00					
⑥ Maint. of road sign—					
Qty VmBPS ⑥ = 0.08 km					
⑥ Rs. 1104.14/km Rs. 88.00					
⑦ Pruning of branches off tree—					
Qty VmBPS ⑦ = 1.0110					
⑦ Rs. 113.64/110 Rs. 114.00					
⑧ M/L of hot applied thermoplastic—					
Qty VmBPS ⑧ = 50.0 m ²					
⑧ Rs. 721.95/m ² Rs. 36098.00					
⑨ Riped Portion—					
Qty VmBPS ⑨ = 48.67 m ²					

Continuation

Material.

① Coastal - 34.22 m^3

② As - 23.28 m^3

③ Bushed stone - 3.94 m^3

④ As - 523.37 m^3

RS-2 - 0.04013 m^3

R-90 - 0.277305 m^3