

59
2nd year maintenance.
Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work: Maint. of road from					
mukhi Thakur ke ghar					
To Samba wali.					
Agency: vikash kr. pandey					
Agg.No:-					
Actual completion date:- 05/02/2023.					
<u>Record Entry</u>					
1.	Restoration of				
	raincuts do-				
	15X	6.48	X 1.19	X 0.30	= 34.70m ³
	18X	5.92	X 1.20	X 0.30	= 38.36m ³
					73.06m ³
2.	making up of				
	earth shoulder do-				
	2X16X	7.32	X 1.34		= 313.88m ²
	2X13X	6.94	X 1.28		= 230.96m ²
					544.84m ²
3.	patch repair over				
	B.T surface do-				
	8X	4.45	X 0.91		= 32.40m ²
	9X	3.27	X 0.81		= 23.84m ²
					56.24m ²
4.	Maint HPC do-				
	= 1 No.				
5.	Maint of slab				
	Culvert do-				
	= 3 No.				
6.	Maint. of road				
	signs do-				
	= 0.90km				

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
7. Maint. of road signs - 0.90 m					
78. Maint. of 200 m					
km stone - do - 2					1.81 km
8. Trimming of grass					
& weeds - do -					
28 17 X 30.00 X 1.322					1346.40
19. Maint. of trees by					
road sides - do - 2					120 Mo.
<u>Asila</u> 01/02/25 P.S.					
<u>Asila</u> 01/02/25 P.S.					

Abstract of cost					
(11).	Restoration of				
	raincuts - do -				
73.06 m ³	vide T.m.B p. - (59)				
RS. 407.70/m ³				RS. 29787.00	
(12).	Making up of				
	earthen shoulder - do -				
544.84 m ²	vide T.m.B p. - (59)				
RS. 60.79/m ²				RS. 33121.00	
(13).	patch repairs over				
	B.T surface - do -				
56.24 m ²	vide T.m.B p. - (59)				
RS. 289.44/m ²				RS. 16278.00	
(14).	Maint of M.P.C - do -				
1 No.	vide T.m.B p. - (59)				

Continuation

Continuation