

Block - Runnisaidpur.

श्री १२२६५५ (५०) श्री गणेशाय नमः श्री १३१-१५६५१ श्री
श्री १३१-१५६५१ श्री १३१-१५६५१ श्री १३१-१५६५१ श्री १३१-१५६५१

Schedule XLV-Form No. 134
Appendix No. 97SBD/2020-21)

११०५५-५५ DIVISION

SUB-DIVISION

MEASUREMENT BOOK

Mans Bhushan Kumar,

4275

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/101- Const. of road with 15 year maint. from Bhagwan Lal Mahato's house to picksoni Baghain Road under mistry (SC) scheme.					
Agency:- Karami Bhusham Kumar					
Agg. No:- 97535/20-21					
D.O.S:- 29.12.20					
D.O.C:- 28.12.2021					
A.D.O.C:- 28.09.21					
Maint:- 29.09.23 to 28.09.24					

<u>Record Measurement:-</u>				
① Record Restoration of rain cuts/Berms with 561				
1x16.70m	x0.70m	x0.25m	=	2.92m ³
2x14.90m	x0.60m	x0.25m	=	4.47m ³
2x17.20m	x0.65m	x0.25m	=	5.62m ³
2x12.20m	x0.45m	x0.25m	=	2.74m ³
2x22.40m	x0.55m	x0.25m	=	6.16m ³
1x27.00m	x0.50m	x0.25m	=	3.75m ³
				6.75m³
				25.28m ³
② Maint. of road high - - -				
1x	0.06 Km		=	0.061cm
③ Maint. of 200 mm and Km stone - - -				
1x	0.07 Km		=	0.071cm

Continuation

Scanned with CamScanner

Abstract of cost
(39 years against Bill).

34

Sch. XLV-Form No. 134

[illegible]

Continuation

97 B/1104-24 EE