

4th year maintenance

77

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work :- Maint. of road from Harpur					
To Toli Harpur Chauk					
Agency :- Arbind K. Singh					
Reg. No :- 1075BB/MMHSY/2019-20					
Actual date of completion :- 28/04/2021.					
<u>Record Entry :</u>					
1. Restoration of					
rainscuts -do-					
8X 5.98X 1.12X 0.30 = 16.07m ³					
9X 6.74X 1.15X 0.30 = 20.93m ³					
5X 4.12X 2.10X 0.30 = 12.98m ³					
					49.98m ³
2. Making up of					
earthen shoulder -do-					
2X 11X 3.46X 2.04 = 155.28m ²					
2X 9X 4.81X 2.09 = 180.95m ²					
2X 14X 5.94X 2.14 = 355.92m ²					
2X 7X 6.73X 2.17 = 204.46m ²					
2X 10X 5.48X 2.08 = 238.93m ²					
					1135.54m ²
3. Repair of potholes -do-					
6X 4.44 X 1.3 8 = 36.76m ²					
8X 3.07 X 1.2 1 = 29.72m ²					
					34.56m ²
					66.48m ²
					limit = 65.63m ²
4. patch repairs over bituminous -do-					
Qty. same as above item = 65.63m ²					

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
5. Maint. of road signs do = 1.42 km					
6. Maint. of 200m of km stone do = 2.84 km					
7. Trimming of grass of weeds do					
	2411 X 30.00 X 1.06 =	699.60 m ²			
8. Maint. of trees by road sides do = 66 No.					
<i>Akila 26/04/98 F.E.</i>					
<i>to recover on cost</i>					
(1). Restoration of rainwater do					
49.98 m ³ Vide T.m.B P (77)					
	RS. 379.50/m ³	RS. 18972.00			
(2). Making up of erosion shoulder do					
1135.54 m ² Vide T.m.B P (77)					
	RS. 57.01/m ²	RS. 64737.00			
(3). Repair of potholes do					
65.63 m ² Vide T.m.B P (77)					
	RS. 407.40/m ²	RS. 26738.00			
(4). Patch repair others B.T Surface do					
65.63 m ² Vide T.m.B P (77)					

C/O - RS. 110447.00

Continuation

Continuation