

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, सहरसा

Email ID:-ee.saharsa.rwd2@gmail.com

Mob:- 8986915395

पत्रांक 1128 (3730)

सहरसा/दिनांक 30/05/2025

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सहरसा

सेवा में,

नोडल पदाधिकारी (MR 3054)
ग्रामीण कार्य विभाग
पटना, बिहार

विषय :- नई अनुरक्षण नीति-2018MR (3054)योजना के अंतर्गत पथ में कराये गये कार्य के विरुद्ध आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में सूचित करना है कि नई अनुरक्षण नीति-2018 MR (3054)योजना के अंतर्गत पथ में कराये गये कार्य के लिए संवेदक को भुगतान करने हेतु अधियाचना विहित प्रपत्र में भरकर आवश्यक कार्यवाही हेतु समर्पित की जाती है।

अनु :- यथोक्त।

विश्वासभाजन


30/5/25
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सहरसा।

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)

Form of Utilization Certificate up to May 30, 2025

Sl.No	Name of Scheme	Sanction No.&Date With Amount (In lac Rs.)	Amount Received (In lac Rs.)	Particulars
1	Construction of Rural roads Under "New Maintenance Policy-2018 MR (3054)"	New Maintenance Policy-2018 MR (3054) BRRDA PATNA Lt no-45 Dt-27.05.2025	7855.75602	Certified that out of Rs.7855.75602 Lac of grants-in-aid sanctioned during the years 2025-26. In favor of EE,RWD Works Division Saharsa a sum of Rs. 7565.84005 lac has been utilized for the purpose of MR (3054) Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 289.91597 Lac remaining unutilized at the end of the period under report.
	Total:		7855.75602	

2. Certified that I have satisfied myself that the conditions on which the grant-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was utilized for the purpose for which it was sanctioned.

Kind of Checks exercised:-

- Works have been supervised by Executive Engineer/ Superintending Engineer.
 - Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
 - Construction materials have been tested.
 - Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
 - All other caudal formalities have been observed.
3. **Physical Progress achieved:-**
- Construction of Road Works.
 - Construction of CD works.


Divisional Accounts Officer
R.W.D, works Division
Saharsa.


Executive Engineer
R.W.D, works Division
Saharsa.

Rural Works Department

MIR NEW MAINTENANCE POLICY-2018 REQUISITION

Name of Division:- RWWD Works Division Saharsa

SL. No.	Year	Name of Road	Name of Contractor (In English)	Project Id	Administrative Sanction		Agreement Amount (In Lacs)		Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Allotment Received (in Lacs)	Total Expenditure as per MIS (in Lacs)	Value of Measurement (in Lacs)	Current Demand (in Lacs)	Remarks
					Length (in KM)	Amount (in Lac)	Main Work Amount	Maintenance Amount								
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17
1	2023-24	Saharsa Sonbarsa Road Dhakjuri Village To Bharauli	Pankaj Kumar Singh	20904312013	2.500	139.776	90.50679	18.20415	3257	25mm	5%	0.000000	0.000000	90.50679	90.50679	Work Completed
Total					2.500	139.776	90.507	18.204				0.000000	0.000000	90.50679	90.50679	

Rural Works Department
Works Division, Saharsa

Executive Engineer
Rural Works Department
Works Division, Saharsa

20/5/24 P.C.

20/5/24

Name of Road:- Saharsa Sonbarsa Road Dhakjari Village To Bharauli
Name of Contractor:- Pankaj Kumar Singh

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY ROAD	Latitude	Longitude	Event
26/05/25	8:33:19	71	0.1	290	0	2900	3475 G		25.82140	86.583527	Normal
26/05/25	8:33:54	71	0.1	320	10.1	3200	3816 G		25.821339	86.583547	Normal
26/05/25	8:34:0	71	0.1	260	20.2	2600	3134 G		25.814713	86.578737	Normal
26/05/25	8:34:0	71	0.1	260	30.3	2600	3134 G		25.814713	86.58737	Normal
26/05/25	8:34:0	71	0.1	290	30.3	2900	3475 G		25.814232	86.579471	Normal
26/05/25	8:34:0	71	0.1	250	40.4	2500	3020 G		25.812445	86.580852	Normal
26/05/25	8:34:30	71	0.1	240	40.4	2400	2907 G		25.812663	86.580737	Normal
26/05/25	8:34:30	71	0.1	200	40.4	2000	2452 G		25.81419	86.58009	Normal
26/05/25	8:34:30	71	0.1	290	30.3	2900	3475 G		25.815311	86.578014	Normal
26/05/25	8:35:0	71	0.1	290	40.4	2900	3475 G		25.816891	86.579104	Normal
26/05/25	8:35:5	71	0.1	240	20.2	2400	2907 G		25.818847	86.580413	Normal
26/05/25	8:35:5	71	0.1	240	20.2	2400	2907 G		25.818841	86.580408	Normal
26/05/25	8:35:5	71	0.1	200	30.3	2000	2452 G		25.820195	86.58207	Normal
26/05/25	8:35:41	71	0.1	250	30.3	2500	3020 G		25.821495	86.58291	Normal
26/05/25	8:36:0	71	0.1	260	10.1	2600	3134 G		25.821495	86.582909	Curve
26/05/25	8:36:16	71	0.1	300	20.2	3000	3588 G		25.821397	86.583623	Curve
26/05/25	8:36:16	71	0.1	310	30.3	3100	3702 G		25.821389	86.583547	Normal
26/05/25	8:36:16	71	0.1	300	40.4	3000	3588 G		24.713342	85.285387	Normal
26/05/25	8:36:16	71	0.1	300	30.3	3000	3588 G		24.710163	85.28968	Normal
26/05/25	8:37:0	71	0.1	240	30.3	2400	2907 G		24.707023	85.289057	Normal
26/05/25	8:37:0	71	0.1	240	30.3	2400	2907 G		24.70785	85.27508	Normal
26/05/25	8:37:0	71	0.1	300	20.2	3000	3588 G		24.721005	85.262103	Curve
26/05/25	8:37:0	71	0.1	300	30.3	3000	3588 G		25.82140	86.583527	Normal
26/05/25	8:37:26	71	0.1	310	20.2	3100	3702 G		25.821339	86.583547	Normal
26/05/25	8:37:26	71	0.1	290	10.1	2900	3475 G		25.821368	86.583564	Normal
Average IRI							3257				

Y = 0 * X ^ 2 + 1.136 * X + 181
X = 2900
Y = 3475
(R) RURAL ROAD
Good Average Poor
<4000 4001-5000 >5001

26/5/25

26/5/25

26/5/25

4452

3452

2452

1452

U/V
mm/
km

File : E:\Steco Bumb Indicator Report\28.01.2025\26050246.Xls. Section No. : 71. Eqn : $Y = 0 * X^2 + 1.136 * X + 18$
Name of Customer : Pankaj Kumar Singh. Name of Work/ Road : Saharsa Sonbarasa Road Dhakjari Village to Bharaul

Distance * 1000 m

0 0.0010.0020.0030.0040.0050.0060.0070.0080.0090.010.0110.0120.0130.0140.0150.0160.0170.0180.0190.020.0210.0220.0230.0240.025

26/05/25
26/05/25

26/05/25
26/05/25

26/05/25
26/05/25