

3rd year 17<sup>th</sup> maintenance  
Sch. XLV-Form No. 134

| Particulars | Details of actual measurement |    |    |    | Contents of area |
|-------------|-------------------------------|----|----|----|------------------|
|             | No.                           | L. | B. | D. |                  |

N/w:- Mainf. of road from Ganga  
Kaurf to Gola to Rasta Shah Ka  
Pola.

Agency - Sri Manoj Mishra.

Ag. No - 66 SEP / PMAS / 2021-2022

Date of Start - 11/06/2021

Actual completion 21/09/2022

Record Entry

① Rehabilitation of road  
cut - 20 -

$$10 \times 4.40 \times 1.00 \times 0.30 = 15.84$$

$$16 \times 3.70 \times 1.10 \times 0.30 = 20.59$$

$$9 \times 4.60 \times 1.05 \times 0.30 = 13.04$$

$$8 \times 4.90 \times 0.95 \times 0.30 = 11.17$$

$$7 \times 5.30 \times 0.90 \times 0.30 = 10.02$$

$$6 \times 6.40 \times 0.85 \times 0.30 = 9.79$$

$$8 \times 5.20 \times 0.80 \times 0.30 = 10.18$$

$$6 \times 5.95 \times 0.85 \times 0.30 = 9.10$$

99.73 m

② Mainf. of Gullies  
Shoulder - 20 -

$$2 \times 9 \times 6.60 \times 0.95 = 112.86$$

$$2 \times 8 \times 5.80 \times 1.10 = 102.08$$

Continuation

| Particulars                           | Details of actual measurement |    |    |    | Contents of area |
|---------------------------------------|-------------------------------|----|----|----|------------------|
|                                       | No.                           | L. | B. | D. |                  |
| <u>Abstract of cost</u>               |                               |    |    |    |                  |
| ① Restoration of rain cuts — do —     |                               |    |    |    |                  |
| 99.78 m <sup>2</sup> — wide — P-75    |                               |    |    |    |                  |
| @ 396.79/m <sup>2</sup> —————         |                               |    |    | 6  | 39566.10         |
| ② Maint. of earthen shoulder — do —   |                               |    |    |    |                  |
| 554.99 m <sup>2</sup> — wide — P-75   |                               |    |    |    |                  |
| @ 59.87/m <sup>2</sup> —————          |                               |    |    | 6  | 33191.10         |
| ③ Repair of lat holes — do —          |                               |    |    |    |                  |
| @ 437.18/m <sup>2</sup> —————         |                               |    |    | 6  | 44247.10         |
| ④ Patch repair over lat holes — do —  |                               |    |    |    |                  |
| 101.91 m <sup>2</sup> — wide — P-76   |                               |    |    |    |                  |
| @ 287.66/m <sup>2</sup> —————         |                               |    |    | 6  | 29114.10         |
| ⑤ Maint. of stone pipe culvert — do — |                               |    |    |    |                  |
| 03 Nos. — wide — P-77                 |                               |    |    |    |                  |
| @ 1130.67/each —————                  |                               |    |    | 6  | 3392.10          |
| ⑥ Maint. of road sign — do —          |                               |    |    |    |                  |

Continuation

| Particulars                                                                                 | Details of actual measurement |    |    |    | Contents of area |
|---------------------------------------------------------------------------------------------|-------------------------------|----|----|----|------------------|
|                                                                                             | No.                           | L. | B. | D. |                  |
| ⑫ White washing of furo<br>road parapet walls - 620 -<br>62.98 m <sup>2</sup> - side - 1-78 |                               |    |    |    |                  |
| @ 16.84/m <sup>2</sup>                                                                      |                               |    |    | 6  | 1060.00          |
| Total =                                                                                     |                               |    |    | 6  | 4470.91          |
| Add B.S.T @ 12% -                                                                           |                               |    |    | 6  | 5365.10          |
| Add J.C @ 1% -                                                                              |                               |    |    | 6  | 4471.00          |
| Add S.F.C -                                                                                 |                               |    |    | 6  | 489.00           |
| Total =                                                                                     |                               |    |    | 6  | 50570.2          |
| Less @ 0.11% Rebar -                                                                        |                               |    |    | 6  | - 586.10         |
|                                                                                             |                               |    |    | 6  | 50514.6          |

*[Signature]*  
29/05/2023  
S.R.

Material used:-

|             |   |                        |
|-------------|---|------------------------|
| Earthwork   | - | 182.889 m <sup>3</sup> |
| Emulsion    | - | 32.00 k                |
| Sand        | - | 0.607 m <sup>3</sup>   |
| Bitumen     | - | 218.00 k               |
| Stone chips | - | 2.733 m <sup>3</sup>   |

*[Signature]*  
29/05/2023  
S.R.