

Continuation

2nd yr Mauts Bill
ABSTRACTS OF COST

11

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Restoration of Raincuts					
Qty vide P.No 9 in TMB					
		90.81	M ³		
@ R 386		344	M ²		R 350652
2. Making up of Berms					
Shoulder stopping excor					
soil from the shoulder					
surface to achieve level					
Qty vide P.No 9 in TMB					
		508.10	M ²		
@ B 572		56	M ²		B 291312
3. 111/15 for repair of W					
bituminous surface					
with down M.S. Type B					
Qty vide P.No 9 in TMB					
		56.22	M ²		
@ R 2552		74	M ²		R 143782
4. Mauts of H. Pavement					
Qty vide P.No 10 in TMB					
		5	N		
@ R 11302		67	each		B 56532
5. Mauts of Road signs					
Qty vide P.No 10 in TMB					
		0.18	KM		
@ B 10772		82	KM		B 19420
			Total	B 244	2120

Continuation



Material statement

Q.W $1.25 \times 90 \text{ 8M}^3 = 113.512 \text{ M}^3$

Tack coat (RS-1) 0.016 MT

M.S.S (S-90) 0.106 MT

Crushed stone Aggregate

1.517 M^3

QR 408 $= 83 \text{ M}^3$

Biny / 08/09/2025
SF

Rahul Raturaj
08/09/25
AE

