

Tei construction

MS. No. 1719

Schedule XLV-Form No. 134

Muzaffarpur East-2 DIVISION

Meerapur SUB-DIVISION

Madhubani P.O. D Pith. to Danyapur

SE Sheohar Sadak Tak

MEASUREMENT BOOK

Tei construction

ABSTRACT of Cos.


37

Sch.XLV-Form No. 134

Particulars	Details of actual measure				Contents of area
	No.	L.	B.	D.	
1. Restoration of Rain cuts					
with safe vide item					
① & P.N. (35)					
138.52 M ³					
@ Rs 398.08/M ³					Rs 55142 = 0
2. Maintenance of Earthen					
Shoulder vide item					
① & P.N. (35)					
781.91 M ³					
@ Rs 62.85/M ³					Rs 49143 = 0
3. Repair to Pot hole mix					
seal Surface vide item					
N.O. 3 & P.N. 35					
65.20 M ²					
@ Rs 556.52/M ²					Rs 36291 = 0
4. Maintenance of Lume pipe					
curry vide item ①					
① P.N. (35)					
2 M.B.					
@ Rs 1299.88/c					Rs 2600 = 0
5. Maintenance of seal culvert					
vide item ⑤ & P.N. (35)					
2 M.B.					
@ Rs 658.66/c					Rs 5317 = 0
6. Maintenance of 100 metre					
and KM stone.					
vide item ⑤ & P.N. 35					
2.74 KM					
@ Rs 377.18/KM					Rs 2403 = 0
C.O.					Rs 150896 = 0

Continuation

Sch.XLV-Form No. 134

Particulars	Details of actual measure				Contents of area
	No.	L.	B.	D.	
		B.F.			R ₂ 150896 = 100
Add 1% Labour cess					R ₂ 1509 = 100
Add 12% G.S.T.					R ₂ 18108 = 100
Add 10% S.F.					R ₂ 2090 = 100
					R ₂ 172603 = 100
Less 10% beton					R ₂ 17260 = 100
					R ₂ 155348 = 100
 19/10/2015 JE					

Material statement

1. Earth - 221.17 m³
2. bitumen - 0.12 m³
3. Stone - 1.76 m³

Continuation