

MD. ASFAK ALAM M.B. No - 1104

MMESY-50

Schedule XLV-Form No. 134

R.W.D. Madhepura. DIVISION

R.W.D. Shrikerkhura SUB-DIVISION
2nd Time Measurement Entered

Measurement Book

for Ashfaqur Alam.

Supra Bandha Sadhara to Bandha Sadhara
Tumkur Sadhara to Tumkur

Abstract of Cost			
1/1.	Restoration of Raincuts/Berms etc....do	Qty vide TMB P- 40	
		33.87 m ³ @ Rs 379.59 / m ³	
		= Rs	12856.71
2/2	Making up berms/shoulder strips by excess soil from of the should er --- do --- E/I	Qty vide TMB P- 40	
		754.55 m ² @ Rs 56.81	= Rs. 42865.99
3/3	Repair of pot holes filled with 75 MM WBM.	Qty vide TMB P- 40	
		39.3 m ² @ Rs 289.66	= Rs 11384.00
4/5.	Patch Repair Over Bituminous surface with 20 MM ---	Qty vide TMB P- 41	
		39.3 m ² @ 186.07	= Rs 7313.00
5	Maintenance of CP (HP) Culvert.		
	3 Nos. @ Rs 1102.80/-	= Rs	3308.40

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
G. Maintenance of Road Signs.					
0.26 km @ RS 1054.20 VTMB P-4				- RS	274.11
T. Maintenance of 200 m And Km Stone - RS					
Qty upto TMB P-4 0.41 km @ 561.09				- RS	230.05/
			Total.	RS	78282.2
			Add GST 12% (+)	RS	9387.87
			Add 1% LC (+)		782.3
					88402.4
			Below 1.25% (-)		1105.03
					87297.09
Pratik Kumar 20.11.24					