

5th year maintenance

71

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/w: Ramkrishnapur REO Sadak					
to Bishanpur REO					
Agency: Mr. Mustafa					
Ag. No: 04 (SBD) / 2019-20					
D.O. No. 21/09/2019					
Actual D.O.C - 02/09/2020					

① Restoration of Raincuts -

$$14 \times 3.10 \times 1.15 \times 0.30 = 14.97$$

$$12 \times 2.55 \times 1.20 \times 0.35 = 12.85$$

$$15 \times 3.10 \times 1.00 \times 0.30 = 13.95$$

$$20 \times 2.55 \times 1.20 \times 0.35 = 21.42$$

$$16 \times 2.40 \times 1.10 \times 0.30 = 12.67$$

$$18 \times 3.25 \times 0.95 \times 0.35 = 19.45$$

$$15 \times 2.85 \times 1.10 \times 0.30 = 14.10$$

$$109.41 \text{ m}^3$$

② Maint. of Berms/shoulder -

$$24 \times 5.50 \times 0.90 = 118.8$$

$$18 \times 7.50 \times 0.80 = 108.0$$

$$25 \times 10.0 \times 0.80 = 200.0$$

$$20 \times 8.00 \times 0.85 = 136.0$$

$$15 \times 6.70 \times 0.90 = 90.45$$

$$22 \times 7.50 \times 0.95 = 156.75$$

$$810.00 \text{ m}^3$$

③ Repair to pot holes with

WBM -

$$14 \times 2.95 \times 1.00 = 41.30$$

$$12 \times 2.40 \times 1.10 = 31.68$$

Continuation

$$72.98 \text{ m}^3$$

S.A. 111 - Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
		3x1	—	3 nos.	
		Qty. vide Trib P-72	—	3 nos.	
		3 nos. @ RS. 1117.00/nos.		RS.	3351
(6) Road marking of BT surface					
		Qty vide Trib P-72		240 m ²	
		240 m ² @ RS. 850.93/m ²			
					RS-204223.00
(7) Road marking of C.C. surface					
		Qty. vide Trib P-72		80 m ²	
		80 m ² @ 953.99/m ²		RS-	76319.00
					RS. 451720.00
		Less 10% Below (-)		RS.	45172.00
					RS. 406548.00

Material statement

C/W - 121.5 m³
 S/metal - 170.29 m³
 S/chips - 126.66 m³
 RS-1 - 38.5 kg
 Bitumen 0.341 MT

P3

 13/09/2025
 JE