

[illegible]

M.B. R101 - 822 ~~2557-17~~
DIVISION

CH 26-10-2019
SUB-DIVISION

MEASUREMENT BOOK

4th year maintenance bill

78

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W - Routine maintenance work for 4th year of Social for Lozi Chote Lal Sing Ke Bagi cha to mark / Nawada Zila Sing Kark - M.M. (S.C) at block / Katarisara					
M / Agency - Nacari Construction Pvt. Ltd.					
Agg / No - 261 SBI / 2019 / 20					
Actual date of completion -					
				12/6/21	
Date of measurement -				3/8/25	

1st year work

① Restoration of rainwater / Berms with soil -

12 x 10 m x 1.25 x 0.3 =	45.0 m ³
10 x 13 m x 1.20 x 0.28 =	43.68 m ³
11 x 8 m x 1.10 x 0.25 =	24.2 m ³
10 x 9 m x 1.10 x 0.27 =	26.97 m ³
Total	139.85 m³

② making of up of Berms s/shoulder stripping excess soil
Shoulder

07 x 10 m x 1.25 m =	87.5 m ²
05 x 12 m x 1.20 m =	72 m ²

Continuation



1. Hygiene maintenance bill

84

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
K/w - Routine maintenance					
walk fresh floor of					
prayer hall 1031 Chhatra					
Lal Singh ka Bagicha					
to murel (Kavai) Alasima					
Kak - (M Mury) at					
block Katariswari					
M / Agency - Nadei Construction					
PVT. LTD					
Agg / No - 76 / SBD / 2019-20					
Actual Date of completion - 12/11/20					
Date of maintenance - 3/8/25					

1st term of work					
(1.) Restoration of Kaincrits)					
Beams with soil					
12 x 2.65 x 1.95 x 0.30	=	11.92	m ³		
6 x 2.65 x 1.45 x 0.30	=	6.91	m ³		
8 x 2.30 x 1.8 x 0.30	=	9.93	m ³		
12 x 2.5 x 1.5 x 0.30	=	13.5	m ³		
9 x 3 x 2.1 x 0.30	=	17.01	m ³		
7 x 2.8 x 1.8 x 0.30	=	10.58	m ³		
5 x 1.4 x 2.2 x 0.30	=	4.62	m ³		
12 x 2.85 x 1.60 x 0.30	=	16.41	m ³		
15 x 2.70 x 1.65 x 0.30	=	20.04	m ³		
12 x 2.85 x 1.40 x 0.30	=	14.36	m ³		
10 x 3.20 x 1.50 x 0.30	=	14.40	m ³		

Continuation

Total = 139.70
139.88



Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
② Making up of Borders/Shoulders →					
15 X 4.20 X 1.10 =					69.30 m ²
18 X 2.80 X 1.10 =					55.44 m ²
15 X 3.75 X 1.125 =					63.28 m ²
10 X 4.70 X 1.125 =					52.87 m ²
12 X 3.20 X 1.10 =					42.24 m ²
18 X 3.75 X 1.25 =					75.93 m ²
16 X 4.10 X 1.195 =					73.80 m ²
10 X 3.50 X 1.10 =					38.50 m ²
15 X 3.80 X 1.10 =					62.70 m ²
12 X 4.20 X 1.25 =					63.00 m ²
14 X 3.5 X 1.10 =					53.9 m ²
15 X 4.1 X 1.20 =					73.8 m ²
8 X 2.5 X 1.20 =					24 m ²
9 X 3.1 X 1.10 =					30.49 m ²
total					779.15 m ²
					779.45

③ Repair of pot holes filled with 75mm

10 X 2.15 X 1.20 X 0.075 =	1.93 m ³
12 X 1.80 X 1.08 X 0.075 =	2.43 m ³
7 X 1.50 X 1.10 X 0.075 =	0.94 m ³
6 X 1.70 X 1.35 X 0.075 =	1.03 m ³
10 X 2.10 X 1.20 X 0.075 =	1.89 m ³
8 X 1.80 X 0.75 X 0.075 =	0.81 m ³
13 X 1.7 X 1.50 X 0.075 =	2.48 m ³

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
5 x 1.9 x 0.6 x 0.075					0.42 m ³
					11.93 m³
④ Patch repair over spot hole with 20 mm					
10 x 2.15 x 1.20					25.80 m ³
12 x 1.80 x 1.50					32.40 m ³
7 x 1.50 x 1.20					12.60 m ³
6 x 1.70 x 1.35					13.77 m ³
10 x 2.10 x 1.20					25.20 m ³
8 x 1.80 x 0.75					10.80 m ³
15 x 1.4 x 1.20					25.20 m ³
7 x 1.6 x 1.30					14.56 m ³
					164.49 m³
					164.52 m ³
					LTD = 163.13 m ³

- ⑤ Patch repair over Bt Surface with 20 mm premix carpet with seal coat Type B
 San Qty of S/NO-04
- ⑥ Maintenance of DP works
 Home pipe - No. 7
- ⑦ Maintenance of Road line
 — 0.26 km
- ⑧ Cutting of branches of trees and shrubs - No. 4

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Artificially cast					
① Restoration of drains / Berms with soil					139.88 139.70
			RS		380.52
			Total	RS	53158.64 53227 =
② Making up of Berms / shoulder excess soil					
			SVT / MBP		779.45 773.15 m
			RS		57.31/m ²
			Total	RS	44309.9 44670 =

③ Repair of pot holes filled with 75mm B.M					
			SVT + MBP		11.93 m ³
			RS		10286.89 (A)
			Total	RS	102722.59

④ Patch repair over pot holes with 20mm premix carpet					
			SVT + MBP		164.52 163.13 m ³
			279.74 (A)		
			Total RS		45634 = 45633.98 45623 =

⑤ Patch repair over Rt surface with 20mm premix					
---	--	--	--	--	--

Continuation

Continuation