

MB No - 1591

Post. P - Kewatgama Baisack Main Road 116
Charaki Usthan Road. - 2.790 K.M

MB No - 1591

Schedule XLV Form No. 134.

4x16.5 M.

1000/2000 DIVISION

Kumar Khand. SUB-DIVISION

MB - Bridge

Measurement Book

M/S. Jay Mata Di. Buzha

Particulars	Details of actual measurement				Contents of area
	No.	L	B.	D.	
1st Year Maintenance Work					
ABSTRACT OF COST					
① Restoration of Rain-cuts with soil etc. comp as per T.S.					
Qty vide TMA Pg No-18 item NO-1.					
4.24 m ³					
Unit = 4.22 m ³					
@ Rs 388.14/m ³					Rs 1629.04
② Making up of berms					
Shipping excess soil from the shoulder etc. comp as per T.S.					
Qty vide TMA Pg No-18-19 item NO-2					
22.20 m ²					
@ Rs 55.22/m ²					Rs 1297.04
③ Patch Repair over bituminous surface with 20mm m/c etc. comp as per T.S.					
Qty vide TMA Pg No-49 item NO-3					
					Rs 2856.00

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				B/10 R1	2888.00
2.35 m ²					
limit = 2.74 m ²					
@ R 218.87/m ²					R 593.00
④ Repair of RCC					
Railings etc. comp. as					
per L.S.					
only vide. T.M. Pg No					
49 Item No-4,					
160.38 m					
limit = 16.01 m					
@ R 2922.56/m ²					R 46784.00
				R 1	50170.00
				R 1	50153.00
ADD SST @ 12% of T.C. R 1					6018.00
ADD 1% @ 1% of T.C. R 1					502.00
ADD SF				R 1	12.00
				R 1	56685.00
18/03/25					
JE					