

Kishor Kumar Singh
Agno- 13 S.B.D/2019-20

Gharana Gharat M.M.Z.VY To Machhna Pali
M.M.G.S.Y (S.C)

Measurement Book

Schedule XLV-Form No. 134

Chagaria

DIVISION

Alandi

SUB-DIVISION

M.B-1048

17 year maintenance bill

54

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work :- Const ⁿ of Road from Ahana ghat NMGSP to Nakhra path NMGSP SC.					
Name of Agency :- Kishor Kumar Singh					
No. of Agreement :- 13 SBD/019-20.					
Date of work ^{start} order - 02/03/2020					
A.C.D.C - 20/06/2021					
(Const ⁿ work)					
① Restoration of Rainscut					
with soil - do - do - compact.					
1x10x2.4x0.90x0.45 = 8.10m ²					
1x10x5.10x $\frac{0.90+0.80}{2}$ x0.40 = 17.34m ²					
1x7x6.10x $\frac{0.70+0.40}{2}$ x0.55 = 12.91m ²					
1x15x4.10 $\frac{1.00+0.90}{2}$ x0.60 = 35.05m ²					
1x15x9.00 $\frac{0.95+0.90}{2}$ x0.58 = 22.77m ²					
					96.17m ²
② making up Berm/Shoulder					
stripping soil - do - do - well cut					
1x10x1.10x0.90 - = 9.9m ²					
1x10x6.70x $\frac{0.80+0.90}{2}$ - = 56.95m ²					
1x10x8.00x $\frac{1.10+0.90}{2}$ - = 80m ²					
1x10x9.00x0.85 - = 76.5m ²					
1x10x10x0.95 - = 95m ²					
1x10x7.80x0.89 - = 69m ²					
1x10x4.10x0.75 - = 30.75m ²					
					418.10m ²

Continuation

Abstract of cost

57

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of drain cuts with Soil - do - do -					
Qty vide T.M.B.P. (57)					
96.17 @ 371.59					36505.17
② Maling Bore shoulder strip Soil - do - do -					
Qty vide T.M.B.P. (57)					
418.10 @ 56.81					23752.26
③ Repair pot holes fitted over paten Repair do - do -					
Qty vide T.M.B.P. (57)					
87.03 @ 279.43					24318.79
④ Patch over potholes with 2mm Penning surface - do - do -					
Qty vide T.M.B.P. (57)					
87.03 @ 219.30					19085.67
⑤ Patch repair over bituminous surface with 20mm do - do -					
Qty vide T.M.B.P. (57)					
87.03 @ 236.93					20620.01
⑥ Maintenance of concrete H.P.C. rot do - do - do -					
Qty vide T.M.B.P. (57)					
110 @ 1102.80					1102.80
⑦ Maintenance of concrete slab culvert do - do -					
Qty vide T.M.B.P. (57)					

Continuation

Continuation