

Schedule XLV-Form No. 134

लघुगणित (अ) विभाग, ममस्य से.

RWD (W) Division, Tanjavarbur. DIVISION

RWD (W) Vidali, Madhebur SUB-DIVISION

MEASUREMENT BOOK

Shankar prasad

1574
1589

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
ABSTRACT OF COST					
3rd year maintenance					
(1) Repainting of sumpit					
beams with sand paper					
as per E/I					
atb with T.M.B.P.-57(1)					
105.58 m ² @ 380.58/m ² =					40106.00
(2) Making up beams & pillars					
as per E/I					
atb with T.M.B.P.-57(2)					
543.68 m ² @ 58.37/m ² =					31735.00
(3) Repair of Pol. Vals + Vals					
with 25mm B.M. as per E/I					
atb with T.M.B.P.-57(3)					
6.79 m ² @ 11200.88/m ² =					79490.00
(4) Patching up Pol. Vals					
with mixed sand paper					
as per E/I					
atb with T.M.B.P.-57(4)					
90.32 m ² @ 300.16/m ² =					27125.00
(5) Maintenance of road					
shoulder with E/I					
atb with F.A.-58(5)					
400.00 m @ 2.62/m =					1048.00
(6) Maintenance of C.D. work					
H.D.C. / vertical curve E/I					
atb with F.M.B.P.-58(6)					
03 H.D. @ 1117.00/m =					3351.00
(7) Maintenance of C.D. work					
					20-182955.00

Continuation

[illegible]

Continuation

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(11) White painting of P.W.D. wall of C.D. No. 12 H.P.					
current asp. E/I					
2+3+ 6.15+ 0.40					14.76 m ²
2+2+3+ 6.15+ 0.60					44.28 "
2+2+3+ 0.40+ 0.60					2.88 "
					61.92 m ²
(12) Road markings in B.T.					
Portion road above E/I					
2+4+ 30.4+ 0.10					252.00 m ²
2+ 27.4+ 0.10					5.40 "
					257.40 m ²
(13) Road markings in P.C.C.					
2+4+ 30.4+ 0.10					36.00 m ²
2+ 20.4+ 0.10					4.00 "
					40.00 m ²
ABSTRACT OF COST.					
5th year maintenance					
(11) restoration of beam and wall					
Ball masonry asp. E/I					
at 5 m to T.M.P. - 76(1)					
135.50 m ³ @ 380.58/m ³					51569.00
(12) masonry up beam and double					
asp. E/I					
at 5 m to T.M.P. - 77(2)					

Continuation

44-51569.00

