

17.11.65.Y. (GEN)

कार्य - T 10 सदनापुरा से करारी बिन्द टोला (बिन्दपुरवा)

Schedule XLV-Form No. 134

श्री रामचन्द्र पंडित, सहायक अभियन्ता

DIVISION

कार्य अवर प्रमंडल दुर्गावती

सर्वेक्षक - श्री चन्द्र किशोर

SUB-DIVISION

M.B.No-348

19-20

Measurement Book

Abstract Cost

① Restoration of reinforced - do -

vide TM P - (42) $at_1 = 40.50 m^3$

@ R 380.58 / m^3

R 15413 = 9

② Making up berum do - 1 -

vide TM P - (42) $at_1 = 225.00 m^2$

@ R 58 = 60 / m^2

R 13185 = 0

③ Repair of pot holes - do -

vide TM P - (42) $at_1 = 2.81 m^3$

@ R 11244.28 / m^3

R 31625 = 0

④ Patch repairs over pot holes - do -

vide TM P - (42) $at_1 = 37.50 m^2$

@ R 305 = 96 / m^2

R 11474 = 4 -

⑤ Patch repairs over broken m/s - do -

vide TM P - (42)

$at_1 = 37.50 m^2$

@ R 324 = 63 / m^2

R 12174 = 00

⑥ Maintenance road m/s do -

vide TM P - (42) $at_1 = 0.08 km$

@ R 1024 = 51 / km

R 81 = 00

⑦ Maintenance of road m/s do -

vide TM P - (42) $at_1 = 0.09 km$

@ R 654 = 04 / km

R 59.00 =

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
⑧ Cully branches do - do					
	side m P (43) at = 1.00 m				
	CR 106 = 52 / Nm				R 107 = 0
⑨ Cully g shrubs - do - do					
	side m P (43) at = 5.00 m				
	CR 6 = 54 / Nm				R 33 = 4
⑩ Cully g grass - do - do					
	side m P (43) at = 2.00 m				
	CR 218 / m ²				R 6 = 00
					R 84157 = 00
less 10% below					(C) R 8415 = 00
					R 75742 = 00
returning glass					June 15/12/2014
⑪ E/W = 38.00 m ³					
⑫ branches = 0.080 kg					
⑬ glass = 32 kg					
8-50 = 54.00 kg					
June 15/12/2014					

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	<u>Abstract of Cost</u>				
① Restoration of main cut - do -					
vide TMS P - (45)					at = 45.56 m ²
					CR 388.58/m ² Rs 17340 = 00
② Making up berm - do -					
vide TMS P - (45)					at = 253.13 m ²
					CR 58 = 60/m ² Rs 14833 = 00
③ Repair of pot hole - do -					
vide TMS P - (45)					at = 352 m ²
					CR 11244.28/m ² Rs 39531 = 00
④ Patch repair over pot hole -					
					vide TMS P - (45)
					at = 46.88 m ²
					CR 305 = 96/m ² Rs 14342 = 00
⑤ Patch repair over bitumen - do -					
					vide TMS P - (45)
					at = 46.88 m ²
					CR 324 = 63/m ² Rs 15217 = 00
⑥ Maintenance road 885 - do -					
					vide TMS P (45) at = 0.08 km
					CR 1074 = 51/km Rs 81 = 00
⑦ Maintenance of 200 m road - do -					
					vide TMS P (45) at = 0.12 km
					CR 654 = 04/km - Rs 78.00 =
⑧ Cully & branches - do -					
					vide TMS P - (45) at = 1.00 km
					CR 106 = 52/km Rs 107 = 00
⑨ Cully & branches - do - vide TMS P - (45)					at = 5.00 km
					CR 6 = 54/km Rs 33 = 00
⑩ Some of grass vide TMS P - (45)					at = 4.88 m ²
					CR 2 = 18/m ² Rs 11.00 =
less 10% below					Rs 101573 = W.
					Rs 10157 = W.

Continuation

Rs 91416 = 00

June 15/6/2025