

Name of Road - SH-101 Vishal Computer To
Yadav Tola Tak

MMWSY (Gien)

MBIND-6341

Schedule XLV-Form No. 134

✓

DIVISION

Taxaaya _____
SUB-DIVISION

Measurement Book

Yadav Preeti Kumari

year
4th Maintenance Bill

47

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W - Maintenance of Road					
from SH-104 Vishu					
computer to find Total					
Agency - Jyoti Preeti Kumari					
Actual Date of completion -					24-04-2021
Agg No - 24/MMSG/SBD/20.					
Date of starting -					03-02-2020.

					<u>Record Entry</u>
①	Restoration of rain				
	cuts - 2 - 2				
③	7X	4.00X	1.20X	0.300	= 10.08 m ³
	5X	10.00X	1.40X	0.300	= 21.00 m ³
	8X	5.30X	1.30X	0.300	= 16.54 m ³
	6X	4.60X	1.25X	0.300	= 10.35 m ³
	6X	6.00X	1.25X	0.300	= 13.50 m ³
	7X	4.50X	1.30X	0.300	= 12.29 m ³
					<u>83.76 m³</u>
②	Maintenance				
	of Both ends Sh.				
	cutted - 2 - 2				
	6X	5.50X	1.30		= 42.90 m ²

Continuation

~~AK~~ R-M-~~Am~~
 04/08/25 04/08/25
 AB J.E.

Abstract of List

(1) Restoration of
Raincreek — de — de —

83.76³ V.T.M.B.P. (44)

@ 380.58/m³ — R 31877 =

(2) Maintenance of
Eastern Shoulder

465.54 m² (V.T.

M.B.P. — 48)

@ 58.37/m² — R 27176 = ∞

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(3) Repair of pot hole do do do do					
7.20 m ³ (V.T.M.					
B.P-48)					
@ Rs 20028.10/m ³ - Rs 144202 =					
(4) Patch Repair over pot hole - do - do -					
96.0 m ² (V.T.M.B.P-48)					
@ Rs 682.98/m ² - Rs 65566 =					
(5) Patch Repair over B.T. surface - do -					
96.0 m ²					
(@ Rs V.T.M.B.P-48)					
@ Rs 614.31/m ² - Rs 58974 =					
(6) Maintenance of Work (H.P. culvert)					
2 H.P. (V.T.M.B.P-48)					
@ Rs 111700/H.P. - Rs 2234 =					
(7) Maintenance of Road sign - 0.31 KM.					
(V.T.M.B.P-49)					
@ Rs 1074.51/KM - Rs 333 =					
(8) Maintenance of 200m 2 KM Stone - 0.37 KM.					
(V.T.M.B.P-49)					
@ Rs 65145/KM - Rs 241 =					

Continuation

