

2863

प्राप्तकृत्य S.C.

प्राप्तकृत्य 3281

Schedule XIV Form No. 134.

DIVISION

SUB-DIVISION

Measurement Book

प्राप्तकृत्य 3281

4th year maintenance

54

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/w:- Hasulahi Bazar Pradhan					
mantri Sadak to Nahar					
Bandh Note Huga Dhupan					
Singh mukhiya ke Tola Tall.					
Agency:- Sri Narunjay Singh					
Agg:- 34 SBO/20-21					
D.O.C (Actual):- 10.00.2021					

① Restoration of rainCuts

12x 2.00m x 0.70m x 0.30m	= 5.04m ²
10x 2.50m x 0.70m x 0.30m	= 5.25m ²
8x 2.75m x 0.70m x 0.30m	= 0.58m ²
4x 2.00m x 0.70m x 0.30m	= 2.52m ²
6x 2.25m x 0.70m x 0.30m	= 4.10m ²
5x 3.50m x 0.70m x 0.30m	= 3.68m ²
2x 2.80m x 0.70m x 0.30m	= 1.18m ²
7x 4.10m x 0.70m x 0.30m	= 6.03m ²
4x 3.70m x 0.70m x 0.30m	= 10.88m ²

② Making up of berms

15x 2.00m x 0.80m	= 24.00m ²
10x 2.25m x 0.80m	= 18.00m ²
11x 2.50m x (0.80m + 0.70m)	= 20.63m ²
8x 3.00m x (0.80m + 0.70m)	= 18.00m ²
5x 3.25m x 0.70m	= 11.28m ²
4x 4.00m x 0.70m	= 11.20m ²
2x 3.10m x 0.70m	= 2.87m ²

Continuation

C/o 105.28m²

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
8x 4.50m x $\frac{(0.60+0.70)}{2}$ m					27.00m ²
3x 4.80m x 0.70m					10.08m ²
6x 5.00m x 0.70m					21.00m ²
7x 5.50m x 0.70m					26.95m ²
5x 6.00m x 0.70m					21.00m ²
4x 6.50m x 0.70m					18.20m ²
					229.61m ²
(3) Repair of pot holes					
with Bm					
6x 1.20m x 0.80m x 0.075m					0.43m ²
2x 0.80m x 0.80m x 0.075m					0.14m ²
4x 1.50m x 1.00m x 0.075m					0.45m ²
2x 1.70m x 1.25m x 0.075m					0.32m ²
1x 4.20m x 1.50m x 0.075m					0.47m ²
1x 3.60m x 1.75m x 0.075m					0.47m ²
1x 2.50m x 1.30m x 0.075m					0.24m ²
2x 2.80m x 1.25m x 0.075m					0.55m ²
1x 1.20m x 0.90m x 0.075m					0.09m ²
					3.14m ²
(4) Repair over pot holes —					
Area of Bm					
					3.14m ²
					0.075m
					41.87m ²
(5) Repair over bituminous surface —					
Qty. same as line 2-(4)					
					41.87m ²

Continuation

ABSTRACT OF COST

57

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of raincuts —					
Qty. vide TMBP (54)					
1. no :- ① = 44.48 m ²					
@ Rs 86 = 14/m ²					Rs 17176 = 00
② making up of berms —					
Qty. vide TMBP (55)					
1. no :- ② = 229.6 m ²					
@ Rs 57 = 26/m ²					Rs 13168 = 00
③ Repair of pot holes					
with Bm —					
Qty. vide TMBP (55)					
1. no :- ③ = 3.14 m ²					
@ Rs 12126 = 79/m ²					Rs 38078 = 00
④ Repair of pot holes					
Over —					
Qty. vide TMBP (55)					
1. no :- ④ = 41.87 m ²					
@ Rs 335 = 70/m ²					Rs 14026 = 00
⑤ Repair over bituminous					
Surface —					
Qty. vide TMBP (55)					
1. no :- ⑤ = 41.87 m ²					
@ Rs 349 = 01					Rs 14613 = 00
⑥ maintenance of C/P works —					
Qty. vide TMBP (56)					
1. no :- ⑥ = 1 no.					
@ Rs 2329 = 20/no.					Rs 2329 = 00

C/o Rs 99391 = 00
Continuation

B/F M 9939100

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
⑦ maint ⁿ of road sign					
Qty. vide TMBP (56)					
⑧ 1 st no :- ⑦ = 0.20 km					
@ M 1077 = 82/km					Rs 216 = 00
⑧ maint ⁿ of 200m and					
Km Stone					
Qty. vide TMBP (56)					
1 st no :- ⑧ = 0.24 km					
@ M 628 = 24/km					Rs 151 = 00
⑨ Cutting of branches					
of trees and shrubs					
Qty. vide TMBP (56)					
1 st no :- ⑨ = 2 nos.					
@ M 103 = 74/no.					Rs 219 = 00
⑩ Cutting of shrubs					
from roadway					
Qty. vide TMBP (56)					
1 st no :- ⑩ = 8 nos.					
@ M 6 = 73/no.					Rs 54 = 00
					Rs 100031 = 00
Less 12.01% below					Rs 13014 = 00
					Rs 87017 = 00
Add 12% GST					Rs 10442 = 00
Add 1% L.Cm					Rs 870 = 00
Add S. Fee					Rs 1500 = 00
					Rs 99829 = 00

Signed
11.09.25
J.E.

Continuation

Signed
11/09/25
A.E.