

ग्रामीण कार्य विभाग, कार्य प्रमंडल, बाढ़।

एम0आर0 (3054)

| क्र० सं० | पथ का नाम | प्रखण्ड | अभ्युक्ति। |
|----------|---|-------------|----------------------|
| 1 | 2 | 3 | 4 |
| 1 | Aunta Chowk to NH-31 Road Via Ram Balak Mahto House | Mokama | Out of Maintenance |
| 2 | Benuavasar to Ghataura Path | Pandarak | Transfer to RCD |
| 3 | Const. of RCC Culvert in Ghosbari Karra Path near vill Karra Under Ghosbari Block | Ghoswari | Out of Maintenance |
| 4 | Ghataura to Daulatpur Path | Pandarak | Out of Maintenance |
| 5 | Mokama Mekra Kanhaipur Village Road | Mokama | Out of Maintenance |
| 6 | Near the Hathidah water tank to Harijan tola via the MDR | Mokama | Out of Maintenance |
| 7 | NH-31 Ibrahimpur to Gosain Village | Ghoswari | Sanction in PMGSY-II |
| 8 | NH-31 Kalyanpur Dih to Jamalpur Bigha | Athamalgola | Out of Maintenance |
| 9 | NH-31 to Athmalgola Railway Station | Athamalgola | Out of Maintenance |
| 10 | NH-31 to Jai Prakash Mahuli Railway Halt | Athamalgola | Out of Maintenance |
| 11 | NH-30 A to Nadwa | Barh | Out of Maintenance |
| 12 | NH-31 To Towards Umanath Ghat Via Gas Godown | Barh | Transfer to RCD |
| 13 | PCC Work in the damaged part of RWD Road in Meura | Athamalgola | Out of Maintenance |
| 14 | PMGSY Path Bhaghatila to Korari Path | Belchhi | Out of Maintenance |
| 15 | REO Road to Shekhpura Dhanuk Tola (PMGSY Road Phase-II year 2011-13) under Pandarak | Pandarak | Out of Maintenance |
| 16 | Repair in road from NH-31 to Pipra ghat going via Karkoi Pahalwan in Shivnar Gram | Mokama | Out of Maintenance |
| 17 | Repair in road from NH-31 to Railway halt going road in Barahpur gram | Mokama | Out of Maintenance |

| क्र० सं० | पथ का नाम | प्रखण्ड | अभ्युक्ति । |
|----------|---|----------|---------------------------|
| 1 | 2 | 3 | 4 |
| 18 | Repair of Approach Road From Barh Shahri Sarmera Main Road to New Constructed milk Chilling Plant by confed | Barh | Out of Maintenance |
| 19 | Special repair in road from Bagi Tola to Railway Line going road in Sultanpur Gram | Mokama | Out of Maintenance |
| 20 | Specail repair in road from Chamar toli to Railway line going road in sultanpur gram | Mokama | Out of Maintenance |
| 21 | Special repair in road from NH-31 to Harijan toli going road in sultanpur gram | Mokama | Out of Maintenance |
| 22 | Specail repair of remaining part of Gwasashehpura rural road | Pandarak | Out of Maintenance |
| 23 | Specail repair of road from Nawada road to Chaknawada | Barh | Out of Maintenance |
| 24 | Specail repair of rural road from Gwasashehpura RWD Roat to the house of Bipin Singh via the house of sarpanch saab and towards the house of Ramanand Singh | Pandarak | Out of Maintenance |
| 25 | Specail repair of rural road from NH31 to village Dhibar | Pandarak | Out of Maintenance |

Executive Engineer,
RWD, Works Division, Barh