

कार्यपालक अभियंता, ग्रामीण कार्य विभाग कार्य प्रमंडल, दलसिंहसराय, समस्तीपुर

पत्रांक 2718अनु

दलसिंहसराय / दिनांक 22/12/2020

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, दलसिंहसराय

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी
सचिव-सह-प्राधिकृत पदाधिकारी
ग्रामीण पथ विकास एजेंसी पटना ।

विषय- **New Maintenance Policy 2018(MR New)** योजनान्तर्गत पथ में आवंटन
उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में सूचित करना है कि **New Maintenance Policy 2018(MR New)** योजनान्तर्गत चल रहे पथ के निर्माणधीन कार्य के विरुद्ध चल रहे योजनाओं का भुगतान **Rs.-45.67550 (Forty Five Lakh Sixty Seven Thousand Five Hundred Fifty Rupess)** कि आवश्यकता है। अधियाचना का निर्माण कार्य विशिष्टों के अनुरूप है तथा कार्य संतोषप्रद है।


अतः अनुरोध है कि अधियाचना पत्र के आधार पर आवंटन **Rs.-45.67550 (Forty Five Lakh Sixty Seven Thousand Five Hundred Fifty Rupess)** उपलब्ध कराने की कृपा की जाये।

अनु0- 1) अधियाचना प्रपत्र।

2) 19 ए फॉर्म।

3) IRI Report की छायाप्रति सलग्न।

विश्वासभाजन



कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, दलसिंहसराय

Romy Rat
22-12-2020

Rural Works Department, Works Division Dalsinghsarai
Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy 2018
(Initial Rectification and Surface Renewal)

Name of Division : PU(Dalsinghsarai)

Sl No	Package no.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA) Length (In Km)	Administrative Approval (AA) Amount (in Lac)	Agreement Amount (in Lac)	Initial Rectification with Surface Renewal (in Lac)	5 years Routine Maintenance (in Lac)	Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of RL (in mtr/km)	Thickness of Bitumen Layer (in mtr)	Value of Bitumen Content in percentage	Previous Total Allocated Amount (1 Lac)	up to date expenditure as per MIS (in Lac)	Requisition Against work done (in Lac)	Remarks
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	
RRM/SA/DAL/19/0017																			
1		Samastipur jila antargat morwa prkhand me kali ashan nandkishor mishr ke ghar hote hua shivchandar sah ke dukan PMGSY tak path nirman	32010403009		0.690	21.26390	9.39500	4.09392					3764	25mm	5.10%	8.45550	8.45550	0.93950	
2		Samastipur jila antargat morwa prkhand ke gram panchayat indrawara ke prdhamanti sadak madhy chok se vai shivji sabhi ke ghar hote hua nun nadi ghat ashal tak sadak nirman	32010403010		0.570	18.44820	8.29300	3.36880					3729	25mm	5.10%	0.00000	0.00000	8.29300	
3		Chandauli Hart Se Mirajpur Village me Reo Sadak Tak	10105100	2200 / 08.07.2019	1.800	57.50880	34.22700	13.79259		MBD 73/2019 20 27.02.2020	16.09.2020					0.00000	0.00000	0.00000	
4		Gumai Basai Ward-1 Se Ward No-2 Tak	10105101		1.250	42.07280	25.38200	9.50637								0.00000	0.00000	0.00000	
5		Nikaspur Mahadalit Basti Se Sharlesh Baba Shan se REO Path Tak	10105104		0.500	15.62720	9.90100	2.83012								0.00000	0.00000	0.00000	
6		SH Paton Path Se Pahadpur Hote Hue Bagipur Chowk Tak	10105106		1.850	61.09060	36.44300	14.43161					2744	25mm	5.10%	0.00000	0.00000	36.44300	
7		SUST Path se Rai Tola Tak	10105108		0.750	29.83630	18.86800	5.90173								0.00000	0.00000	0.00000	
8		PWD Sadak Se Chandauli APHC Mandir Tak	10105116		1.000	29.97940	19.20500	5.64539								0.00000	0.00000	0.00000	
					3.060	97.22090	51.915	21.255								8.45550	8.45550	45.67350	

1 Signed Hard Copy and Soft Copy (in Excel) of recorded RL is enclosed.
2 Up-to date Physical Progress has been uploaded in MIS.

Sr Divisional Account Officer
Rural Works Department,
Works Division Dalsinghsarai

Executive Engineer
Rural Works Department,
Works Division Dalsinghsarai

22-12-2020

New Maintenance Policy 2018(MR New)

RWD Works Division Dalsinghsarai

Sl No	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lakh)	Amount Received (in Lakh)	Particulars
1	2	3	4	5
1	New Maintenance Policy 2018 (MR New)	457.38141	457.38141	Certified that out of Rs-457.38141 Lakh received till date in favour of Executive Engineer, RWD Works Division Dalsinghsarai a Sum of Rs-457.38141 Lakh has been utilized for the New Maintenance Policy 2018(MR New) Scheme as given in the margine for which it was Sanctioned and that the Balance of Rs-0.00 Lakh remaining unutilized at the end of period under the time of completion
		457.38141	457.38141	


2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was

Kind of Checks Exercised:-


- (i) Workers have been supervised by Executive Engineer/ Superintending Engineer
- (ii) Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer
- (iii) Construction materials have been tested
- (iv) Measurements have been recorded in the MB's and test check conducted by the
- (v) All other codal formalities have observed

3. Physical Progress Achieved


- (i) Construction of Road Works
- (ii) Construction of CD Works


22/12/2020


Sr.DAO
Rural Works Department,
Works Division Dalsinghsarai


22/12/2020

Executive Engineer
Rural Works Department,
Works Division Dalsinghsarai


22-12-2020

File : D:\bump\Integrated\Division Dalsingaraj\samastipur jila antargat morma prakhand me kali sthan Nandkisor
Name of Customer : Ratnesh Construction Pvt.Ltd. Name of Work/ Road : Morva Prakhand me Kali Asithan



Signature
11.11.2011

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY ROAD	Latitude	Longitude	Event	Y = 0 * X ^ 2 + 1.136 * X + 132.5 X = 6900 Y = 7970		
9/11/20	16:6:34	78	0.1	290	0	2900	3426	G	25.6926	85.6551	Curve			
9/11/20	16:7:8	78	0.1	280	20.1	2800	3313	G	25.6926	85.65409	Curve			
9/11/20	16:7:44	78	0.1	460	20.1	3000	3658	G	25.69264	85.653182	Curve			
9/11/20	16:8:0	78	0.1	330	20.1	3300	3881	G	25.69237	85.652558	Curve			
9/11/20	16:8:19	78	0.1	360	20.1	3100	3722	G	25.69154	85.652322	Normal			
9/11/20	16:9:0	78	0.1	440	20.1	3500	4130	A	25.6906	85.65234	Speed Breaker			
9/11/20	16:10:0	78	0.1	360	20.1	3600	4222	A	25.68986	85.65202	Speed Breaker			
												(R) RURAL ROAD		
													Average	
													Poor	

Handwritten signature