

Record entry

Home of Urook - Restoration of
Solan chaidy house to
Katai chaidy in Aydar
Block in Urook - Alyzefom

~~Sub-entry~~ - 26/7 2019

Agency - Departmental

① Supply & laying of
brick bats by tractor
etc in cell
complete 25

Continuation

Scanned by CamScanner

ABSTRACT OF work

Named work Restorational tooth from
Dewan Chaudhary Keshav Katar
check in Area Block

ch- 3054 (M/R)

Agency- Departmental

entry - 416/20

① provide supply & laying & spreading
in form of in all work

wide THZ. P204 ch①

quantity: $120.0 \text{ M}^3 \times 1527 = 851 \text{ M}^3 - 183342 =$

② provide quarry material Ratio

fully in voids in brick wall

wide THZ. P204 ch②

quantity: $60.0 \text{ M}^3 \times 361.19 \text{ M}^3 - 26$

Continuation

216712

6 total 28501320

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				15.5	205013:-
Add	935-12%				246012:-
	Labours				2050:-
				total	231664:-
				Sum	
				41612	
				72.	