

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग कार्य प्रमंडल बेनीपट्टी।

दिनांक...12/9/2020

पत्रांक...1900/2020

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, बेनीपट्टी।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी -सह- सचिव,
बिहार ग्रामीण पथ विकास अभिकरण,
ग्रामीण कार्य विभाग,
बिहार, पटना।

विषय:-

शीर्ष NEW MAINTENANCE POLICY - 2018 (MR - 3054) में आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में कहना है शीर्ष NEW MAINTENANCE POLICY - 2018 (MR - 3054) अन्तर्गत पथ में संलग्न विवरणी के अनुसार आवंटन उपलब्ध कराने की कृपा की जाय ताक संवेदक का भुगतान किया जा सके।

अनु०:-

1. अध्याचना प्रमाण पत्र 1 पृष्ठ में।
2. उपयोगिता प्रमाण पत्र एक प्रति।

विश्वासभाजन

12/9/20
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, बेनीपट्टी।

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)

Form of Utilisation Certificate Upto the month of 31 August 2020

New Maintenance policy - 2018

PIU – Executive Engineer, R.W.D (W) Division, Benipatti

SL. No	Name of Gen.heme	Sanction No. & Date with Amount (In Rs. lacs)	Amount Received (In Rs. lacs)	Particulars
1	Construction of Rural roads under New maintenance policy - 2018	Authorisation letter No. 47 dt-24.06.2020 Rs.347.92960	347.92960	Certified that out of 347.92960 Lakh received during the years up to 2020-21 in favour of Ex. Engineer, RWD (W) Division Benipatti, Madhubani, Bihar, a sum of Rs. 347.71227 Lakh has been utilized for the purpose of New maintenance policy-2018 as given in the margin for which the balance of Rs 0.21733 Lakh remaining unutilized at the end of the period under.


2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-

- I. Works have been supervised by Executive Engineer/Superintending Engineer.
- II. Periodical inspection has been conducted by Executive Engineer/Superintending Engineer.
- III. Construction materials have been tested.
- IV. Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/Executive Engineer.
- V. All other codal formalities have been observed.

3. Physical Progress achieved :-

- I. Construction of Road Works.
- II. Construction of CD Works.


S.D.A.O 11/9/2020
R.W.D (W) Division
Benipatti

27/11/20
12-9-20
Executive Engineer
R.W.D (W) Division
Benipatti


Formate of Requisition under Head New Maintenance policy - 2018 (MR- 3054) for the month of September - 2020

Name of Division :- Benipatti

Sl No.	Package No.	Name of road	Project ID as per MIS	Administrative Approval (AA) Letter No & Date	Administrative Approval (AA)		Agreement Amount (in Lakh)		Agreement No & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of BDI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (in Lakh)	up-to-date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (In km)	Amount of (in lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance (in Lakh)										
1	MR-N/19-20 Benipatti/09	N.H.-52 Benipatti Ambedkar Chauk(Sona cinema) To Mukhayalay Tak	31910005001	2147 05.07.2019	2.000	71.32700	45.56834	19.25988	69MBD/19-20 31.12.2019	30.12.2020	—	2492	25	5	29.92930	29.92930	12.20064	Work Completed
Total					2.000	71.327	45.56834	19.25988	—	—	—	2492.00	25.000	5.000	29.929	29.929	12.2006	

[Signature]
St. D.A.O
R.W.D(W)Div. Benipatti
11/9/2020

27/11/20
12-9-20
Executive Engineer
R.W.D(W)Div. Benipatti
[Signature]

[illegible]

① P/A tack Coat with bit. emulsion - - all Comp job - SDE(I).

$$14 \times 3.75 = 52.50 \text{ m}^2$$

extra widening

$$3 \times 10 \times \left(\frac{5.00 + 4.50 + 3.75}{3} - 3.75 \right) = 19.99 \text{ m}^2$$

$$72.49 \text{ m}^2$$

② P/L SDBC 25mm thick SDBC - - all Comp job - SDE(I).

$$14 \times 3.75 \times 0.025 = 1.31 \text{ m}^2$$

extra widening

$$3 \times 10 \times \left(\frac{5.00 + 4.50 + 3.75}{3} - 3.75 \right) \times 0.025 = 0.49 \text{ m}^2$$

Continuation 1.80 m³

Date	Time	Section	Length	Bumps	Speed	OR	IRI CATEGORY	Latitude	longitude	Event
N.H.-52 Benipatti Ambedkar Chauk(Sona cinema) To Mukhayalay Tak										
		No.	in km	in mm	Rate	mm/km	mm/km			
16/6/20	9:28:4	25	0.1	130	0	1300	1439 G	26.45271	85.90675	Normal
16/6/20	9:29:0	25	0.1	160	20.2	1600	1724 G	26.45294	85.90581	Normal
16/6/20	9:29:11	25	0.1	250	20.2	2500	2576 G	26.45324	85.90485	Curve
16/6/20	9:29:11	25	0.1	210	20.2	2100	2197 G	26.45268	85.90411	Normal
16/6/20	9:29:11	25	0.1	170	30.3	1700	1818 G	26.45182	85.90374	Culvert
16/6/20	9:29:46	25	0.1	210	30.3	2100	2197 G	26.45096	85.90337	Normal
16/6/20	9:30:0	25	0.1	260	30.3	2600	2671 G	26.45012	85.90296	Normal
16/6/20	9:30:0	25	0.1	220	30.3	2200	2292 G	26.44961	85.90219	Normal
16/6/20	9:30:21	25	0.1	220	30.3	2200	2292 G	26.4491	85.90131	Culvert
16/6/20	9:30:21	25	0.1	240	30.3	2400	2481 G	26.44854	85.90056	Culvert
16/6/20	9:30:21	25	0.1	250	30.3	2500	2576 G	26.44793	85.8998	Normal
16/6/20	9:31:0	25	0.1	250	30.3	2500	2576 G	26.44743	85.89887	Culvert
16/6/20	9:31:0	25	0.1	310	20.2	3100	3144 G	26.44683	85.89825	Culvert
16/6/20	9:31:0	25	0.1	310	30.3	3100	3144 G	26.44601	85.89774	Normal
16/6/20	9:31:32	25	0.1	240	20.2	2400	2481 G	26.44508	85.89773	Normal
16/6/20	9:31:32	25	0.1	290	20.2	2900	2955 G	26.44479	85.89692	Normal
16/6/20	9:32:0	25	0.1	240	30.3	2400	2481 G	26.44388	85.89667	Normal
16/6/20	9:32:7	25	0.1	260	20.2	2600	2671 G	26.44317	85.89668	Speed Breaker
16/6/20	9:32:43	25	0.1	280	10.1	2800	2860 G	26.44284	85.89576	Normal
16/6/20	9:33:0	25	0.1	230	10.1	2300	2386 G	26.44197	85.89535	Normal
16/6/20	9:33:0	25	0.027	90	60.6	3333	3365 G	26.44169	85.8953	Normal

$$Y = 0 * X^2 + 0.947 * X + 208.9$$

$$X = 4400$$

$$Y = 4375$$

(R) RURAL ROAD
 Good <4000
 Average 4001-5000
 Poor >5001

9

File D:\Bump Integrator\Benipatti Ambedkar Chowk to Mukhyalay\16061020.Xls, Section No. 25, Eqn : $Y = 0 \cdot X^{\wedge}$
 Name of Customer : Sri Birchandra Mishra, Name of Work/ Road : Benipatti Ambedkar Chowk (Sona Cinema) to

