

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, मोतिहारी।

पत्रांक.....1889अनु. / दिनांक 26.7.2021.

प्रेषक

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल मोतिहारी।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी,
—सह—सचिव BRRDA,
बिहार, पटना।


विषय — MR-3054(New Maintenance Policy 2018) के अन्तर्गत पथ के
अनुरक्षण के लिए निधि उपलब्ध कराने के संबंध में।

महाशय,

उपर्युक्त विषय के संबंध में कहना है कि MR-3054(New Maintenance Policy 2018) के अन्तर्गत पथ के अनुरक्षण के निधि के लिए सूची बनाकर इस पत्र में संलग्न कर भवदीय के अवलोकनार्थ एवं आवश्यक कार्रवाई हेतु समर्पित की जा रही है।

अनु०:- यथोक्त।

विश्वासभाजन


कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, मोतिहारी।
26/7/21

Requestion formate for Scheme Head- MIR-3054 Under Bihar Kuran Road	Previous

Junior Engineer

Asst. Engineer

Sr. Divisional Accounts Officer
Rural Works Department,

Executive Engineer,
Rural Works Department,
26/7/72

R.W.D Work Division Motihari

FORM GFR 19A

(See Government of India's Decision (1) below Rule-150)
Form of Utilisation Certificate up to the month of 25.06.2021
MR HEAD-3054 (Initial Rectification with Surface Renewal)

Sl. No.	Name of Scheme	Selection No. of Date with Amount (in Rs. In Lacs)	Amount Received (in Rs. In Lacs)	Particulars
1	Construction of Rural Roads under MR HEAD-3054 (Initial Rectification with Surface Renewal)		4329.29827	Certified that out of Rs.4329.29827 Lacs received during the years 2020-21 in favour of Executive Engineer, R.W.D. Works Division, Motihari A sum of Rs.4154.54928 Lacs has been utilised for the purpose of MR HEAD-3054 (Initial Rectification with Surface Renewal) Scheme as given in the margin or whichever sanctioned and that the balance Rs.174.74899 Lacs remaining unutilised at the end of the period under.
			4329.29827	


- 2 Certified that I have satisfied myself that the conditions on which the grant-in-aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilised for the purpose for which it was sanctioned.


Kinds of exercised :-

- (i) Works have been supervised by Executive Engineer/ Superintending Engineer.
- (ii) Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- (iii) Construction Material have been testes.
- (iv) Measurement have been recorded in the MBs and test check conducted by the Assistant.
- (v) All other codal formalities have been observed.

- 3 Physical Progress achieved :-

- (i) Construction of Road Works.
- (ii) Construction of CD Works.


Sr. Divisional Accounts Officer
Rural Works Department;
Works Division, Motihari


Executive Engineer,
Rural Works Department,
Works Division, Motihari
26/7/21

Road Name-Motihari Ajarari REO Road - Siswa, Contractor-M/S SRI SAI CONSTRUCTION

Project ID-31708202034

Date	Time	Section	Length	Bumps	Speed	OR	IRI in	CATEGO	Latitude	Longitu	Event
		No.	in km	in mm	Rate	mm/km	UIV	ROAD		de	
1/7/21	13:14:0	59	0.1	210	0	2100	2205 G	26.6859	84.89503	Normal	
1/7/21	13:14:25	59	0.1	240	20.2	2400	2504 G	26.68661	84.89498	Normal	
1/7/21	13:14:25	59	0.1	220	30.3	2200	2305 G	26.6874	84.89542	Normal	
1/7/21	13:14:25	59	0.1	260	30.3	2600	2704 G	26.68806	84.89608	Normal	
1/7/21	13:15:0	59	0.1	220	30.3	2200	2305 G	26.68864	84.89684	Normal	
1/7/21	13:15:36	59	0.1	200	20.2	2000	2105 G	26.68921	84.89759	Normal	
1/7/21	13:16:0	59	0.1	210	20.2	2100	2205 G	26.68914	84.8985	Normal	
1/7/21	13:16:10	59	0.1	250	20.2	2500	2604 G	26.68948	84.89948	Normal	
1/7/21	13:16:10	59	0.1	230	20.2	2300	2404 G	26.68991	84.90027	Normal	
1/7/21	13:16:10	59	0.1	270	20.2	2700	2804 G	26.69027	84.9012	Normal	
1/7/21	13:16:45	59	0.1	250	20.2	2500	2604 G	26.69061	84.90205	Normal	
1/7/21	13:17:0	59	0.1	230	20.2	2300	2404 G	26.6909	84.90296	Normal	
1/7/21	13:17:20	59	0.1	290	20.2	2900	3003 G	26.69157	84.90362	Normal	
1/7/21	13:17:20	59	0.1	210	30.3	2100	2205 G	26.69211	84.90443	Normal	
1/7/21	13:18:31	59	0.1	240	30.3	2400	2504 G	26.69262	84.90527	Normal	
1/7/21	13:19:6	59	0.1	300	30.3	3000	3103 G	26.6933	84.90582	Normal	
1/7/21	13:19:42	59	0.1	270	30.3	2700	2804 G	26.6939	84.90667	Normal	
1/7/21	13:20:17	59	0.1	220	30.3	2200	2305 G	26.69428	84.90749	Normal	
1/7/21	13:20:17	59	0.1	310	30.3	3100	3203 G	26.69494	84.90818	Normal	
1/7/21	13:21:0	59	0.1	200	30.3	2000	2105 G	26.69569	84.9087	Normal	
1/7/21	13:21:27	59	0.057	180	20.2	3158	3261 G	26.69602	84.90919	Normal	

TOTAL IRI 53646
AVERAGE IRI 2554.571

$$Y = 0 * X^2 + 0.998 * X + 109.5$$

$$X = 3158$$

$$Y = 3261$$

(R) RURAL ROAD
Good Average Poor
<4000 4001-5000 >5001

JE

01/07/21

AE

01/07/21


Executive Engineer
Rural Works Department
Works Division, Motihari

01/07/21

Name of Customer : M/S SRI SAI CONSTRUCTION
 Name of Work/ Road : Mohan Ajagari REO Road - Siswa
 Lab Job number : 31708202034
 Date : 01-07-2021
 Section No. : 59

Test Date :	01-07-2021	Road Name :	Mohan Ajagari REO Road - Siswa
Machine No :	378	Road Type :	(R) RURAL ROAD
Start S No :	0 00 KM	Side :	
Start E No :	2 005 KM	Interval	
Weather :	Normal	U/V Range :	1105 To 4000 mm/km
Start Location :	26685902	Dist Range :	0 To 22 01 1000 m
End Location :	84909192	Equation :	$Y = 0 + X^2 + 0.998 * X + 109.5$

File D:\BuMP Indicator\Mothari\Sai Construction\28061324.Xls. Section No. : 59. Eqn : $Y = 0 + X^2 + 0.998 * X +$
 Name of Customer : M/S SRI SAI CONSTRUCTION. Name of Work/ Road : Mohan Ajagari REO Road - Siswa. Lab



R.N.D (N) DIVISION
 Executive Engineer
 Mothari