

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, टिकारी।

पत्रांक:- 1477 अनु०

/टिकारी ,

दिनांक:- 2.8.21

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, टिकारी।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण, पटना।

विषय-

3054/MR New Maintenance Policy-2018 अंतर्गत आवंटित राशि
का उपयोगिता प्रमाण पत्र तथा आवंटन अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषय के संबंध में कहना है कि इस प्रमण्डल अंतर्गत **3054/MR New Maintenance Policy-2018** अंतर्गत **Gendbigha to singhara** पथ में चल रहे कार्यों के भुगतान हेतु उपयोगिता प्रमाण पत्र विहित प्रपत्र में संलग्न करते हुए आग्रह है कि माँग पत्र के अनुसार योजना में रुपये **84,52,200.00** (चौरासी लाख बावन हजार दो सौ रुपये) मात्र का आवंटन उपलब्ध कराने की कृपा की जाय।

अनु०- यथोक्त।

विश्वासभाजन

(Handwritten signature)
8.8.21

कार्यपालक अभियंता
ग्रामीण कार्य विभाग, कार्य प्रमंडल, टिकारी।

(Handwritten signature)
3/8/21

**OFFICE OF THE EXECUTIVE ENGINEER,
RURAL WORKS DEPARTMENT, WORKS DIVISION TEKARI.**

Requisition Format for Scheme Head: - MR (3054) under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Works Division:- Tekari

Sl. No.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lakh)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Amount (in Lakh)	Up to date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (in Km)	Amount of (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance (in Lakh)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	MR-N/19-20 Tekari/- 10	Gendbigha to singhara	10502102083	Lt.5546 Dt. 23.10.19	4.600	137.90400	84.52200	44.87400	26/MBD/MR/2 020-21 & 14.07.2020	13.04.2021	-	3314	25 mm	5.04%	0	0	84.52200	Work Completed, RI का शुद्ध वर्तमान।
Total					1.400	37.01500	28.60200	13.02702									84.52200	

Amount in Word:- Eighty Four Lakh Fifty Two Thousand Two Hundred Only.

Sr. D.A.O.,
RWD, Works Division, Tekari

Executive Engineer
RWD, Works Division, Tekari

FORM GFR 19-A

(See Government of India's Decision (1) below Rule 150)
Form of Utilization Certificate up to the Month of **31-JULY-2021**

S. No	Name of Scheme	Sanction No. & Date with Amount (In Rs.lacs)	Amount Received (in Rs.Lacs)	Particulars
1	Bihar Rural Roads New Maint. Policy 2018	Lt. No. 47/Encl. Dated 24.06.2020	98.21031	Certified that out of Rs. 1493.52758 Lakh received during the Financial Year 2021-22 (31-JULY-21) in favour of Executive Engineer, RWD (W) Division, Tekari, Gaya, Bihar out of which a sum of Rs. 1207.56098 Lacs has been utilized for the purpose of New Maintenance Policy 2018 Under MR3054 Scheme as given in the margin for which it was sanctioned and that the balance of Rs. 285.96660 Lacs remaining unutilized at the end of the said period.
2		Lt. No. 82/Encl. Dated 13.11.2020	148.49067	
3		Lt. No. 84/Encl. Dated 26.11.2020	199.17599	
4		Lt. No. 05/Encl. Dated 12.01.2021	65.81907	
5		Lt. No. 17/Encl. Dated 26.02.2021	10.83516	
6		Lt. No. 22/Encl. Dated 24.03.2021	95.70700	
7		Lt. No. 26/Encl. Dated 15.04.2021	78.50000	
8		Lt. No. 27/Encl. Dated 15.04.2021	334.32100	
9		Lt. No. 30/Encl. Dated 21.05.2021	462.46838	
			1493.52758	

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.



Kind of Checks exercised :-

- Works have been supervised by Executive Engineers/Superintending Engineer.
- Periodic inspection has been conducted by Executive Engineer/Superintending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant.
- All other codal formalities have been observed.

Physical Progress achieved :-

- Construction of Road Works
- Construction of CD Works


Sr. Divisional Accounts Officer,
Rural Works Department,
Works Division, Tekari.


Executive Engineer,
Rural Works Department,
Works Division, Tekari.



सहायक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य अवर प्रमंडल, कोंच।

पत्रांक:- २१२५


दिनांक:- 31/04/2021

जाँच प्रतिवेदन

प्रखण्ड का नाम	योजना का नाम	पथ की लम्बाई	S.D.B.C परत की मोटाई	विटुमिन Content की मात्र	BUMP INTEGRATOR का Reading	अभियुक्ति
Konch	Gendbigha to singhara	4.60	25MM	5.04	Reading Attached	Satisfactory


सहायक अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रमंडल, कोंच।

File :C:\Users\DELL\Desktop\Bump\19.07.21\31071618.dxc Section No. 54. Egn Test
 Name of Customer :SANJAY KUMAR. Name of Work Road : Gendbielha to singhara lab



[Signature]
 05/11/21
 JE

[Signature]
 05/11/21
 AE

[Signature]
 05/11/21
 Executive Engineer
 RWD, Works Division
 Tekari, Gaya

CONT. NAME:-SANJAY KUMAR
ROAD NAME:- GEND BIGHA TO SINGHARA

Date	Time	Section No.	Length in km	Bumps in mm	Speed	OR	IRI	CATEGORY	Latitude	Longitude	Event
31/7/21	13:3:3	64	0.1	250	20.2	2500	2970	G	25.012877	84.717025	Normal
31/7/21	13:3:3	64	0.1	320	20.2	3200	3659	G	25.029322	84.740763	Normal
31/7/21	13:3:38	64	0.1	210	30.3	2100	2577	G	25.029078	84.741742	Normal
31/7/21	13:3:38	64	0.1	240	20.2	2400	2872	G	25.028917	84.742707	Normal
31/7/21	13:4:0	64	0.1	240	30.3	2400	2872	G	25.029987	84.735869	Normal
31/7/21	13:4:0	64	0.1	240	30.3	2400	2872	G	25.029844	84.736805	Normal
31/7/21	13:4:14	64	0.1	320	20.2	3200	3659	G	25.029768	84.737843	Normal
31/7/21	13:4:14	64	0.1	230	20.2	2300	2773	G	25.029768	84.737843	Normal
31/7/21	13:4:49	64	0.1	340	20.2	3400	3856	G	25.029643	84.738897	Curve
31/7/21	13:5:0	64	0.1	290	20.2	2900	3364	G	25.030542	84.731943	Normal
31/7/21	13:5:0	64	0.1	230	20.2	2300	2773	G	25.0304	84.732929	Normal
31/7/21	13:5:10	64	0.1	230	20.2	2300	2773	G	25.032513	84.718332	Normal
31/7/21	13:5:24	64	0.1	270	20.2	2700	3167	G	25.030124	84.734826	Normal
31/7/21	13:5:24	64	0.1	250	20.2	2500	2970	G	25.031148	84.728047	Normal
31/7/21	13:6:0	64	0.1	270	20.2	2700	3167	G	25.030941	84.729006	Normal
31/7/21	13:6:35	64	0.1	320	20.2	3200	3659	G	25.030697	84.730919	Normal
31/7/21	13:6:35	64	0.1	350	20.2	3500	3954	G	25.030819	84.729981	Normal
31/7/21	13:7:10	64	0.1	290	20.2	2900	3364	G	25.031908	84.724173	Normal
31/7/21	13:7:10	64	0.1	320	20.2	3200	3659	G	25.031696	84.725066	Normal
31/7/21	13:7:10	64	0.1	330	20.2	3300	3757	G	25.031424	84.726054	Normal
31/7/21	13:7:45	64	0.1	280	20.2	2800	3265	G	25.031295	84.727043	Normal
31/7/21	13:7:55	64	0.1	280	20.2	2800	3265	G	25.032513	84.718332	Normal
31/7/21	13:8:0	64	0.1	290	20.2	2900	3364	G	25.032215	84.722186	Normal
31/7/21	13:8:21	64	0.1	280	20.2	2800	3265	G	25.032358	84.721204	Normal
31/7/21	13:9:0	64	0.1	230	20.2	2300	2773	G	25.033121	84.716311	Normal
31/7/21	13:9:0	64	0.1	260	20.2	2600	3069	G	25.032946	84.717275	Normal
31/7/21	13:9:31	64	0.1	240	20.2	2400	2872	G	25.032677	84.719246	Normal
31/7/21	13:9:31	64	0.1	240	20.2	2400	2872	G	25.032776	84.71826	Normal

Sanjay Kumar
31/7/21
JE

31/7/21
HE

31/7/21
Executive Engineer
Road Works Division

Dat	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGORY	Latitude	Longitude	Event
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD			
31/7/21	13: 9: 31	64	0.1	280	20.2	2800	3265	G	25.033585	84.713351	Normal
31/7/21	13: 10: 6	64	0.1	280	10.1	2800	3265	G	25.033652	84.712403	Normal
31/7/21	13: 10: 6	64	0.1	300	20.2	3000	3462	G	25.03356	84.714367	Normal
31/7/21	13: 10: 42	64	0.1	290	20.2	2900	3364	G	25.033321	84.715296	Normal
31/7/21	13: 11: 0	64	0.1	320	10.1	3200	3659	G	25.034561	84.708808	Normal
31/7/21	13: 11: 17	64	0.1	300	20.2	3000	3462	G	25.034492	84.709687	Normal
31/7/21	13: 11: 17	64	0.1	290	20.2	2900	3364	G	25.034055	84.711411	Normal
31/7/21	13: 12: 0	64	0.1	290	10.1	2900	3364	G	25.034239	84.711411	Normal
31/7/21	13: 12: 0	64	0.1	300	20.2	3000	3462	G	25.034239	84.71065	Normal
31/7/21	13: 12: 28	64	0.1	290	20.2	2900	3364	G	25.030297	84.714972	Normal
31/7/21	13: 12: 28	64	0.1	320	10.1	3200	3659	G	25.032513	84.718332	Normal
31/7/21	13: 13: 3	64	0.1	300	10.1	3000	3462	G	25.032073	84.715351	Normal
31/7/21	13: 13: 3	64	0.1	310	10.1	3100	3561	G	25.03291	84.71562	Normal
31/7/21	13: 13: 38	64	0.1	320	10.1	3200	3659	G	25.028596	84.71437	Normal
31/7/21	13: 14: 13	64	0.1	300	20.2	3000	3462	G	25.027855	84.714188	Normal
31/7/21	13: 14: 13	64	0.1	290	20.2	2900	3364	G	25.027614	84.713280	Normal
31/7/21	13: 14: 49	64	0.1	330	20.2	3300	3757	G	25.029441	84.71463	Normal
AVERAGE							3314				

Handwritten signature
31/7/21
J.E

Handwritten signature
31/7/21
A.E

Executive Engineer
RWD, Works Division
Tekari, Gaya

Handwritten signature
31/7/21