

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग कार्य प्रमण्डल, बाँका-2

पत्रांक 1333 (अइ)/बाँका

दिनांक 01/08/2021

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, बाँका-2

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण, पटना।

विषय :- शीर्ष "3054 एम0आर0" योजना अन्तर्गत आवंटन के संबंध में।

महोदय,

उपपुर्वत विषयक से संबंधित एम0आर03054 योजना अन्तर्गत संवेदक द्वारा कराए
गये कार्यों के भुगतान हेतु विहित प्रपत्र में अधिघातित राशि रूपया 1,40,40,000/-लाख का
आवंटन उपलब्ध कराने की कृपा की जाय। ताकि संवेदक को भुगतान किया जा सके।

अनु0-1: अधियाचना प्रपत्र
2।RI। Report

विश्वसमान

02.08.21

कार्यपालक अभियंता
ग्रामोपवि0 कार्य प्रमण्डल,
बाँका-2

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग कार्य प्रमण्डल, बाँका-2

पत्रांक...../बाँका

दिनांक

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, बाँका-2

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण, पटना।

विषय :- शीर्ष "3054 एम0आर0" योजना अन्तर्गत आवंटन के संबंध में।

महाशय,

उपर्युक्त विषयक से संबंधित एम0आर03054 योजना अन्तर्गत संवेदक द्वारा कराए गये कार्यों के भुगतान हेतु विहित प्रपत्र में अधियाचित राशि रूपया 1,40,40,000/-लाख का आवंटन उपलब्ध कराने की कृपा की जाय। ताकि संवेदक को भुगतान किया जा सके।

अनु0:-1. अधियाचना प्रपत्र

2. IRI Report


विश्वासभाजन

ह0/-

कार्यपालक अभियंता
ग्रा0का0वि0, कार्य प्रमण्डल,
बाँका-2

झापांक-1333/बाँका दिनांक 04/08/2021 .

प्रतिलिपि :- मुख्य अभियंता-4, ग्रामीण कार्य विभाग, बिहार, पटना को सूचनार्थ एवं आवश्यक कार्रवाई हेतु समर्पित।


कार्यपालक अभियंता
ग्रा0का0वि0, कार्य प्रमण्डल,
बाँका-2

Form GFR 19-A

(See Government of India's Decision (1) below rule-15)
Form of utilization Certificate up to the Month June' 2021
MR/3054(NEW MAINTENANCE POLICY)

PIU-RWD(W), BANKA-2

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lacs)	Amount Received (in Rs. Lacs)	Particulars
1	Construction of Rural roads under MR/3054(NEW MAINTENANCE POLICY)	विभागीय पत्रांक 37 दिनांक 27.05.2020 45(Encl)/18.06.2020 56(Encl)/12.08.2020 59(Encl)/18.08.2020 61(Encl)/26.08.2020 82(Encl)/13.11.2020 84(Encl)/26.11.2020 86(Encl)/11.12.2020 05(Encl) /12.01.2021 17 (Encl) / 26.02.2021 20 (Encl) /19.03.2021 22(Encl) /24.03.2021 27(Encl) /04.05.2021 30 (Encl) /21.05.2021 32 (Encl) / 28.05.2021	217.86340 30.12339 525.63100 320.50000 6.57325 88.44000 395.49360 368.11196 570.35090 604.70836 361.33115 82.05330 88.60000 58.28940 440.19502	Certified that out of Rs. 4158.26473 Lacs received during the years 2020-21 in favour of Ex. Engineer. RWD Bihar, RWD-2 Banka a sum of Rs. 4137.93652 Lacs has been utilized for the purpose of MR/3054(New Maintenance Policy) schemes as given in the margin for which it was sanctioned and that the balance of Rs 20.32821 remaining unutilized at the end of the period under.
	Total		4158.26473	

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-

- (i) Works have been supervised by Executive Engineer/ Superintending Engineer .
- (ii) Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- (iii) Measurement have been recorded in the MBs.
- (iv) All other code formalities have been observed.

3. Physical progress achieved :

- (i) Construction of Road Works.
- (ii) Construction of CD Works.

Sr. D.A.O.

Works Division Banka-II
Rural Works Department

Executive Engineer

Works Division Banka-II
Rural Works Department

Requisition Format for Scheme Head-MR (3054) Under Bihar Rural Road Maintenance Policy 2018 (Initial Rectification and Surface Renewal)
 Name of Division :- Banka-2


Sl No.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lac)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion (Expected)	Value of IRI (in mm/km)	Thickness of Bitumen layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Alloted Amount (In Lac)	Up to date expenditure as per MIS (in Lac)	Requisition Against work done (in lac)	Remarks
					Length (In Km)	Amount (in Lac)	Initial rectification on with Surface renewal (in lac)	5 Years Routine Maintenance (In lac)										
1	MR-N/19-20 Banka-2/26 under 3054/MR	Katoriya Baliyama Road To Sathiyari	20703602048	6276 02.12.2019	1.500	58.637	38.07673	14.85633	44/MBD/20-21 24.09.20	23.09.21	31.07.2021	2916.400	25mm	5%	0.00000	0.00000	38.00000	Completed
2	MR-N/19-20 Banka-2/24	Repair of Road from Sanhaula-Panjwara To Chormara under MR/3054	20703502117	6276 02.12.2019	4.137	153.633	102.45565	41.44152	11/MBD/20-21 15.07.2020	14.07.21	31.07.2021	2703.267	25mm	5%	0.00000	0.00000	102.40000	Completed
		Total															140.40000	

02.08.21
 Executive Engineer
 R.W.D.(W) Division
 Banka-2


Lab Job number :39

Date :31.07.2021

Name of Customer :		Mister Azad ,Majlishpur ,Banka	
Name of Work/ Road :		Katoriya Baliyamara to Sadiyari under MR 3054 New Maint. Policy 2018	
Sr.no	Location of test(in km)	Corrected I.I value(mm/km)	Road catagory
1	0.1	3562	G
2	0.2	3078	G
3	0.3	2400	G
4	0.4	3175	G
5	0.5	2884	G
6	0.6	2497	G
7	0.7	3175	G
8	0.8	2787	G
9	0.9	3078	G
10	1.0	3562	G
11	1.1	2690	G
12	1.2	2787	G
13	1.3	2593	G
14	1.4	2400	G
15	1.5	3078	G
Avg IRI Value per Km		2916.40	G


Junior Engineer

Assistant Engineer
R.W.D Works Division
Banka-2



Executive Engineer
R.W.D Works Division
Banka-2

Name of Customer : Mister Azad, Majlishpur, Banka


Name of Work/Road : Katoriya Baliyamara to Sadiyari under MR 3054 New Maint. Policy 2018

Lab Job No:39

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	UIV	CATEGORY ROAD	IRI	Latitude	Longitude	Event
31/ 7/ 21	10: 16: 0	39	0.1	360	20.2	3600	3562	G	4.69	24.787105	86.738873	Normal
31/ 7/ 21	10: 16: 0	39	0.1	310	20.2	3100	3078	G	4.12	24.786188	86.738569	Normal
31/ 7/ 21	10: 16: 0	39	0.1	240	20.2	2400	2400	G	3.3	24.785786	86.739054	Normal
31/ 7/ 21	10: 19: 0	39	0.1	320	20.2	3200	3175	G	4.23	24.785632	86.739612	Normal
31/ 7/ 21	10: 19: 0	39	0.1	290	20.2	2900	2884	G	3.88	24.785455	86.740315	Normal
31/ 7/ 21	10: 19: 12	39	0.1	250	20.2	2500	2497	G	3.42	24.784718	86.740026	Normal
31/ 7/ 21	10: 19: 47	39	0.1	320	20.2	3200	3175	G	4.23	24.783213	86.739938	Normal
31/ 7/ 21	10: 20: 0	39	0.1	280	10.1	2800	2787	G	3.77	24.782909	86.73935	Speed Breaker
31/ 7/ 21	10: 20: 23	39	0.1	310	10.1	3100	3078	G	4.12	24.782049	86.738931	Normal
31/ 7/ 21	10: 20: 23	39	0.1	360	10.1	3600	3562	G	4.69	24.781403	86.73865	Normal
31/ 7/ 21	10: 21: 0	39	0.1	270	20.2	2700	2690	G	3.65	24.780047	86.738716	Normal
31/ 7/ 21	10: 21: 33	39	0.1	280	20.2	2800	2787	G	3.77	24.778702	86.739112	Normal
31/ 7/ 21	10: 22: 9	39	0.1	260	20.2	2600	2593	G	3.53	24.779125	86.738903	Normal
31/ 7/ 21	10: 22: 44	39	0.1	240	20.2	2400	2400	G	3.3	24.777219	86.739584	Normal
31/ 7/ 21	10: 23: 19	39	0.1	310	20.2	3100	3078	G	4.12	24.778074	86.739468	Normal


Junior Engineer

Assistant Engineer
Rural Works Department
Works Division ,Banka-2


Executive Engineer
Rural Works Department
Works Division ,Banka-2

Name of Customer :

Name of Work/Road :

Lab Job number :

Date :

Section No. :

Test Date :

Road Name :

Machine No :

Road Type :

Start S No :

Side :

Start E No :

Interval :

Weather :

U/V Range :

mm/km

Start Location :

Dist Range :

0.1

End Location :

Equation :


* 1000 m

Print

Generate Report and Graph

Redraw Graph


Map View



for 27/8/21
JW

EXECUTIVE ENGINEER
R.W.D. (R) Division
Bardhaman

02.08.21



for 2/8/21

02-08-21
EXECUTIVE ENGINEER
R.W.D. (C) T...
Bar...