

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- *Cyan bibhakar*

2 Name of Block/Road :- *Aurai / Tarajiwar Binda Jag shop to Sahni tola Tarajiwar*

(A) For Road:

1. Damage Location/Chainage :- *0+300m , 0+400m*
2. Damage Length :- *0.11893 Km*
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- *Brick bats*
 - (ii) Equipment's/Tools being used in Restoration works:- *Tractor*
 - (iii) Procedure taken up in Restoration works:
 - (iv) Restored Length :- *0.11893 Km*

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE

[Signature]
Signature

(Name of Inspection)

कार्यपालक अभियंता

ग्रामीण कार्य विभाग

कार्य प्रमंडल, मुजफ्फरपुर पूर्वी-1

GENERAL ABSTRACT

Name of Road Tarajiwar Binda Das Shop to Sahni Tola Tarajiwar

District Muzaffarpur

Block Aurai

Division Muzaffarpur East-2

Length of Road (in Km) 1.780 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Earthwork	0.000
2	Jhama metal	2.878
3	Sand Filling	0.000
4	Sand bag	0.000
5	H.P.	0.000
	GRAND SUB TOTAL	2.878
TOTAL COST OF PROJECT IN LACS =		2.878

Secy
11/1/21
JE
RWD

AE
RWD

EE
RWD

Technically approved for Rs 2.878 lac
(Rupees Two lac Eighty seven thousand Eight hundred only)

अधीक्षण अभियंता
ग्रामीण कार्य विभाग
कार्य अंचल, मुजफ्फरपुर