

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, सासाराम-1

Email ID:-ee.rwd.sasaram1@gmail.com

Mob:- 8986915310

पत्रांक... 205 830 सासाराम/दिनांक... 02-02-2021

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सासाराम-1

सेवामें,

नोडल पदाधिकारी (MR 3054)
ग्रामीण कार्य विभाग
पटना, बिहार

विषय :- नई अनुरक्षण नीति-2018MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के विरुद्ध आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में सूचित करना है कि नई अनुरक्षण नीति-2018 MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के लिए संवेदक को भुगतान करने हेतु अध्याचना विहित प्रपत्र में भरकर आवश्यक कार्यवाही हेतु समर्पित की जाती है।

अनु० :- यथोक्त।

विष्वासभाजन

21/2/21
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सासाराम-1

02/02/21

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)

Form of Utilization Certificate up to Feb 2021

Sl.No	Name of Scheme	Sanction No.&Date With Amount (In lace Rs.)	Amount Received (In lace Rs.)	Particulars
1	Construction of Rural roads Under MR	New Maintenance Policy-2018 MR (3054) BRRDA PATNA Letter No.82, dt. 13.11.2020 Letter No.84, dt. 26.11.2020 Letter No.86, dt. 11.12.2020 Letter No.05, dt. 12.01.2021	24012800.00 19457900.00 65864300.00 142175100.00	Certified that out of Rs. 25,15,10,100.00 lakh of grants-in-aid sanctioned during the years 2020-21 Infavor of EE,RWD works division Sasaram-1 a sum of Rs 162385738.00 lakh has been utilized for the purpose of MR (3054) Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 87103358.00 lakh remaining unutilized at the end of the period under report.
	Total:		25,15,10,100.00	


2. Certified that I have satisfied my self that the conditions on which the grant-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was utilized for the purpose for which it was sanctioned.

Kind of Checks exercised:-


- Works have been supervised by Executive Engineer/ Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- All other caudal formalities have been observed.


3. Physical Progress achieved:-

- Construction of Road Works.
- Construction of CD works.


Divisional Accounts Officer
R.W.D, works Division
Sasaram-1

Sr. Divnl. Accounts Officer
R.W.D, Division, Sasaram-1


Executive Engineer
R.W.D, works Division
Sasaram-1


02/02/21
Executive Engineer

OFFICE OF EXECUTIVE ENGINEER, RURAL WORKS DEPARTMENT, WORKS DIVISION, SASARAM-1

Requisition Format for Scheme Head - MR(3054) under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Works Division:- Sasaram-1

Sl no.	Package No MR-N/ 2019-20	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No & Date	Administrative Approval (AA)		Agreement Amount (In Lakh)		Agreement No& Date	Date of Completion as per Agreement	Actual Date of Completion	Value of RRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Amount Allotted (in Lakh)	up-to-date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (in km)	Amount of (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance (in Lakh)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	9	Dumara Agarar Road - Bhavni	10301002162	3021 16.07.2019	3.910	103.13180	64.784	20.48966	42/MBD/ 2020-21 22.02.20	21.11.2020	-	1415	25.00	5.01	0.00000	0.00000	64.78400	
Total					3.910	103.13180	64.784	20.48966							0.00000	0.00000	64.78400	

[Signature]
Sr. Divl. Accounts Officer
Divisional Accounts Office
Rural Works Department,
Works Division, Sasaram-1

[Signature]
Executive Engineer
Rural Works Department
Works Division, Sasaram-1
02/02/21
R.V.D.(V) Dtr. Sasaram-1


Name of Customer : Lalan Sukla
 Name of Work/Road : Dumara Agar Road - Bhavni
 Lab Job number : 20
 Date : 1/15/2021
 Section No. : 20

Test Date : 1/15/2021
 Machine No : 391
 Start S No : 7362
 Start E No : 7401
 Weather : Normal
 Start Location : 25.58647, 84.21
 End Location : 25.38095, 84.31
 Road Name : Dumara Agar Road - Bhavni
 Road Type : (R) RURAL ROAD
 Side : Kargher
 U/V Range : 415 To 4000
 Dist Range : 0 To 1.148
 Equation : $Y = 0 * X^2 + 1.000 * X + 415.2$

Print Generate Report and Graph

Redraw Graph

Map View



24/24
 24/24
 EXECUTIVE ENGINEER
 A.W.D.(V) Dh. Bhavni

Name of Road : Dumara Agrer Road - Bhavni

Date	Time	Section	Length	Bumps	Speed	OR	IRI	EGORY	Latitude	Longitude	Event
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD			
15/1/21	14:36:10	20	0.1	130	22.6	1300	1715	G	25.58647	84.20707	Normal
15/1/21	14:37:0	20	0.1	220	10.1	2200	2615	G	25.57802	84.20453	Normal
15/1/21	14:38:0	20	0.1	150	23.6	1500	1915	G	25.5692	84.20302	Normal
15/1/21	14:38:0	20	0.1	290	10.1	2900	3315	G	25.56003	84.2003	Normal
15/1/21	14:38:30	20	0.1	210	20.2	2100	2515	G	25.55173	84.1968	Normal
15/1/21	14:38:30	20	0.1	270	10.1	2700	3115	G	25.5432	84.1946	Normal
15/1/21	14:39:5	20	0.1	230	20.2	2300	2715	G	25.5381	84.18905	Normal
15/1/21	14:39:5	20	0.1	220	20.2	2200	2615	G	25.5397	84.17962	Normal
15/1/21	14:39:41	20	0.1	120	20.2	1200	1615	G	25.5416	84.16968	Normal
15/1/21	14:40:0	20	0.1	240	20.2	2400	2815	G	25.54277	84.16027	Normal
15/1/21	14:40:16	20	0.1	120	20.2	1200	1615	G	25.53413	84.15842	Normal
15/1/21	14:40:16	20	0.1	250	20.2	2500	2915	G	25.52507	84.15638	Normal
15/1/21	14:40:16	20	0.1	120	20.2	1200	1615	G	25.51682	84.15622	Normal
15/1/21	14:41:0	20	0.1	180	10.1	1800	2215	G	25.51368	84.16665	Normal
15/1/21	14:41:26	20	0.1	230	10.1	2300	2715	G	25.51212	84.17592	Normal
15/1/21	14:42:2	20	0.1	130	10.1	1300	1715	G	25.51098	84.18568	Normal
15/1/21	14:42:2	20	0.1	160	10.1	1600	2015	G	25.51292	84.19427	Normal
15/1/21	14:43:0	20	0.1	130	10.1	1300	1715	G	25.5093	84.20387	Normal
15/1/21	14:43:12	20	0.1	270	10.1	2700	3115	G	25.5066	84.21278	Normal
15/1/21	14:43:12	20	0.1	230	20.2	2300	2715	G	25.49988	84.21918	Normal
15/1/21	14:43:12	20	0.1	220	20.2	2200	2615	G	25.49512	84.22743	Normal
15/1/21	14:43:48	20	0.1	250	30.3	2500	2915	G	25.49282	84.23787	Normal
15/1/21	14:44:0	20	0.1	240	20.2	2400	2815	G	25.49018	84.24697	Normal
15/1/21	14:44:23	20	0.1	270	30.3	2700	3115	G	25.48803	84.25572	Normal
15/1/21	14:44:23	20	0.1	280	30.3	2800	3215	G	25.4865	84.26648	Normal
15/1/21	14:44:23	20	0.1	150	10.1	1500	1915	G	25.48602	84.27642	Normal
15/1/21	14:45:0	20	0.1	130	20.2	1300	1715	G	25.4787	84.27895	Normal
15/1/21	14:45:0	20	0.1	150	20.2	1500	1915	G	25.46982	84.28147	Normal
15/1/21	14:45:0	20	0.1	290	30.3	2900	3315	G	25.46143	84.2847	Normal
15/1/21	14:45:33	20	0.1	220	20.2	2200	2615	G	25.45328	84.29007	Normal
15/1/21	14:46:0	20	0.1	240	20.2	2400	2815	G	25.44428	84.29192	Normal
15/1/21	14:46:9	20	0.1	260	20.2	2600	3015	G	25.4356	84.29275	Normal
15/1/21	14:46:9	20	0.1	180	20.2	1800	2215	G	25.42707	84.29747	Normal
15/1/21	14:46:9	20	0.1	170	30.3	1700	2115	G	25.41823	84.29898	Normal
15/1/21	14:46:44	20	0.1	280	30.3	2800	3215	G	25.40947	84.3015	Normal
15/1/21	14:47:0	20	0.1	150	20.2	1500	1915	G	25.40102	84.30505	Normal

$$Y = 0 * X^2 + 1.000 * X + 415.2$$

$$X = 1000$$

$$Y = 1415$$

(R) RURAL ROAD

Good Average Poor

<4000 4001-5000 >5001

W
22/21
Executive Engineer
A.V.D.(V)/Dy. Engineer

15/1/21	14:47:19	20	0.1	140	20.2	1400	1815	G	25.39208	84.30773	Normal
15/1/21	14:47:19	20	0.1	200	10.1	2000	2415	G	25.38618	84.31397	Normal
15/1/21	14:48:0	20	0.1	180	20.2	1800	2215	G	25.3811	84.31347	Normal
15/1/21	14:48:0	20	0.1	100	23.6	1000	1415	G	25.38095	84.31347	Normal
Total			4								

M
2/2/21

Executive Engineer
A.V.D.(V)/Dr. Kaveri