Inspection Report for Flood Damage Work

	Date:-
	1 Name of PIUs:- Cityan Vibhakard
	2 Name of Block/Road: Auxai/ Construction of 2×17·11 mt Rcc Brilge at Loss (A) For Road: To3 to Retwork roal.
X	(A) For Road: To3 to Retwork roal.
V	1. Damage Location/Chainage :-
	2. Damage Length :- 0.093 Kon
	3. Nature of Damage :-
	4. Details of Restoration Works:
	(i) Material being used in Restoration works:- Bride bould
	(ii) Equipment's/Tools being used in Restoration works:-
	(iii) Procedure taken up in Restoration works:
	(iv) Restored Length :- 0-093 Km
	(B) For Bridge:
1	1. Damage Location/Chainage :-
	2. Damage Length :-
	3. Nature of Damage :-
	4. Details of Restoration Works:
	(i) Material being used in Restoration works:- (ii) Equipment's/Tools being used in Restoration works:- Transfer
	(ii) Equipment's/Tools being used in Restoration works:-
	(iii) Procedure taken up in Restoration works:-
	(iv) Restored Length :

Signature of JE/AE/EE

Signature

(Name of Inspection) कार्यपालक अभियंता ग्रामीण कार्य विभाग कार्य प्रमंडल,मुजफ्फरपुर पूर्वी-1

GENERAL ABSTRACT

Name of Road

Construction of 2x17.11 mt RCC Bridge at L025 T03 to Ratwara Road

District

Muzaffarpur

Block

Aurai

Division

Muzaffarpur East-2

Length of Road (in Km)

0.000 Km

engui oi	AMOUNT (LAKES)	
SI. No.	DESCRIPTION	3.788
1	Jhama metal	7.870
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	11.658
	GRAND SUB TOTAL	11.658
TOTAL C	COST OF PROJECT IN LACS =	

SE4 1111121

48/11/01/2

JE RWD

RWD

RWD II)

Technically approved for 11.658 lac (Rupees Eleven lac sixty five thousand Eight hundred only)

> अधीक्षण अभियंता ग्रामीण कार्य विभाग कार्य अंचल,मुजफ्फरपुर