कार्यपालक अभियंता का कार्यालय ग्रामीण कार्य विभाग, कार्य प्रमंडल, सासाराम–1

Email ID:-ee.rwd.sasaram1@gmail.com

Mob:- 8986915310

ч**я**іक.....26 о 3150

सासाराम/दिनांक 11 - 02 - 2021

प्रेषक,

कार्यपालक अभियंता, ग्रामीण कार्य विभाग, कार्य प्रमंडल, सासाराम–1

सेवामें,

नोडल पदाधिकारी (MR 3054) ग्रामीणकार्यविभाग पटना, बिहार

विषय :- नई अनुरक्षण नीति-2018MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के विरुद्ध आवंटन उपलब्ध कराने के संबंध में।

महाषय,

उपरोक्त विषय के संबंध में सूचित करनाहै कि नई अनुरक्षण नीति—2018 MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के लिए संवेदक को भुगतान करने हेतु अधियाचना विहित प्रपत्र में भरकर आवष्यक कार्यवाही हेतु समर्पित की जाती है।

अनु० :- यथोक्त।

विष्वासभाजन

कार्यपालक अभियंता, ग्रामीण कार्य विभाग, कार्य प्रमंडल, सासाराम–1

9/0/02/21

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)

Form of Utilization Certificate up to Feb 2021

Sl.No	Name of Scheme	Sanction No.&Date With Amount (In lace Rs.)	Amount Received (In lace Rs.)	Particulars
1	Construction of Rural roads Under MR	New Maintenance Policy-2018 MR (3054)		Certified that out of Rs. 25,15,10,100.00 lakh of grants-in-aid sanctioned during the years 2020-21 Infavor of EE,RWD works division
		BRRDA PATNA Letter No.82, dt. 13.11.2020	24012800.00	Sasaram-1 a sum of Rs 187759733.00 lakh has been utilized for the purpose of MR (3054) Schemes as given in the margin for which it was sanctioned and
		Letter No.84, dt. 26.11.2020	19457900.00	that the balance of Rs. 63750362.00 lakh remaining unutilized at the end of the period under report.
		Letter No.86, dt. 11.12.2020	65864300.00	
		Letter No.05, dt. 12.01.2021	142175100.00	
	Total:		25,15,10,100.00	

2. Certified that I have satisfied my self that the conditions on which the grant-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was utilized for the purpose for which it was sanctioned.

Kind of Checks exercised:-

- i. Works have been supervised by Executive Engineer/ Superintending Engineer.
- ii. Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- iii. Construction materials have been tested.
- iv. Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- v. All other caudal formalities have been observed.
- 3. Physical Progress achieved:
 - i. Construction of Road Works.
 - ii. Construction of CD works.

Divisional Accounts Officer R.W.D, works Division Sasaram-1

Executive Engineer R.W.D, works Division

Sasaram-1

OFFICE OF EXECUTIVE ENGINEER, RURAL WORKS DEPARTMENT, WORKS DIVISION, SASARAM-1

Regisition Format for Scheme Head- MR(3054) under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

	n n	1		Si no. No 2019-20	
	23 B	2			
	Badkadih Vihea - Sishanpura	ω		Name of Road	
Total	10301002148	4		Project ID as per MIS	
	3021 16.07.2019	5		Approval (AA) Letter No & Date	
1.600	1.600	6		Length (In km)	Administrat (A
1.600 72.59480	72.59480	,	,	Amount of (In Lakh)	Administrative Approval (AA)
27.659	27.659	o		Initial Rectification with Surface Renewal (In Lakh)	Agreement Amount (In Lakh)
12.94132	12.94132	9	0	Initial Rectification 5 Year Routine with Surface Maintenance Renewal (In Lakh) (In Lakh)	akh)
	15/MBD/ 2020-21 20.02.20	TO	10	Agreement Completion No& Date as per Agreemen	
	15/MBD/ 2020-21 19.10.2020 20.02.20	1.1	11	+ 3	Date of
	1	**	12	of Completion	
	2631		13	IRI (in mm/km)	Value of
	25.00		14	IRI of Bitumen Bitumen (in Layer Content in mm/km) (in mm) Percentage	Value of Thickness Value of
	5.04		15	Bitumen Content in Percentage	Value of
16.59540			16	Alloted Amount (In Lakh)	Previous
16.59540 16.59540 11.06360	16.59540 16.59540 11.06360		17	Alloted as per MIS work done Amount (in Lakh) (in Lakh) (in Lakh)	up-to-date Requisition
11.06360	11.06360		18	against work done (In Lakh)	Requisition
	Called Son			D	W. N

Remarks

19

Divisional Accounts Office
Rural Works Danner Rural Works Department, works Division, Sasaram-1

Rural Works Department Works Division, Sasaram-1

10/02 S

Executive Engineer

Name of Road: Badkadih Vlhea - Sishanpura


_	Norma	83.88253 Normal	24.85066	2631 G		2200	10.1	220	0.1	82	16/ 12/ 20 14: 44: 13	16/ 12/ 20
	Norma		24.85047	3199 G		2700	10.1	270	0.1	82	16/ 12/ 20 14: 44: 13	16/ 12/ 20
	Norma	83.88449 Normal	24.85027	2404 G		2000	14.3	200	0.1	82	16/ 12/ 20 14: 43: 37	16/ 12/ 20
	Norma		24.85003	2972 G		2500	12.3	250	0.1	82	14: 43: 2	16/ 12/ 20 14: 43: 2
	Norma	1	24.84964	2972 G		2500	10.1	250	0.1	82	14: 43: 0	16/ 12/ 20 14: 43: 0
	Norma		24.84957	2631 G		2200	13.2	220	0.1	82	16/ 12/ 20 14: 42: 27	16/ 12/ 20
	Normal		24.84947	2518 G		2100	10.1	210	0.1	82	16/ 12/ 20 14: 41: 16	16/ 12/ 20
	83.8885 Normal	\top	24.85033	2972 G		2500	13.2	250	0.1	82	14:41:0	16/ 12/ 20
	83.8886 Normal	83.8886	24.85123	2177 G		1800	10.1	180	0.1	82	14: 40: 6	16/ 12/ 20
^4000	Normal	000	24.85218	2858 G		2400	20.2	240	0.1	82	14: 40: 0	16/ 12/ 20 14: 40: 0
	NOTITION		24.85306	2972 G	1	2500	20.2	250	0.1	82	16/ 12/ 20 14: 39: 30	16/ 12/ 20
	NOTIFICAL	03.000/ Normal	24.85399	3199 6		2700	10.1	270	0.1	82	14: 39: 0	16/12/20 14:39:0
(B) BI IRA	Normal	03.0000 Normal	24.65469	2972 G		2500		250	0.1	82	14: 39: 0	16/12/20 14:39:0
	Normal	1~	24.85541	2745 G		2300	10.1	230	0.1	82	16/12/20 14:38:20	16/ 12/ 20
1 = 203	Normal		24.85532	3086 G		2600	20.2	260	0.1	82	14: 38: 0	16/ 12/ 20 14: 38: 0
	Normal	83.89136 Normal	24.85526	2972 G		2500	16.1	250	0.1	82	16/ 12/ 20 14: 37: 45	16/ 12/ 20
				ROAD	mm/km	mm/km	Rate	in mm	in km	No.		
×-0*<	Evell	_atitude_ongitude	Latitude	IRIATEGORY		OR	Speed	Bumps	Length	Section	Time	Date



)*X^2+1.136*X+132.5 2200 2631

RAL ROAD

Average Poor 4001-5000 >5001



Managares Magares