

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, रजौली।

Mob No. 8986915851

Email. ID-eerwdrajauli@gmail.com

पत्रांक..... 1737

रजौली/दिनांक..... 29.12.2020.

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, रजौली।

सेवा में,

नोडल पदाधिकारी,
M.R 3054 ,
ग्रामीण कार्य विभाग, बिहार, पटना।

विषय:-


योजना मद शीर्ष (3054) अन्तर्गत नई अनुरक्षण नीती 2018 अन्तर्गत कार्य हेतु अधियचना के संबंध में।

महाशय,


उपर्युक्त विषय से संबंधित योजना मद शीर्ष 3054 अन्तर्गत नई अनुरक्षण नीती 2018 से संबंधित कार्य हेतु अधियचना विहित प्रपत्र में भरकर आवंटन उपलब्ध कराने हेतु समर्पित किया जाता हैं।

अनु0- यथोक्त

विश्वासभाजन



कार्यपालक/अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, रजौली।


29/12/20

Requisition for Scheme Head :- MR (3054) under Bihar Rural Road Maintenance Policy 2018
(Initial Rectification and Surface Renewal)

Name of Works Division: RWD (W) Division, Rajauli

SL. NO	Package No-	Name Of Road	Project Id as Per MIS	Administrative Approval (AA) Letter No- & Date	Administrative Approval (AA)		Agreement Amount		Agreement No- & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/Km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen content in percentage	Previous Total allotted Amount (in Lakh)	upto date expenditure as per MIS (in Lakh)	Requisition against work done (in lakh)	Remarks
					Length (in km)	Amount (in lakh)	Initial Rectification with surface Renewal (in lakh)	5 years routine Maintenance (in Lakh)										
1	RM/NA/RAJ/20/0002	Oilpur to Akri Road	15271033258	6285/02.12.2019	2.48	92.464	59.544	21.73164	03/MR-3054/MBD/2020-17.08.2020	16.05.2021	-	2790	25	5.01	47.6352	44.55485	11.9088	On-going
2	RM/NA/RAJ/20/0002	NH 31 to Garibas	15271032841	6285/02.12.2019	3	108.928	67.397	27.98366	03/MR-3054/MBD/2020-17.08.2020	16.05.2021	-	3005	25	5	53.9176	51.03846	16.35854	On-going
3	RM/NA/RAJ/20/0002	NH-31 to Madaini (Bahadurpur)	15271033064	3020/16.07.2019	3.1	111.72	68.936	29.04602	03/MR-3054/MBD/2020-17.08.2020	16.05.2021	-	2993	25	5.01	-	-	68.936	On-going
4	RM/NA/RAJ/19/013	Jhikarua- Chatar	10502602066	5165/25.09.2019	7.5	218.077	141.969	59.54149	02/MR-3054/MBD/2020-14.03.2020	13.12.2020	-	2063	25	5.01	94.927	94.927	40.683	On-going
5	RM/NA/RAJ/19/0002	KALAUNDA- DARIYAPUR	10502602069	2162/06.07.2019	2.682	125.5031	87.68	27.89501	11/MR-3054/MBD/2019-10.01.2020	09.10.2020	-	2600	25	5.01	0	0	87.68	On-going
TOTAL															225.56634			

[Signature]
Executive Engineer
Rural Works Department
Works Division- Rajauli

[Signature]
29/12/20

FORM GFR 19 -A

[See Government of India's Decision (I) below Rule - 150]

Name of PIU : Rural Works Department, Works Division, Rajauli

Head : Rural Road Maintenance Policy 2018 Form of Utilization Certificate for the month of December 2020

SL. No.	Name of Scheme	Sanctioned No. & Date with Amout	Amount Received	Pariculars
1	Rural Road Maintenance Policy 2018	Vide letter No. & Date	RS. 246349559	Certified that out of <u>Rs.246349559</u> Of grants in aid sanctioned during the Year December 2020 in favour of RWD (W) Division, Rajauli (bihar) a sum of Rs has been utilized for the purpose of <u>RS. 219383188</u> Shemes as given in the margin for which it was given in which it was sanctioned and that the balance <u>Rs.26966371</u> remaining utilized at the end of the period under report


2. Certified that I have satisfied myself that the conditions on which the grants in aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exersed the following cheks to see that that the money was acutally utilized for the purpose for which it was sanctioned.


Kind of Checks exerclased :

- (i) Works have been supervised by Executive Engineer/ Superintending Enigneer
- (ii) Periodical inspection has been conducted by Executive Engineer/Superintending Enigneer
- (iii) Construction materials have been tested.
- (iv) Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/Executive Engineer
- (v) All other codal formalities have been observed

3. Physical Progress achieved

- (i) Construction of Road works
- (ii) Construction of CD works


29/12/20
Executive Engineer
RWD (W) Division
Rajauli


21/12/20

Name of Road - NH-31 to Madaini (Bahadurpur)

Name of Contractor -Saroj Kumar										Batch Name - MR-N/19-20/Rajauli-16	
Date	Time	Section	Length	Bumps	Speed	OR	IR In	CATEGORY	Latitude	Longitude	Event
		No.	in km	in mm	Rate	mm/km	UV	ROAD			
29/12/20	8:35:0	52	0.1	380	0	3800	3621	G	24.679838	85.512845	Normal
29/12/20	8:35:26	52	0.1	310	10.1	3100	3023	G	24.678957	85.512625	Normal
29/12/20	8:36:1	52	0.1	320	10.1	3200	3109	G	24.678073	85.51244	Speed Breaker
29/12/20	8:37:11	52	0.1	310	10.1	3100	3023	G	24.6772	85.512153	Normal
29/12/20	8:38:0	52	0.085	280	0	3294	3189	G	24.676477	85.511902	Normal
29/12/20	8:43:0	54	0.1	290	0	2900	2853	G	24.674957	85.511598	Normal
29/12/20	8:43:35	54	0.1	280	0	2800	2767	G	24.674152	85.511245	Normal
29/12/20	8:44:10	54	0.1	390	10.1	3900	3707	G	24.673435	85.510655	Normal
29/12/20	8:45:0	54	0.1	260	0	2600	2596	G	24.672687	85.51008	Normal
29/12/20	8:45:21	54	0.1	280	10.1	2800	2767	G	24.672032	85.50946	Normal
29/12/20	8:46:0	54	0.1	310	10.1	3100	3023	G	24.67138	85.508737	Speed Breaker
29/12/20	8:47:0	54	0.1	360	10.1	3600	3450	G	24.670772	85.508047	Normal
29/12/20	8:47:42	54	0.1	330	10.1	3300	3194	G	24.670152	85.507357	Speed Breaker
29/12/20	8:48:17	54	0.1	330	10.1	3300	3194	G	24.669585	85.506632	Normal
29/12/20	8:49:28	54	0.1	270	10.1	2700	2682	G	24.66898	85.505858	Speed Breaker
29/12/20	8:51:13	54	0.1	220	10.1	2200	2255	G	24.668472	85.50505	Normal
29/12/20	8:52:0	54	0.1	310	10.1	3100	3023	G	24.667672	85.504612	Normal
29/12/20	8:53:0	54	0.1	350	10.1	3500	3365	G	24.666782	85.504393	Normal
29/12/20	8:54:10	54	0.1	300	10.1	3000	2938	G	24.665945	85.504107	Normal
29/12/20	8:55:0	54	0.1	250	10.1	2500	2511	G	24.665115	85.50372	Normal
29/12/20	8:55:56	54	0.1	310	10.1	3100	3023	G	24.664263	85.5034	Normal

$$Y = 0 * X^2 + 0.854 * X + 376.5$$

$$X = 2400$$

$$Y = 2426$$

(R) RURAL ROAD

Good Average Poor

<4000 4001-5000 >5001

✓
29/12/20

29/12/20

AT

29/12/20

29/12/20	8:56:31	54	0.1	340	10.1	3400	3280	G	24.66343	85.503097	Normal
29/12/20	8:57:6	54	0.1	270	10.1	2700	2682	G	24.662528	85.503013	Normal
29/12/20	8:58:17	54	0.1	360	10.1	3600	3450	G	24.661623	85.50308	Normal
29/12/20	8:59:27	54	0.1	340	10.1	3400	3280	G	24.661013	85.502677	Curve
29/12/20	9:0:3	54	0.1	300	10.1	3000	2938	G	24.66102	85.5017	Normal
29/12/20	9:1:13	54	0.1	240	10.1	2400	2426	G	24.6607	85.500823	Normal
29/12/20	9:2:24	54	0.1	240	10.1	2400	2426	G	24.660623	85.499882	Normal
						Total	83795				
						Average	2992.67				


$\frac{29.57}{29.12.20}$
 hr

Gmt
 29.12.20
 AC


 30/12/20
 EV

File : E:\Bump Indicator\29120903.Xls. Section No. : 52. Eqn : $Y = 0 \cdot X^2 + 0.854 \cdot X + 376.5$

Name of Customer : Shri Saroj Kumar. Name of Work/ Road : NH-31 to Madaini (Bahadurpur). Lab Job number :




$\frac{29.12.20}{29.12.20}$
M, -

$\frac{29.12.20}{29.12.20}$
AC

$\frac{29.12.20}{29.12.20}$
EL

File : E:\Bump Indicator\29120903.Xls. Section No. : 54, Eqn : $Y = 0 \cdot X^2 + 0.854 \cdot X + 376.5$
 Name of Customer : Shri Saroj Kumar, Name of Work/ Road : NH-31 to Madaini (Bahadurpur), Lab Job number :



Y. S. P.
 29.12.20
 DE

Sumit
 29/12/20
 AE

JK
 30/12/20
 EV