

कार्यपालक अभियंता, ग्रामीण कार्य विभाग कार्य प्रमंडल, दलसिंहसराय, समस्तीपुर

पत्रांक 154/2021

दलसिंहसराय / दिनांक 12/01/21

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, दलसिंहसराय

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी
सचिव-सह-प्राधिकृत पदाधिकारी
ग्रामीण पथ विकास एजेंसी पटना ।

विषय- **New Maintenance Policy 2018(MR New)** योजनान्तर्गत पथ में आवंटन
उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में सूचित करना है कि **New Maintenance Policy 2018(MR New)** योजनान्तर्गत चल रहे पथ के निर्माणधीन कार्य के विरुद्ध चल रहे योजनाओं का भुगतान **Rs.-36.44300 (Thirty Six Lakh Forty Four Thousand Three Hundred Rupess)** कि आवश्यकता है अधियाचना का निर्माण कार्य विशिष्टों के अनुरूप है तथा कार्य संतोषप्रद है।


अतः अनुरोध है कि अधियाचना पत्र के आधार पर आवंटन **Rs.-36.44300 (Thirty Six Lakh Forty Four Thousand Three Hundred Rupess)** उपलब्ध कराने की कृपा की जाये।

अनु0- 1) अधियाचना प्रपत्र।

2) 19 ए फॉर्म।

3) IRI Report की छायाप्रति सलग्न।

विश्वासभाजन


12/01/21

कार्यपालक अभियंता
ग्रामीण कार्य विभाग

कार्य प्रमंडल, दलसिंहसराय

14/01/21

Rural Works Department, Works Division Dalsinghsarai
Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy 2018
(Initial Rectification and Surface Renewal)

Name of Division : PIU(Dalsinghsarai)

Sl No	Package no.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA) Length (in Km)	Administrative Approval (AA) Amount (in Lac)	Agreement Amount (in Lac)	Initial Rectification with Surface Renewal (in lac)	5 years Routine Maintenance (in lac)	Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Amount (Lac)	up to date expenditure as per MIS (in Lac)	Requisition Against work done (in lac)	Remarks
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	
RRM/SA/DAL/19/0017																			
1		Samastipur jila antargat morva prkhand me kali ashan namdisthor mistar ke ghar hote hua shivchandar sah ke dukan PMCSY tak path nitman	32010403009		0.690	21.26390	9.39500	4.09392				-	3764	25mm	5.10%	9.39500	8.45550	0.00000	
2		Samastipur jila antargat morva prkhand ke gram panchayat indrawara ke prdhanmantri sadak madhay chok se vai shivji saroni ke ghar hote hua nun nadi ghari ashtal tak sadak nitman	32010403010		0.570	18.44820	8.29300	3.36880				-	3729	25mm	5.10%	8.29300	0.00000	0.00000	
3		Chandauli Hart Se Mirjapur Village me Reo Sadak Tak	10105100	2200 / 08.07.2019	1.800	57.50880	34.22700	13.79259		MBD 73/2019 20 27.02.2020	16.09.2020	-	-	-	-	0.00000	0.00000	0.00000	
4		Gumai Basi Ward-1 Se Ward No-2 Tak	10105101		1.250	42.07280	25.38200	9.50637				-	-	-	-	0.00000	0.00000	0.00000	
5		Nikaspur Mahadalit Basti Se Shantlesh Baba Sihan se REO Path Tak	10105104		0.500	15.62720	9.90100	2.83012				-	-	-	-	0.00000	0.00000	0.00000	
6		SH Paton Path Se Paladpur Hote Hue Bajilpur Chowk Tak	10105106		1.700	61.09060	36.44300	14.43161				-	2744	25mm	5.10%	0.00000	0.00000	36.44300	
7		SUST Path se Rai Tola Tak	10105108		0.750	29.83630	18.86800	5.90173				-	-	-	-	0.00000	0.00000	0.00000	
8		PWD Sadak Se Chandauli AHHC Mandir Tak	10105116		1.000	29.97940	19.20500	5.64539				-	-	-	-	0.00000	0.00000	0.00000	
					3.060	97.22090	51.915	21.255								17.68800	8.45550	36.44300	

1 Signed Hard Copy and Soft Copy (in Excel) of recorded IRI is enclosed.

2 Up-to date Physical Progress has been uploaded in MIS.

Sr. Divisional Account Officer
Rural Works Department,
Works Division Dalsinghsarai

Executive Engineer
Rural Works Department,
Works Division Dalsinghsarai

FORM GFR-19-A

(See Govt. of India's decision(i) below rule 150)
Form of Utilisation Certificate upto January 2021

New Maintenance Policy 2018(MR New)

PIU;- RWD Works Division Dalsinghsarai

Sl No	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lakh)	Amount Received (in Lakh)	Particulars
1	2	3	4	5
1	New Maintenance Policy 2018 (MR New)	752.28171	752.28171	Certified that out of Rs-752.28171 Lakh received till date in favour of Executive Engineer, RWD Works Division Dalsinghsarai a Sum of Rs-457.38141 Lakh has been utilized for the New Maintenance Policy 2018(MR New) Scheme as given in the margine for which it was Sanctioned and that the Balance of Rs-303.35565 Lakh remaining unutilized at the end of period under the time of completion
		752.28171	752.28171	


2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was


Kind of Checks Exercised:-

- (i) Workers have been supervised by Executive Engineer/ Superintending Engineer
- (ii) Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer
- (iii) Construction materials have been tested
- (iv) Measurments have been recorded in the MB's and test check conducted by the
- (v) All other codal formalities have ovserved


3. Physical Progress Achieved

- (i) Construction of Road Works
- (ii) Construction of CD Works


Sr.DAO
Rural Works Department,
Works Division Dalsinghsarai


Executive Engineer
Rural Works Department,
Works Division Dalsinghsarai
14/1/21

File: C:\MyAmaster\New folder\New folder\22121824.Xls. Section No.: 79. Egn: $Y = 0 \cdot X^2 + 1.136 \cdot X + 132.5$
 Name of Customer: Ratnesh Construction Private Limited. Name of Work/ Road: SH Patari Path Se Pahadpur Hote



Checked
 16/12/2020
 J.E.

Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATE GORY	Latitude	Longitude	Event	Y = 0 * X ^ 2 + 1.136 * X + 132.5			
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD				X = 4200			
16/ 12/ 20	15: 41: 47	79	0.1	190	0	1900	2290	G	0	0	Normal				
16/ 12/ 20	15: 42: 22	79	0.1	210	10.1	2100	2518	G	25.69221	85.638602	Normal	Y = 4903			
16/ 12/ 20	15: 43: 0	79	0.1	220	10.1	2200	2631	G	25.69206	85.639982	Normal				
16/ 12/ 20	15: 43: 0	79	0.1	290	10.1	2900	3426	G	25.69194	85.640908	Normal				
16/ 12/ 20	15: 44: 0	79	0.1	400	10.1	4000	4676	A	25.69185	85.641868	Curve	(R) RURAL ROAD			
16/ 12/ 20	15: 44: 8	79	0.1	170	10.1	1700	2063	G	25.6927	85.641935	Normal	Good	Average	Poor	
16/ 12/ 20	15: 45: 0	79	0.1	190	10.1	1900	2290	G	25.69357	85.641868	Normal	<4000	4001-5000	>5001	
16/ 12/ 20	15: 45: 19	79	0.1	230	10.1	2300	2745	G	25.69443	85.642053	Normal				
16/ 12/ 20	15: 45: 19	79	0.1	290	10.1	2900	3426	G	25.69523	85.64212	Speed Breaker				
16/ 12/ 20	15: 46: 0	79	0.1	200	10.1	2000	2404	G	25.696	85.641935	Normal				
16/ 12/ 20	15: 46: 29	79	0.1	180	10.1	1800	2177	G	25.69673	85.642305	Curve ,				
16/ 12/ 20	15: 47: 5	79	0.1	180	10.1	1800	2177	G	25.69738	85.64177	Normal				
16/ 12/ 20	15: 47: 40	79	0.1	300	0	3000	3540	G	25.69819	85.64182	Speed Breaker				
16/ 12/ 20	15: 48: 15	79	0.1	190	10.1	1900	2290	G	25.69893	85.642288	Normal				
16/ 12/ 20	15: 49: 0	79	0.1	290	10.1	2900	3426	G	25.69976	85.642592	Normal				
16/ 12/ 20	15: 49: 26	79	0.1	180	10.1	1800	2177	G	25.70061	85.64239	Normal				
16/ 12/ 20	15: 50: 1	79	0.1	200	10.1	2000	2404	G	25.70135	85.641852	Normal				

Handwritten signature
 16/12/2020
 J.E.