Inspection Report for Flood Damage Work

Date:-1 Name of PIUs: - Gyan bribbakar 2 Name of Block/Road: NHS7 High School chook to tekurn sura tola (Gaighat) (A) For Road: \checkmark :- 0.02km, 0.120km, 1. Damage Location/Chainage :- 1485 M (1.485km) 2. Damage Length (renth=454km) 3. Nature of Damage 4. Details of Restoration Works: Material being used in Restoration works:- Brick bats (i) (ii) Equipment's/Tools being used in Restoration works:-Procedure taken up in Restoration works: (iii) (iv) Restored Length :- 1:485 Km χ (B) For Bridge: 1. Damage Location/Chainage 2. Damage Length 3. Nature of Damage 4. Details of Restoration Works: (i) Material being used in Restoration works:-(ii) Equipment's/Tools being used in Restoration works:-(iii) Procedure taken up in Restoration works:-

Signature of JE/AE/EE

(iv) Restored Length

Signature

(Name of Inspection)

EE

RWD WORK DIVISION
MGZGFFER DAR CONTIL

GENERAL ABSTRACT

Name of Road

NH-57 High School Chowk to Tekuna Sura Tola

District

Muzaffarpur

Block

Gaighat

Division

Muzaffarpur East-2

Length of Road (in Km)

4.540 Km

		AMOUNT (LAKHS)
SI. No.	DESCRIPTION	27.824
1	Jhama metal	0.000
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	27.824
	GRAND SUB TOTAL	27.824
TOTAL	COST OF PROJECT IN LACS =	

3941.27.82 LAC

Andro Galines JE RWD AE RWD

RWD RWD

Technically Approved for Ps. 27.82 Lac.

(pulpees twenty Seven Lac, eighty two thousand enty.).

pud work circle