

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल बाँका - 1

पत्रांक 61 बाँका/

दिनांक 15.01.2021

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल बाँका - 1

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण पटना।

विषय : -गैर योजना मद शीर्ष 3054 एम0आर0 योजना अन्तर्गत आवंटन के संबंध में।


महाशय,

उपर्युक्त विषयक से संबंधित एम0आर0 योजना अन्तर्गत संवेदक द्वारा कराए गये कार्यों के भुगतान हेतु विहित प्रपत्र में अधियाचित राशि रूपया **11.07564/-**लाख का आवंटन उपलब्ध कराने की कृपा की जाय। ताकि संवेदक को भुगतान किया जा सके।

अनु0:-

1. अधियाचनाप्रपत्र
2. IRI Report

विश्वासभाजन


कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल बाँका (1)

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल बाँका - 1

पत्रांक

बाँका/

दिनांक

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल बाँका - 1

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण पटना।

विषय : -गैर योजना मद शीर्ष 3054 एम0आर0 योजना अन्तर्गत आवंटन के संबंध में।


महाशय,

उपर्युक्त विषयक से संबंधित एम0आर0 योजना अन्तर्गत संवेदक द्वारा कराए गये कार्यों के भुगतान हेतु विहित प्रपत्र में अधियाचित राशि रूपया **11.07564/-**लाख का आवंटन उपलब्ध कराने की कृपा की जाय। ताकि संवेदक को भुगतान किया जा सके।

अनु0:-

1. अधियाचनाप्रपत्र
2. IRI Report

विश्वासभाजन




कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल बाँका-1

ज्ञापक- /बाँका, 61

दिनांक- 15.01.2021

प्रतिलिपि-मुख्य अभियंता-4, ग्रामीण कार्य विभाग, बिहार पटना को सूचनार्थ एवं आवश्यक कार्रवाई हेतु समर्पित।



कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल बाँका-1

Name of Division : Banka-I

Requisition format for Scheme Head - MR 3054 Under Bihar Rural Road Maintenance Policy 2018 (In Rectification and Surface Renewal)

Sl No.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (In Lac)		Agreement No. & Date	Date of Completion as per Agreement	Actual of Completion Date	Value of IRI (In Km)	Thickness of Bitumen Layer (In mm)	Value of Bitumen Content in %	Previous Total Allotted Amount (In Lac)	Up to date expenditure as per MIS (In Lac)	Requisition Against work done (In Lac)	Remarks
1	MR-N/19-20 BANKA-1/05	Bhumihara More To Bharatshila Village	NEA22000402	1836 & 24.06.2019	1.380	31.460	27.68910	12.96251	10MIBD/2 019-20	15-09-2020	15-08-2020	3365	25	5	16.61346	16.61346	11.07564	Completed
		Chhatthar To Khajuri	20703502217	1836 & 24.06.2019	3.000	67.070	60.13057	27.24985	10MIBD/2 019-20	15-09-2020	15-08-2020	3165	25	5	36.07834	36.07834	24.05223	Completed
		Imp of Kurma more (Shambhuganj Asarganj RCD Road) To Goyara Lakhampur	20703501017	1836 & 24.06.2019	5.300	131.720	118.47011	47.70550	10MIBD/2 019-20	15-09-2020	15-08-2020	3483	25	5	59.23500	59.235	59.23511	Completed
		Mirzapur Kitanpur Road To Pahampur Via Parana	NEA22000416	1836 & 24.06.2019	4.650	110.360	99.01669	40.67862	10MIBD/2 019-20	15-09-2020	15-08-2020	3218	25	5	59.40600	59.406	39.61069	Completed

SR. Divisional Account Officer

R.W.D. (W) Div. Banka-01

Executive Engineer
Rural Works Department
Works Division, Banka-I

Lab Job number :7

Date :27-11-2020

Name of Customer :Prince Construction

Name of Work/ Road :Bhumihara More To Bharatshila Village


Sr.no	Location of	Corrected U.I	Road catagory
	test(in km)	value(mm/km)	
1	0.1	2981	G
2	0.2	3272	G
3	0.3	2981	G
4	0.4	3756	G
5	0.5	3144	G
6	0.6	3338	G
7	0.7	3562	G
8	0.8	3175	G
9	0.9	3369	G
10	1	2981	G
11	1.1	2981	G
12	1.2	3659	G
13	1.3	3694	G
14	1.4	3659	G

Dumal
14.12.2020
Junior Engineer

Pritam
14.12.2020
Asstt. Engineer
Rural Works Department
Works Division, Banka-I

S. S. S.
14.12.2020
Executive Engineer
Rural Works Department
Works Division, Banka-I

File: C:\Users\ASUS\Desktop\06031656.Xls, Section No.: 7, Eqn: $Y = 0 \cdot X^2 + 0.969 \cdot X + 74.60$



Name of Customer: Prince Construction
Name of Work/ Road: Bhumihera More To Bharatshila
Lab Job number: 7
Date: 27-11-2020
Section No.: 7


Test Date: 27-11-2020 Road Name: Bhumihera More To Bharatshila
Machine No: 407 Road Type: (R) RURAL ROAD
Start S No: Side: Interval
Start E No: Weather: UIV Range: 1981 To 5000 1000 mm/km
Start Location: 25.97645 Dist Range: 0 To 1.5 0.1 * 1000 m
End Location: 86.893097 Equation: $Y = 0 * X^2 + 0.969 * X + 74.60$

Print

Generate Report and Graph

Redraw Graph

Map View



Examiner
14.12.2020
J.E.

Pritam
14.12.2020
A.E.

S. S. S.
14.12.2020
A.E.

Name of Customer :Prince Construction								Lab Job number :7				
Name of Work/ Road :Bhumihara More To Bharatshila Village								Date :27-11-2020				
Date	Time	Section	Length	Bumps	Speed	OR		CATEGORY	IRI	Latitude	Longitude	Event
		No.	in km	in mm	Rate	mm/km	UIV	ROAD				
08-11-2020	13:0:0	7	0.1	300	20.2	3000	2981	G	4	25.97645	86.893097	Normal
08-11-2020	13:0:22	7	0.2	330	30.3	3300	3272	G	4.35	25.97645	86.893097	Normal
08-11-2020	13:0:22	7	0.3	300	10.1	3000	2981	G	4	25.976582	86.892222	Normal
08-11-2020	13:0:22	7	0.4	380	30.3	3800	3756	G	4.92	25.977007	86.891363	Normal
08-11-2020	13:0:22	7	0.5	320	20.2	3200	3144	G	4.37	25.977332	86.89037	Normal
08-11-2020	13:0:22	7	0.6	340	10.1	3400	3338	G	4.59	25.977788	86.889697	Normal
08-11-2020	13:0:22	7	0.7	360	20.2	3600	3562	G	4.69	25.978563	86.889343	Normal
08-11-2020	13:0:22	7	0.8	320	30.3	3200	3175	G	4.23	25.979308	86.889007	Normal
08-11-2020	13:0:22	7	0.9	340	30.3	3400	3369	G	4.46	25.979738	86.88808	Normal
08-11-2020	13:0:22	7	1	300	30.3	3000	2981	G	4	25.98013	86.887153	Normal
08-11-2020	13:0:22	7	1.1	300	20.2	3000	2981	G	4	25.980572	86.886262	Normal
08-11-2020	13:0:22	7	1.2	370	20.2	3700	3659	G	4.8	25.980858	86.885318	Normal
08-11-2020	13:0:22	7	1.3	380	10.1	3800	3694	G	4.13	25.9813	86.884545	Normal
08-11-2020	13:0:22	7	1.38	370	20.2	3700	3659	G	4.8	24.97652	86.894057	Normal

$$Y = 0 * X^2 + 0.969 * X + 74.60$$

$$X = 0$$

$$Y = 74$$

(R) RURAL ROAD

Good Average Poor

<4000 4001-5000 >5001

Okumal
14.12.2020
Junior Engineer

Pritham
14.12.2020
Asstt. Engineer
Rural Works Department
Works Division, Banka-I

Pritham
14.12.2020
Executive Engineer
Rural Works Department
Works Division, Banka-I