Inspection Report for Flood Damage Work

15.1.21 Date:

1. Name of PIUs - Minaffer for Forst-2

2. Name of Block/Road -

Dhaphan ward or bandon Saheri house to Lathinoly canoni house

A. For Road

1. Damage Location/Chainage

1st know

2. Damage Length

8.6 10 B

3. Nature of Damage

Rose cutting

4. Details of Restoration Works

Material being used in Restoration works: brockball ii.

Equipments/Tools being used in Restoration works: Treater iii.

Procedure taken up in Restoration works:

iν. Restored Length

8-5 mt8

B. For Bridge

1. Damage Location/Chainage

2. Damage Length

3. Nature of Damage

4. Details of Restoration Works

i. Material being used in Restoration works:

Equipments/Tools being used in Restoration works: ii.

iii. Procedure taken up in Restoration works:

iv. Restored Length

Signature of JE/AE/EE

(Name of Inspector) Executive Engineer R.W.D. Works Division Muzaffarpur East-1

GENERAL ABSTRACT

Name of Road

Dhapahar Ward No-03 Kailash Sahani House to Lakhindra Sahani House

District

Muzaffarpur

Block

Minapur

Division

Muzaffarpur East-2

Length of Road (in Km)

SI. No.	DESCRIPTION	0.850 Km	
1	Jhama metal	AMOUNT (LAKHS)	
2	Sand Filling	4.200	
3	Sand bag	0.000	
4	H.P.	0.000	
	GRAND SUB TOTAL	0.261	
TOTAL	COST OF PROJECT IN LACS =	4.461	
THOSECT IN LACS =		4.461	

8/1/21

JΕ

RWD

Xel Ein

ΑE

RWD

ET S

RWD

Technically approved for Rs 4.46 Lac

(Rupees sour lac borry six thousand only)

Run work circle