Inspection Report for Flood Damage Work

Date:-

15-1.21

1 Name of PIUs: - Mysefferfur East-2

2 Name of Block/Road :-

sinai parti to ghosant Hospital

(A) For Road:

1. Damage Location/Chainage :- 1st, 2nd & 3ood kng

2. Damage Length

:- 330.0 mm: Scritting many place 3. Nature of Damage

4. Details of Restoration Works :-

Material being used in Restoration works:- Postek ball (i)

Equipment's/Tools being used in Restoration works: (ii)

Procedure taken up in Restoration works: (iii)

3300mh Restored Length (iv)

(B) For Bridge:

1. Damage Location/Chainage

2. Damage Length

3. Nature of Damage

4. Details of Restoration Works :-

(i) Material being used in Restoration works:-

(ii) Equipment's/Tools being used in Restoration works:-

(iii) Procedure taken up in Restoration works:-

(iv) Restored Length

Signature of JE/AE/EE

Signature

(Name of Inspection) Executive Engineer R.W.D. Works Division Muzaffarpur East-1

GENERAL ABSTRACT

Name of Road

Siwaipatti to Ghosaut Hospital(01-02)

District

Muzaffarpur

Block

Minapur

Division

Muzaffarpur East-2

Length of Road (in Km)

3.000 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	17.557
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	17.557
TOTAL COST OF PROJECT IN LACS =		17.557

RWD

Technically approved for RS 17 STF lac (Rupees seventeen lac the Sity five thousand seven hundred only)