Inspection Report for Flood Damage Work

Date:- 17 1-7

1 Name of PIUs: - Mysefforfur Est-2

2 Name of Block/Road: - Liey - Teg Ramnegar to pargambeton Conoul tolq

(A) For Road:

- 1. Damage Location/Chainage :- 2 by
- 2. Damage Length :- 36.0m
- 3. Nature of Damage :- Full Lutting
- 4. Details of Restoration Works :-
- (i) Material being used in Restoration works:-
- (ii) Equipment's/Tools being used in Restoration works:- Treeling
- (iii) Procedure taken up in Restoration works:
- (iv) Restored Length :- Thomas

(B) For Bridge:

- 1. Damage Location/Chainage :
- 2. Damage Length :
- 3. Nature of Damage :
- 4. Details of Restoration Works:
- (i) Material being used in Restoration works:-
- (ii) Equipment's/Tools being used in Restoration works:-
- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length

Signature of JE/AE/EE

Signature /

(Name of Inspection) Executive Engineer R.W.D. Works Division Muzaffarpur East-1

GENERAL ABSTRACT

Name of Road

L101 - T08 Ramnagar to Paigambarpur Sonoul Tola

Muzaffarpur

Minapur

Muzaffarpur East-2

Length of Road (in Km)

3.575 Km

SIL No.	DESCRIPTION	AMOUNT (LAKHS)
1 -	Jhama metal	2.547
2	Sand Filling	0.000
3	Sand bag	0.000
- 4	H.P.	0.000
	GRAND SUB TOTAL	2.547
TOTAL O	COST OF PROJECT IN LACS =	2.547

RWD

RWD

Techanically approved for B 2-547 lacs (Rufees two Lows fifty tour Thousand Seven hundred only)

S.E.
RIED HOOKE CIRCLE
MUZAHERPUR