

## Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan prabakar

2 Name of Block/Road :- talpiti Sahani keghar to purab Nadi tak (Bochara)

(A) For Road: ✓

1. Damage Location/Chainage :- 0.300km, 0.350km, 0.450km, 0.650km
2. Damage Length :- 150.10m (0.1501km)
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:- Brck bgt
  - (ii) Equipment's/Tools being used in Restoration works:-
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :- 0.150km (0.1501km)

(B) For Bridge: ✗

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:-
  - (ii) Equipment's/Tools being used in Restoration works:-
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :-

Signature of JE/AE/EE

Signature

(Name of Inspection)

EE

RWD WORK DIVISION

Muzaffarpur East-I

### GENERAL ABSTRACT

Name of Road Tripti Sahani Ke Ghar to Purab Nadi Tak  
District Muzaffarpur  
Block Bochaha  
Division Muzaffarpur East-2  
Length of Road (in Km) 0.850 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	5.103
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.142
	GRAND SUB TOTAL	5.246
TOTAL COST OF PROJECT IN LACS =		5.246

SAY 5.25 Lac.

*Satish Kumar*  
20/12/2020

*AE*  
20/12/20  
JE

RWD

*AE*  
20/12/20

AE

RWD

*Jan*  
20/12/20  
EE

RWD

Technically Approved for Rs 5.25 Lac.  
(Rupees five Lac, twenty <sup>five</sup> ~~four~~ thousand only).

*SE*  
4.1.21  
RWD work circle  
muzaffarpur.