## **Inspection Report for Flood Damage Work**

Date:-

15-1.21

1 Name of PIUs: - Mysafferfor Eest-2

2 Name of Block/Road:-

Kodassa mminsy to Tatama tola Primary school

## (A) For Road:

:- 14 42 had KM 1. Damage Location/Chainage

2. Damage Length

76.5 nm

3. Nature of Damage

and court work tul

4. Details of Restoration Works:

Material being used in Restoration works:- Panck bats (i)

Equipment's/Tools being used in Restoration works:- Tzelfry (ii)

Procedure taken up in Restoration works: (iii)

Restored Length (iv)

:- Flo. Emp

## (B) For Bridge:

1. Damage Location/Chainage

2. Damage Length

3. Nature of Damage

4. Details of Restoration Works:

(i) Material being used in Restoration works:-

(ii) Equipment's/Tools being used in Restoration works:-

(iii) Procedure taken up in Restoration works:-

(iv) Restored Length

Signature of JE/AE/EE

(Name of Inspection) Executive Engineer R.W.D. Works Division Muzaffarpur East-1

## **GENERAL ABSTRACT**

Name of Road

Kodaria MMGSY to Tatama Tola Primary School

District

Muzaffarpur

Block

Minapur

Division

Muzaffarpur East-2

Length of Road (in Km)

1.500 Km

SI. No.	DESCRIPTION	1.500 Km
1	Jhama metal	AMOUNT (LAKHS)
2 '	Sand Filling	12:303
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	0.000
TOTAL C	COST OF PROJECT IN LACS =	12.40.753
		12.402

B15.21

JE

**RWD** 

ARRONOIN

AE

RWD

Jan 8/11/

RWD

Technically approved for RS 12-403 lac (Rubers Twelve lac forty thousand three hundred only)

86 14.1.21

Kun word circle