Inspection Report for Flood Damage Work

Date:
1 Name of PIUs:- Gyam vibralcad

2 Name of Block/Road:- Katon / pwp Rand Ram Dayal Bartha House to Changel

2 Name of Block/Road:- Katon / pwp Rand Ram Dayal Bartha House to Changel

(A) For Road:

1. Damage Location/Chainage:- 0.800 to 0.830 km, 1.800 km to 1.805 km

2. Damage Length:- 0.342 km

3. Nature of Damage:4. Details of Restoration Works:(i) Material being used in Restoration works:- brite ball

(ii) Equipment's/Tools being used in Restoration works:- Tracked

(iii) Procedure taken up in Restoration works:

:- 0-3421cm

(B) For Bridge:

(iv)

Restored Length

Damage Location/Chainage : Damage Length : Nature of Damage : Details of Restoration Works : Material being used in Restoration works: Equipment's/Tools being used in Restoration works: Procedure taken up in Restoration works: Restored Length :-

Signature of JE/AE/EE

Signature /

(Name of Inspection)

CE

RWD MUZAHAPUS GUA-1

GENERAL ABSTRACT

Name of Road

PWD Road Ram Dayal Baitha House to Changel Bistha Siwan

District

Muzaffarpur

Block

Katra

Division

Muzaffarpur East-2

Length of Road (in Km)

2.320		Km	
	_		

engin or r	AMOUNT (LAKHS)	
. 的	DESCRIPTION	26.157
1.	Jhama metal	0.000
2	Sand Filling	0.000
3	Sand bag	0.000
	H.P.	26.157
	GRAND SUB TOTAL	26.157

Say 26: 157 lac

JEHI I WAY

PWD

AL 11.1.2021

RWD

TOWN SEE

RWD

Technically approved for RS 26.157 lac (Rupees Twenty six lac fifteen thousand seven hundred only)

SE SE

RND wone coule