

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल समस्तीपुर ।

पत्रांक: 81 (अनु०)

दिनांक:- 16/01/2021

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल समस्तीपुर ।

सेवा मे,

अपर मुख्य कार्यपालक पदाधिकारी - सह - सचिव
ग्रामीण कार्य विभाग,
बिहार, पटना ।

विषय:- नई अनुक्षण नीति 2018 शीर्ष MR-3054 योजना मद अंतर्गत व्यय हेतु आवंटन की मांग ।

महाशय,

उपर्युक्त विषयक नई अनुक्षण नीति 2018 शीर्ष MR-3054 योजना मद अंतर्गत व्यय हेतु
विहित प्रपत्र मे अधियाचना पत्र संलग्न कर भेजी जा रही है।

अतः अनुरोध है कि संलग्न विवरणी के अनुसार आवंटन उपलब्ध कराने का कृपा की जाए,
ताकि किये गये कार्यों का भुगतान किया जा सके ।

अनु० :- यथोक्त ।

विश्वासभाजन

16.1.21
कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल समस्तीपुर ।

16.1.2021


Requisition Format for scheme Head : MR(3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Division : Samastipur																		
Sl No	Package No	Project ID as Per MIS	Name of Road	Administrative Approval (A.A) Letter No & Date	Administrative Approval (A.A) Length (km)	Amount (In Lakh)	Initial Rectification with Surface Renewal	5 Year Routine Maintenance	Agreement No & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of RRI (In mm/km)	Thickness of Bitumen Layer (In MM)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (In Lakh)	Upto date Expenditure as per MIS (In Lakh)	Requisition against work done (In Lakh)	Remarks
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RM/SA/SA M/19/0012	32010102034	CHATURABHUIARA - KHATLAHA	2173/07.06.19	0.73	17.92	15.941	6.37047	14(MBD)2019-20/02.03.2020	07.10.2020	Ongoing	3135.57	25	5.1	0	0	15.941	BT Complete
2	RM/SA/SA M/19/0012	32010102040	KHAMPU - UDAIPUR COLONY	2173/07.06.19	1.26	26.47	22.294	11.49856	14(MBD)2019-20/02.03.2020	07.10.2020	Ongoing	3523.41	25	5.2	0	0	22.294	BT Complete
3	RM/SA/SA M/19/0012	32010102045	MDR TOI - RANJITPUR	2173/07.06.19	0.85	18.92	15.439	8.06886	14(MBD)2019-20/02.03.2020	07.10.2020	Ongoing	3681.12	25	5.11	0	0	15.439	BT Complete
4	RM/SA/SA M/19/0012	32010102082	T03 - BHAWANIPUR	2173/07.06.19	0.25	5.02	4.462	2.05126	14(MBD)2019-20/02.03.2020	07.10.2020	Ongoing	2460	25	5.12	0	0	4.462	BT Complete
5	RM/SA/SA M/19/0012	32010102083	T03 - BUZURGWAR	2173/07.06.19	0.43	7.84	6.748	3.82829	14(MBD)2019-20/02.03.2020	07.10.2020	Ongoing	3363.5	25	5.11	0	0	6.748	BT Complete
6	RM/SA/SA M/19/0012	32010102095	X-ROAD 1031 - SADIIPUR	2173/07.06.19	0.64	15.37	12.625	6.36335	14(MBD)2019-20/02.03.2020	07.10.2020	Ongoing	3435.33	25	5.1	0	0	12.625	BT Complete
7	RM/SA/SA M/19/0012	NEA22000585	T03 - SHIVESINGPUR	2173/07.06.19	1.2	31.55	27.455	11.74023	14(MBD)2019-20/02.03.2020	07.10.2020	Ongoing	3411.83	25	5.2	0	0	27.455	BT Complete
8	RM/SA/SA M/19/0007	32010102030	Tara chowk - Bharti chowk	2173/07.06.19	7.0	150.57	133.583	66.90639	12(MBD)2019-20/26.02.2020	7-Oct-20	Ongoing	3326.85	25	5.1	0	0	133.583	BT Complete
9	RM/SA/SA M/19/0007	NEA22000572	SH TO - LACHHRAMPUR	2173/07.06.19	1.45	15.72	29.896	14.06641	12(MBD)2019-20/26.02.2020	07.10.2020	Ongoing	3184.78	25	5.14	17.9376	17.9376	11.95840	BT Complete
10	RM/SA/SA M/19/0007	32010102069	SH - RAMPUR	2173/07.06.19	0.51	13.5	11.993	4.72395	12(MBD)2019-20/26.02.2020	7-Oct-20	Ongoing	3971.6	25	5.14	0	0	11.993	BT Complete
Total						302.89000	280.43600	135.61777									262.09840	

- Signed Hard Copy and Soft Copy (In Excel) of recorded RRI is enclosed.
- Up-to-date Physical Progress has been uploaded in MIS



 Executive Engineer
 RWD (W) Div. Samastipur
 16.1.2021

File :D:\bumpEntegrator\RWD div Samastipur\Panapur Construction.xlsx, Section No. :38, Eqn :test
 Name of Customer :Panapur Construction Pvt, Name of Work/ Road :SH se Laxrampur, Lab Job number :



स्पीड ब्रेकर। कर्व रहने के कारण संबंधित चैनल पर सीडिंग 4000 से ज्यादा आना है।


 21/12/20
 J.E.


 21/12/20
 A.E.


 22/12/20

Executive Engineer
 A. W. D. Works Division,
 Samastipur

Date	Time	Section	Length	Bumps	Speed	OR	IRI	TEGORY	Latitude	ongitude	Event			
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD				$Y = 0 * X^2 + 1.136 * X + 132.5$		
20/12/20	8:44:7	38	0.1	390	0	1900	2562	G	25.98222	85.73229	Normal	X = 3500		
20/12/20	8:44:7	38	0.1	350	10.1	3500	4108	A	25.98285	85.73295	Curve	Y = 4108		
20/12/20	8:44:43	38	0.1	450	20.2	1500	2244	G	25.98348	85.73369	Normal			
20/12/20	8:45:0	38	0.1	370	10.1	1700	2335	G	25.98409	85.73444	Normal			
20/12/20	8:45:18	38	0.1	340	10.1	3400	3994	G	25.9847	85.73515	Normal	(R) RURAL ROAD		
20/12/20	8:45:53	38	0.1	330	20.2	3300	4081	A	25.98537	85.73591	Curve	Good	Average	Poor
20/12/20	8:46:0	38	0.1	360	10.1	3600	4122	A	25.98573	85.73675	Culvert	<4000	4001-5000	>5001
20/12/20	8:46:28	38	0.1	320	20.2	3200	3767	G	25.98647	85.73741	Normal			
20/12/20	8:46:28	38	0.1	350	20.2	1500	2244	G	25.98715	85.73801	Normal			
20/12/20	8:47:4	38	0.1	370	10.1	1700	2335	G	25.98792	85.73859	Normal			
20/12/20	8:47:4	38	0.1	390	20.2	3400	3994	G	25.98862	85.73924	Normal			
20/12/20	8:47:39	38	0.1	380	10.1	1800	2449	G	25.98924	85.73993	Normal			
20/12/20	8:48:0	38	0.1	450	20.2	1500	2244	G	25.98991	85.74066	Normal			
20/12/20	8:48:14	38	0.1	350	10.1	3500	4108	A	25.99061	85.74125	Curve			

सुरोड बेडर / कर्क रहने से कारण संबंधित चैनल पर वीडियो 4000 के ऊपर है।


21/12/20
J.E


21/12/20
A.E


22/12/20

Executive Engineer
A. W. D. Works Division
Ganpatpur