

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan vibhakar

2 Name of Block/Road :- mirabpur / Uroam Hitora Ram Nagar Puroam Bazar to PWD Road
via Nagendra Sah Keshari

(A) For Road:

1. Damage Location/Chainage :- 0.320 km, 0.900 km, 0.980 km,
2. Damage Length :- 0.145 km
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- Brick ball
 - (ii) Equipment's/Tools being used in Restoration works:- Tractor
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 0.145 km

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE

Signature

(Name of Inspection)


EG

RWD muzaffarpur East-1


GENERAL ABSTRACT

Name of Road Gram Hitra Ram Nagar Purani Bazar to PWD Road via Nagendra Sah ke Ghar
District Muzaffarpur
Block Minapur
Division Muzaffarpur East-2
Length of Road (in Km) 1.280 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	5.693
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	5.693
TOTAL COST OF PROJECT IN LACS =		5.693


11/1/21


JE
RWD


11/1/21

AE
RWD


EE
RWD

Technically approved for Rs 5.693 lac
(Rupees five lac sixty nine thousand three hundred only)


13.1.21
SE

RWD work circle
muzaffarpur