

GOVERNMENT OF BIHAR

NAME OF WORK- Restoration work of road from PWD road Saidpur to Hukraha via MastiChak

(FDR PART-A)

Length-6.85km

BLOCK-DARIYAPUR

DETAILED PROJECT REPORT

UNDER FDR(2245)

ESTIMATED COST Rs-5.263LAcs

.:PREPARED BY :-EXECUTIVE ENGINEER RWD(W) DIVISION SONPUR

Inspection Report for flood damage work

Date:	
1. Name of Plus- R. N. D (W) DN Sont	5U/S
2. Name of Block/Road- Dariyabus, PND 8	이 그 이 계약 경험 보면 하는 그 집에 가장 하는데 그 가장 하는데 그렇게 되었다. 그 이 사람들은 사람들은 그는데 그렇게 되었다.
A.For Road	
1. Damage Location/Chainage: CH-1300m-1400	m (4-145000-1570M CH3
1. Damage Location/Chainage: CH = 1300 m = 1400	-CH-3435
2. Damage Lengh :195 ml	1 - Late 1
3. Nature of Damage Damage WBm Gr	I of Will be body dos
4.Details of Restoration :	
i Material being used in Restoration	: No
ii Equipment/Tools being used in Restoration w	orks: NO
iii Procedure taken up in Restoration works	Campa of wind of the d
iv Restored Length	:
19500	
B. For Bridge	
1.Damage Location/Chainage :	
2. Damage Lengh :	
3. Nature of Damage ;	
4.Details of Restoration :	
i Material being used in Restoration	
ii Equipment/Tools being used in Restoration w	orks:
iii Procedure taken up in Restoration works	•
iv Restored Length	
17 Restored Bengai	
	111/2
Signature of IE/AE/EE	Signature
Signature of JE/AF/EE	Signature
Bligh Property	(Name of Inspector)

A TON A TO

12.10 Winter

प्रमंडल का नामः

ग्रामीण कार्य विभाग, कार्य प्रमंडल सोनपुर

कार्य का नाम:--

सारण जिला अन्तगर्त दरियापुर प्रखंड में दरियापुर PWD रोड सैदपुर से हुकराहाँ भााया मस्तीचक पथ का बाढ़ एवं अति वृष्टि से क्षतिग्रस्त (FDR) पथांश का पूर्नःस्थापन कार्य।

पथ की कुल लम्बाई:-8.50कि0मी0 क्षतिग्रस्त पथ की लम्बाई:- 195मी0

प्राक्कलित राशि:-5.263 लाख

प्रतिवेदन

यह प्राक्कलन सारण जिला अन्तगर्त दिरयापुर प्रखंड में दिरयापुर PWD रोड सैदपुर से हुकराहाँ भााया मस्तीचक ग्रामीण पथ का बाढ़ एवं अति वृष्टि से क्षितग्रस्त (FDR) पथांश का पूर्नःस्थापन कार्य का प्राक्कलन का तैयार किया गया है।इस वर्ष अचानक अत्यधिक वाढ़ एवं अति वृष्टि के कारण Ch-1300M से Ch-1400m.एवं Ch-1450M से Ch-1550m पथांश पानी में कई दिनो तक डुबे रहने के कारण पथ बिल्कुल क्षितग्रस्त हो गया।साथ ही साथ पानी में भी पथ से भारी वाहनों के आवागमन होने के कारण पथ में कई स्थानो पर एक फीट से डेढ़ फीट गहरा कई pot holes बन गये है,जिसके के कारण पथ से आवागमन दुष्कर हो गया हैं

प्रस्तावित प्राक्कलन में Pot holes को WBM Gr2 WBM Gr3 एवं उसके उपर कालीकरण का प्रावधान किया गया है।

यह प्राक्कलन वर्तमान अनुसूचित दर पर तैयार किया गया है, जिसकी स्वीकृति आपेक्षित हैं।

कनीय अभियंता ग्रामीण कार्य विभाग कार्यग्रां प्रशाखा दरियापुर 10.12.20

सहायक अभियंता ग्रामीण कार्य विभाग कार्य अवर प्रंमडल दरियापुर कार्यपालक अभियंता ग्रामीण कार्य विभाग कार्य प्रमंडल, सोनपुर

Restoration work of road from PWD road Saidpur to Hukraha via MastiChak in Dariyapur Block

igth of road-									
	ABSTRACT OF COST								
Cpost of Emergent repair of road & Bridge		Rs. 465,747.53							
Add 1% Labour Cess		Rs. 4,657.48							
Add 12% GST		Rs. 55,889.70							
	. Tota	II Rs. 526,294.71							
	Sa	y Rs. 526,300.00							

Junior Engineer RWD(W) Dariyapur Assistant Engineer
RWD(W) sub division Dariyapur

Executive Engineer RWD(W) DiV Sonpur

T/A Approved for RS-5,263 larkh (Rupees Zive lace towesty Six Thousand Three) hundred) only 1

S.E. Chafra

Restoration work of road from PWD road Saidpur to Hukraha via MastiChak in

Dariyapur Block

	Item of work	Nos	Length	width	Height	Quantity	unit	Rate	Amount
1			V						
	Construction of embankment with approved material obtained from borrow pits with a lift upto 1.5 m, transporting to site, spreading, grading to required slope and compacting to meet requirement of Tables 300.1 and 300.2 with a lead upto 1000 m as per Technical								
_	Specification Clause 301.5 CH-3400 to 3435m	_	25.00	1.10					
-		1	35.00	1.13	0.60	23.63			
-	Total					23.63	cum	230.65	5449.2
	WBM Grading 2 Providing, laying, spreading and								
Bear of the Control o	compacting stone aggregates of specific sizes to water bound macadam specification including spreading in uniform thickness, hand packing, rolling with smooth wheel roller 80-100 kN in stages to proper grade and camber, applying and brooming, stone screening to fill-up the interstices of coarse aggregate, watering and compacting to the required density Grading 3 as per Technical Specification Clause 405.								
	CH-1300 to 1400m	1	100.00	3.75	0.075				
	CH-1450 to1500m	1	50.00	3.75	0.075	28.13	_		
	CH-3400 to 3435m	1	35.00		0.075	14.06			
	Total	 '	33.00	1.80	0.075	4.73			
	WBM Grading 3	_	-			46.9	cum	4782.10	224340.
	Providing, laying, spreading and compacting stone aggregates of specific sizes to water bound macadam specification including spreading in uniform thickness, hand packing, rolling with smooth wheel roller 80-100 kN in stages to proper grade and camber, applying and brooming, stone screening to fill-up the interstices of coarse aggregate, watering and compacting to the required density Grading 3 as per Technica Specification Clause 405.								
_	CH-1300 to 1400m	1	400.00						
	CH-1450 to 1560m	1	100.00	0.10	0.075	28.1	3		-
	CH-3400 to 3435m	-	60.00	3.75	0.075	16.8			
	Total	1	35.00	1.80	0.075	4.7	-		
	Total	+-				The same of the sa	3 cum		
-						49.1	্য cum	4745.2	6 235958