

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- *Gyan Vihar*

2 Name of Block/Road :- *Bahbal Bazar to Raghapur*

(A) For Road:

1. Damage Location/Chainage :- *ch 2350, 2365, 3005, 3100, 3150.*
2. Damage Length :- *87.70m*
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- *Brick bats, bamboo Piling, Sand bags.*
 - (ii) Equipment's/Tools being used in Restoration works:- *Tractor, JCB, Truck.*
 - (iii) Procedure taken up in Restoration works:
 - (iv) Restored Length :- *87.70m*

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE

[Signature]
Signature

(Name of Inspection)
Executive Engineer
R.W.D. Works Division
Muzaffarpur East-1

GENERAL ABSTRACT

Name of Road Bahbal Bazar to Raghopur

District Muzaffarpur

Block Minapur

Division Muzaffarpur East-2

Length of Road (in Km) 4.270 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	6.105
2	Bamboo Piles	0.064
3	Sand bag	0.131
4	H.P.	0.000
	GRAND SUB TOTAL	6.300
TOTAL COST OF PROJECT IN LACS =		6.300

By 6.300

JE
RWD

AE
RWD

EE
RWD

Technically approved for Rs. 6.30 lac (Rupees six lac-thirty thousand only).

S.E.
R.W.D. work circle
Muzaffarpur