Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs: - Cryon Vibhakar

1 Name of PIUS: - your viorus.

2 Name of Block/Road: - August Lo 69 Araji Ghanshyampur to Chainpur Dharhamua (UR43)

- 1. Damage Location/Chainage :- Many bluces.
 2. Damage Length :- 0.03596 Km
- 3. Nature of Damage 4. Details of Restoration Works :-
- Material being used in Restoration works:- Brick bots (i)
- Equipment's/Tools being used in Restoration works:- Tracker. (ii)
- Procedure taken up in Restoration works: (iii)
- (iv) Restored Length :- 0.03596 Km

(B) For Bridge:

- 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works :-
- Material being used in Restoration works:-(i)
- Equipment's/Tools being used in Restoration works:-(ii)
- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length

Signature of JE/AE/EE

(Name of Inspection)

कार्यपालक अभियंता ग्रामीण कार्य विभाग कार्य प्रमंडल,मुजयकरपुर पूर्वी-1

GENERAL ABSTRACT

Name of Road

L069 Araji Ghanshyampur to Chainpur Dharharwa (VR43)

District

Muzaffarpur

Block

Aurai

Division

Muzaffarpur East-2

Length of Road (in Km)

4.315 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Earthwork	0.000
2	Jhama metal	1.625
3	Sand Filling	0.000
4	Sand bag	0.000
5	H.P.	0.000
	GRAND SUB TOTAL	1.625
TOTAL C	COST OF PROJECT IN LACS =	1.625

111121

JE

RWD

Deblijoily

AE

RWD

EE '1 9

RWD

Technically approved for RS 1.625 lac (Rupees one lac sixty thro thousand five hundred only)

> अधीक्षण अभियंता ग्रामीण कार्य विभाग कार्य अंचल,मुजफ्फरपुर