

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan Vibhakar

2 Name of Block/Road :- Aurai / khetal pur Jih tela to Pryag chawk Jak.

(A) For Road:

1. Damage Location/Chainage :- 0.300 km, 0.450 km, 0.600 km
2. Damage Length :- 0.08534 km
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- Brick bats
 - (ii) Equipment's/Tools being used in Restoration works:- Tractor.
 - (iii) Procedure taken up in Restoration works:
 - (iv) Restored Length :- 0.08534 km

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


Signature

(Name of Inspection)

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, मुजफ्फरपुर पूर्वी-1

GENERAL ABSTRACT

Name of Road Khetalpur Dih Tola to Pryag Chawk Tak

District Muzaffarpur

Block Aurai

Division Muzaffarpur East-2

1.728 Km

Length of Road (in Km)		AMOUNT (LAKHS)
SI. No.	DESCRIPTION	3.354
1	Jhama metal	0.000
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	3.354
	GRAND SUB TOTAL	3.354
TOTAL COST OF PROJECT IN LACS =		3.354

Scp
11/11/21

JE
RWD

AS
11/11/21

AE
RWD

Jan
EE
11/11

RWD

Technically approved for Rs 3.354 lac
(Rupees Three lac thirty five thousand four hundred only)

1/11/21
अधीक्षण अभियंता
ग्रामीण कार्य विभाग
कार्य अंचल, मुजफ्फरपुर