

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग कार्य प्रमंडल बांका-1

पत्रांक 1078अनु0

बांका/

दिनांक 12.07.2021

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल बांका-1

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण पटना।

विषय:- New Maintenance Policy 2018 (MR 3054) योजना अन्तर्गत आवंटन के संबंध में।

महाशय,

उपर्युक्त विषयक से संबंधित एम0आर0 योजना अन्तर्गत संवेदक द्वारा कराए गये कार्यों के भुगतान हेतु विहित प्रपत्र में अधियाचित राशि रूपया 283.211/-लाख का आवंटन उपलब्ध कराने की कृपा की जाय। ताकि संवेदक को भुगतान किया जा सके।

अनु0:-

1. अधियाचना प्रपत्र
2. IRI Report

विश्वासभाजन

Sd/-

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल बांका-1 ।

ज्ञापांक-

/ बांका,

दिनांक-

प्रतिलिपि- मुख्य अभियंता-4, ग्रामीण कार्य विभाग, बिहार, पटना को सूचनार्थ एवं आवश्यक कार्रवाई हेतु समर्पित।

12/7/21

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल बांका-1 ।
Davi
12/7/21
(12/7/21)

Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy 2018 (Initial Rectification and Surface Renewal)

Name of Division : Banka-1

Sl No	Package no	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lac)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of RTI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Allocated Amount (Lac)	up to date expenditure as per MIS (in Lac)	Requisition Against work done (In lac)	Remarks
					Length (In Km)	Amount (in Lac)	Initial Rectification with Surface Renewal	5 years Routine Maintenance										
1		Pratap pur to Belari	NEA22000409	5270 04.10.2019	3.920	133.53100	87.591	34.9071		03.05.2021	26.04.2021	1921.23	25	5%	0.000	0.000	0.000	Surface Completed
2		WARSHBAD SBI ROAD to CHUTIA	20703502130	5270 04.10.2019	3.320	113.41800	72.569	29.95324		03.05.2021	26.04.2021	1812.44	25	5%	0.000	0.000	0.000	Surface Completed
3		ZILANI ROAD - SILOUTA	20703602068	5270 04.10.2019	3.240	114.01300	70.257	29.18989		03.05.2021	26.04.2021	1850.52	25	5%	0.000	0.000	0.000	Surface Completed
4		Impt of Jitarpur (BSP RWD Road) to Baisa Rampur	20703501012	5270 04.10.2019	2.000	68.53800	40.62	24.1028		03.05.2021	26.04.2021	3121.5	25	5%	0.000	0.000	40.620	Surface Completed
5		BANKA- BELDAUR ROAD - MAHARAJGANI	20703502029	5270 04.10.2019	2.930	99.37300	61.204	29.4116	08MBD/2020-21	03.05.2021	10.07.2021	2490.17	25	5%	0.000	0.000	61.204	Surface Completed
6		BANKA- BELDAUR ROAD - SAMUKHIA	20703502031	5270 04.10.2019	3.070	95.42600	63.132	27.18775		03.05.2021	10.07.2021	2559.87	25	5%	0.000	0.000	63.132	Surface Completed
7		Impt of Banka Pokharia PMGSY Road Bishahari more to Kalyampur Karikado	20703501004	5270 04.10.2019	2.670	88.90700	54.368	24.1028		03.05.2021	10.07.2021	2679.48	25	5%	0.000	0.000	54.368	Surface Completed
8		BANKA-KATORIA ROAD - JAMUA	20703502037	5270 04.10.2019	3.190	98.09000	63.887	28.9321		03.05.2021	10.07.2021	1852.13	25	5%	0.000	0.000	63.887	Surface Completed

283.211

12/12/21
Executive Engineer
RWD Works Division
Banka-1
Ravi
12.12.2021
(Signature)

Lab Job number :18

Date :10.07.2021

Name of Customer :		Anil Kumar Singh	
Name of Work/ Road :		Banka Belhar RCD Road to Maharajganj under MR 3054	
Sr.no	Location of test(in km)	Corrected U.I value(mm/km)	Road catagory
1	0.1	2497	G
2	0.2	3466	G
3	0.3	3078	G
4	0.4	2497	G
5	0.5	1624	G
6	0.6	2400	G
7	0.7	3562	G
8	0.8	2206	G
9	0.9	2109	G
10	1.0	2593	G
11	1.1	2303	G
12	1.2	2109	G
13	1.3	3950	G
14	1.4	2981	G
15	1.5	3853	G
16	1.6	2497	G
17	1.7	2787	G
18	1.8	2206	G
19	1.9	2400	G
20	2.0	1528	G
21	2.1	1624	G
22	2.2	2012	G
23	2.3	1528	G
24	2.4	1721	G
25	2.5	2497	G
26	2.6	1528	G
27	2.7	2400	G
28	2.8	1915	G
29	2.9	2981	G
30	3.0	3853	G
Avg Value of IRI Per Km		2490.17	G

Ravi
10/07/2021
(25M)

Skumar
12-07-21
Junior Engineer

Priyam
12-07-2021
Assistant Engineer
R.W.D Works Division
Banka-1

Amey 12/7/21
Executive Engineer
R.W.D Works Division
Banka-1

Name of Customer : Anil Kumar Singh

Name of Work/Road : Banka Belhar RCD Road to Maharajganj under MR 3054

Lab Job No: 18

$Y = 0 * X^2 + 0.969 * X + 74.60$
 $X = 3900$
 $Y = 3853$

(R) RURAL ROAD
 Good Average Poor
 <4000 4001-5000 >5001

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	UIV	CATEGORY ROAD	IRI	Latitude	Longitude	Event
10/7/21	10:6:6	18	0.1	250	10.2	2500	2497	G	3.42	24.926888	86.877878	Normal
10/7/21	10:7:0	18	0.1	350	10.2	3500	3466	G	4.58	24.927675	86.878147	Normal
10/7/21	10:7:16	18	0.1	310	20.2	3100	3078	G	4.12	24.928558	86.87843	Normal
10/7/21	10:7:16	18	0.1	250	30.3	2500	2497	G	3.42	24.929393	86.878787	Normal
10/7/21	10:7:16	18	0.1	160	30.3	1600	1624	G	2.33	24.93022	86.87914	Normal
10/7/21	10:8:0	18	0.1	240	20.2	2400	2400	G	3.3	24.930992	86.879242	Speed Breaker
10/7/21	10:8:0	18	0.1	360	20.2	3600	3562	G	4.69	24.93137	86.87835	Normal
10/7/21	10:8:27	18	0.1	220	30.3	2200	2206	G	3.06	24.932173	86.8784	Normal
10/7/21	10:8:27	18	0.1	210	30.3	2100	2109	G	2.94	24.933103	86.878568	Normal
10/7/21	10:8:27	18	0.1	260	30.3	2600	2593	G	3.53	24.933907	86.878703	Speed Breaker
10/7/21	10:9:0	18	0.1	230	40.4	2300	2303	G	3.18	24.934858	86.87877	Normal
10/7/21	10:9:2	18	0.1	210	30.3	2100	2109	G	2.94	24.93574	86.878938	Normal
10/7/21	10:9:2	18	0.1	400	10.1	4000	3950	G	5.14	24.936577	86.879242	Normal
10/7/21	10:9:38	18	0.1	300	20.2	3000	2981	G	4	24.937462	86.879443	Normal
10/7/21	10:10:13	18	0.1	390	20.2	3900	3853	G	5.03	24.937908	86.878753	Normal
10/7/21	10:10:13	18	0.1	250	30.3	2500	2497	G	3.42	24.938518	86.87803	Normal
10/7/21	10:10:13	18	0.1	280	30.3	2800	2787	G	3.77	24.939355	86.877928	Speed Breaker
10/7/21	10:10:48	18	0.1	220	30.3	2200	2206	G	3.06	24.940168	86.878163	Normal
10/7/21	10:11:0	18	0.1	240	40.4	2400	2400	G	3.3	24.94107	86.87847	Normal
10/7/21	10:11:0	18	0.1	150	30.3	1500	1528	G	2.2	24.9419	86.878618	Normal
10/7/21	10:11:0	18	0.1	160	40.4	1600	1624	G	2.33	24.942777	86.87837	Normal
10/7/21	10:11:23	18	0.1	200	30.3	2000	2012	G	2.82	24.943042	86.877457	Normal
10/7/21	10:11:23	18	0.1	150	30.3	1500	1528	G	2.2	24.943613	86.876885	Normal
10/7/21	10:11:23	18	0.1	170	30.3	1700	1721	G	2.45	24.944428	86.87648	Speed Breaker
10/7/21	10:12:0	18	0.1	250	30.3	2500	2497	G	3.42	24.945253	86.876852	Normal
10/7/21	10:12:0	18	0.1	150	40.4	1500	1528	G	2.2	24.945968	86.877373	Normal
10/7/21	10:12:0	18	0.1	240	30.3	2400	2400	G	3.3	24.94681	86.877878	Normal
10/7/21	10:12:34	18	0.1	190	20.2	1900	1915	G	2.7	24.946682	86.878803	Normal
10/7/21	10:12:34	18	0.1	300	20.2	3000	2981	G	4	24.947175	86.879512	Normal
10/7/21	10:15:0	18	0.1	390	0	3900	3853	G	5.03	24.947913	86.88003	Speed Breaker

[Signature]
 Executive Engineer
 Rural Works Department
 Works Division, Banka-1

[Signature]
 Assistant Engineer
 Rural Works Department
 Works Division, Banka-1

[Signature]
 Junior Engineer

[Signature]
 Ravi
 16/07/21
 (CPM)

Name of Customer : Anil Kumar Singh
 Name of Work/Road : Banka Belhar RCD Road to Ma
 Lab Job number : 18
 Date : 10-07-2021
 Section No. : 18

Test Date : 10-07-2021
 Machine No : 407
 Start S No :
 Start E No :
 Weather :
 Start Location : 24.926888, 86.868
 End Location : 24.947913, 86.868
 Road Name : Banka Belhar RCD Road to Ma
 Road Type : (R) RURAL ROAD
 Side :
 UV Range : 528 To 5000
 Dist Range : 0 To 3.1
 Equation : $0.0002 \times X^2 + 0.969 \times X + 74.60$

Print


Generate Report and Graph

Redraw Graph

Map View

File : H:\BUMP Integrator Report\Anil Kumar Singh\Anil Kumar Singh Shambhuganj Road\New

Name of Customer : Anil Kumar Singh, Name of Work/Road : Banka Belhar RCD Road to Maharajganj, Lab Job



Rawi
 10/07/2021
 (J.E.M.)

Skumar
 12-07-21
 J.E

Ritam
 12-07-2021
 R.E

12/7/21
 E.E



Lesifet

Rawi
10/10/2021
10/10/2021

Bureau
12.07.21
T.M.

Priyam
12.07.2021
A.E

12/11/21
12/11/21
12/11/21